





report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	CLA CLA220 CDI AMG SPORT
Colour	Silver
Year of manufacture	2014
Top speed	143 mph
0 - 100 km/h	8.2 seconds
0 - 60 mph	8.2 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	125 kW / 170 HP / 170 BHP
Max. torque	350 Nm at 1.400 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	111 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-10-09

Pictures 15

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2025-01-28
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	11
Total items failed	3

MOT #10	2024-01-29 15:31
MOT test number	428822243300
Result	✓ Passed
Next expiry date	2025-01-28

MOT #9	2022-10-18 13:13
MOT test number	317280045505
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #8	2022-10-17 15:55
MOT test number	619115125519
Result	X Failed
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents (ii))	the ingress of dirt (5.3.4 (b)

CarCheck.co.uk page 3/12



Result

BD64WMW

report date: 2024-03-28

× Failed

MOT #7 2021-08-16 14:32

MOT test number 757624743328

Minor Offside Obligatory mirror slightly damaged (3.3 (b) (i))

MOT #6 2021-08-16 11:53

MOT test number 745677774392

Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Minor Offside Obligatory mirror slightly damaged (3.3 (b) (i))

MOT #5 2020-08-10 11:58

MOT test number 810934289064

Result ✓ Passed

Minor Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge tyre is starting to go out of shape on inner edge (5.2.3 (e))

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT #4 2019-08-08 10:13

MOT test number 163447646290

Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2018-11-26 14:38

MOT test number 325889787885

Result \rightarrow Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #2 2017-11-21 15:53

MOT test number 699661210424

Result ✓ Passed

MOT #1 2017-11-21 14:52

MOT test number 443598509072

Result X Failed

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords outer side wall (4.1.D.1a)

Advice Advise off side front tyre , tread wearing low and unevenly

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	28 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12




report date: 2024-03-28

Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date
Category
Type
Damage 2
Date
Category



Extra MERCEDES-BENZ salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How material MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. It report here .	

Plate changes	More info >
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	NIK SILV
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-11-28
Last registration	2024-01-29
Complete history	See info



Registration #1	2014-11-28	14 mi
Registration #2	2017-11-21	21.605 mi
Registration #3	2017-11-21	21.605 mi
Registration #4	2018-11-26	32.284 mi
Registration #5	2019-08-08	40.831 mi
Registration #6	2020-08-10	52.611 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

50225	Air conditionin
50295	
50482	
50501	
60566	
60567	
50569	

Safety ratings

NCAP rating	***
Adult	93%
Children	81%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1777 mm
Height	1432 mm
Length	4630 mm
Wheel base	2699 mm
Kerb weight	1525 kg
Max. allowed weight	2005 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	4
CarChock co.uk	nago 12

CarCheck.co.uk page 12/12

Number of seats	5
Number of axles	2
Engine number	65193032120397