





## General information

| Make                | MERCEDES-BENZ                     |
|---------------------|-----------------------------------|
| Model               | VIANO CDI BLUEEFFICIENCY AMBIENTE |
| Colour              | Black                             |
| Year of manufacture | 2013                              |
| Top speed           | 117 mph                           |
| Gearbox             | 6 speed Manual                    |

# Engine & fuel consumption

| Power                   | 120 kW / 163 HP / 163 BHP |
|-------------------------|---------------------------|
| Max. torque             | 360 Nm at 1.600 rpm       |
| Engine capacity         | 2.143 сс                  |
| Cylinders               | 4                         |
| Fuel type               | Diesel                    |
| Consumption city        | 31.7 mpg                  |
| Consumption extra urban | 43.5 mpg                  |
| Consumption combined    | 38.7 mpg                  |
| CO2 emission            | 214 g/km                  |
| CO2 label               | К                         |





| Internet history |             |
|------------------|-------------|
| Entry 1          |             |
| Date             | 2022-01-12  |
| Pictures         | 0           |
| Listing price    | View report |

source: autotrader.co.uk



# MOT history

| MOT expiry date    | 2024-10-31 |
|--------------------|------------|
| MOT pass rate      | 76 %       |
| MOT passed         | 16         |
| Failed MOT tests   | 5          |
| Total advice items | 18         |
| Total items failed | 12         |

| MOT #21     |   | 2023-10-06 13:46 |
|-------------|---|------------------|
| MOT test    | number  | 471594097431     |
| Result      |   | ✓ Passed         |
| Next expire | ry date   | 2024-10-31       |
| Advice      | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))  |                  |
| Advice      | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |                  |

| МОТ #20         | 2022-10-28 09:27 |
|-----------------|------------------|
| MOT test number | 586398497793     |
| Result          | ✓ Passed         |

| MOT #19  | 2022-10-19 15:03 |
|--|------------------|
| MOT test number  | 719075823572     |
| Result   | 🗙 Failed         |
| Fail Offside Rear Rear fog lamp not working (4.5.1 (a) (ii)) |                  |

| MOT #18         | 2021-11-01 16:52 |
|-----------------|------------------|
| MOT test number | 804240760379     |
| Result          | ✓ Passed         |





| MOT #17                   |   |  | 2021-11-01 16:52   |
|---------------------------|---|--|--------------------|
| MOT test                  | number  |  | 683603499549       |
| Result                    |   |  | 🗙 Failed           |
| Pass wit                  | h rectification   | Windscreen washer provides insufficient washer liquid (3.5 (a) | )                  |
| MOT #16                   |   |  | 2021-05-01 09:56   |
| MOT test                  | number  |  | 366761438578       |
| Result                    |   |  | ✓ Passed           |
| Advice                    | Offside Rear Direc  | tion indicator slightly discoloured (4.4.3 (a))                |                    |
| Advice<br>(i))            | Offside Front Susp  | ension arm pin or bush worn but not resulting in excessive m   | ovement (5.3.4 (a) |
| Advice                    | Nearside Rear Nai   | l in tyre  |                    |
| Advice                    | Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b)) |  |                    |
| Advice                    | Under-trays fitted  | obscuring some underside components                            |                    |
| <b>Advice</b><br>(a) (i)) | Nearside Front Su   | spension arm pin or bush worn but not resulting in excessive i | movement (5.3.4    |

| MOT #15         | 2020-10-29 11:46 |
|-----------------|------------------|
| MOT test number | 811647459612     |
| Result          | ✓ Passed         |

| MOT #14                | 2020-  | -06-20 10:55  |
|------------------------|--|---------------|
| MOT test               | number 71:   | 2693540159    |
| Result                 |  | ✓ Passed      |
| Advice                 | Front Registration plate deteriorated but not likely to be misread (0.1 (b))         |               |
| Advice<br>(i))         | Offside Front Suspension arm pin or bush worn but not resulting in excessive movemen | ıt (5.3.4 (a) |
| <b>Advice</b> (a) (i)) | Nearside Front Suspension arm pin or bush worn but not resulting in excessive moveme | ent (5.3.4    |





| MOT #13  | 2020-06-15 08:47    |
|--|---------------------|
| MOT test number  | 282322434237        |
| Result   | 🗙 Failed            |
| Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))              |                     |
| Fail   Nearside Front Side repeater not working intermittent (4.4.1 (a) (ii))                    |                     |
| Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive (i))         | movement (5.3.4 (a) |
| <b>Fail</b> Offside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))  |                     |
| <b>Fail</b> Front Windscreen washer not working (3.5 (a))  |                     |
| Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive (a) (i))    | e movement (5.3.4   |
| <b>Fail</b> Nearside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i)) |                     |

| MOT #12         | 2019-10-16 09:57 |
|-----------------|------------------|
| MOT test number | 850732539707     |
| Result          | ✓ Passed         |

| MOT #11         | 2019-09-30 13:07 |
|-----------------|------------------|
| MOT test number | 940369480180     |
| Result          | ✓ Passed         |

| MOT #10  |  | 2019-05-18 08:58 |
|----------|--|------------------|
| MOT test | number   | 677971512782     |
| Result   |  | ✓ Passed         |
| Advice   | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |                  |
| Advice   | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))  |                  |





| MOT #9  |   | 2019-05-18 08:58 |
|---|---|------------------|
| MOT test number   |   | 389660451866     |
| Result  |   | 🗙 Failed         |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |   |                  |
| Pass with rectification   | Offside Stop lamp(s) not working 380 (4.3.1 (a) (ii)) |                  |
| Advice Offside Front Ty   | re worn close to legal limit/worn on edge (5.2.3 (e)) |                  |

| MOT #8             | 2018-10-16 13:37 |
|--------------------|------------------|
| MOT test number    | 654151269203     |
| Result             | ✓ Passed         |
|                    |                  |
| MOT #7             | 2018-03-27 15:59 |
| MOT to at month an | 204077602010     |

| MOT test number | 384077603019 |
|-----------------|--------------|
| Result          | ✓ Passed     |

| МОТ #6          | 2017-10-16 13:19 |
|-----------------|------------------|
| MOT test number | 115850144003     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #5          | 2017-05-27 09:23 |
| MOT test number | 700174796450     |
| Result          | ✓ Passed         |
|                 |                  |

| MOT #4          | 2016-10-21 10:06 |
|-----------------|------------------|
| MOT test number | 463199526362     |
| Result          | ✓ Passed         |





| MOT #3   |   | 2016-10-20 11:12 |
|--|---|------------------|
| MOT test number  |   | 226490725458     |
| Result   |   | 🗙 Failed         |
| Fail   Nearside Rear Tyre  | tread depth below requirements of 1.6mm (4.1.E.1) |                  |
| Pass with rectification  | Nearside Headlamp aim too high (1.8)              |                  |
| Fail   Offside Rear Tyre has ply or cords exposed 225/55/r17/101h (4.1.D.1b) |   |                  |
| Pass with rectification  | Nearside Stop lamp not working 380 (1.2.1b)       |                  |
| Pass with rectification  | Offside Headlamp aim too high (1.8)               |                  |

| MOT #2          | 2015-10-16 11:55 |
|-----------------|------------------|
| MOT test number | 787211126823     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #1          | 2014-10-13 15:21 |
| MOT test number | 919286584264     |
| Result          | ✓ Passed         |



Tax & MOT check

| ✓<br>Taxed<br>Tax due:<br>1 February 2025 | ✓<br>MOT<br>Expires:<br>31 October 2024 |
|---|---|
| Tax status                                | Valid until 1 February                  |
| Days left                                 | 278                                     |
| MOT expiry date                           | 31 October 2024                         |
| Full MOT history                          | See MOT history                         |

## Tax calculation

| Vehicle class                           | 49         |
|---|------------|
| Band                                    | К          |
| Single payment (12 months)              | £ 395,00,- |
| Single six month payment                | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |





### Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |             |
|----------|-------------|
| Date     |             |
| Category | A AMP       |
| Туре     |             |
|          | MPL         |
| Damage 2 | a cate of a |
| Date     |             |
| Category | AMP         |
| Туре     |             |

#### Extra MERCEDES-BENZ salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4 10.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 10.200 |

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| *******  |             |
|--|-------------|
| *********  |             |
| *********  |             |
|  |             |
|  |             |
|  |             |
| ********   |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this MERCEDES-BENZ had different number plates. |             |
| Number of plates   | ,           |
| Current registration   |             |
| Plate since  |             |
| Current registration   |             |
| Plate since  |             |
|  | More info > |





### Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |


More info  $\rightarrow$ 





# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 23         |
| First mileage registration | 2013-10-31 |
| Last registration          | 2023-10-06 |
| Complete history           | See info   |



| Registration #1  | 2013-10-31 | 6 mi       |
|------------------|------------|------------|
| Registration #2  | 2014-10-13 | 19.693 mi  |
| Registration #3  | 2015-10-16 | 41.673 mi  |
| Registration #4  | 2016-10-20 | 68.056 mi  |
| Registration #5  | 2016-10-21 | 68.056 mi  |
| Registration #6  | 2017-05-27 | 83.397 mi  |
| Registration #7  | 2017-10-16 | 95.111 mi  |
| Registration #8  | 2018-03-27 | 106.256 mi |
| Registration #9  | 2018-10-16 | 120.861 mi |
| Registration #10 | 2019-05-18 | 123.752 mi |
| Registration #11 | 2019-05-18 | 123.752 mi |
| Registration #12 | 2019-09-30 | 131.573 mi |
| Registration #13 |            | 11.777 esi |
| Registration #14 |            | 11.777 esi |
| Registration #15 |            | 11.777 esi |
| Registration #16 |            | 11.777 esi |
| Registration #17 |            | 11.777 est |
| Registration #18 |            | 11.777 est |
| Registration #19 |            | 11.777 esi |
| Registration #20 |            | 11.117 est |
| Registration #21 |            | 11.227 est |
| Registration #22 |            | 11.117 esi |
| Registration #23 |            | 11.777 esi |

More info >





### Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

## Safety ratings

**NCAP** rating

Video

see crash video



#### Dimensions & weight Width 1901 mm Height 1923 mm Length 5008 mm Wheel base 3430 mm Kerb weight 2166 kg Max. allowed weight 3050 kg Additional information Fuel tank capacity 75 I **Fuel delivery Direct Injection** Number of doors 5

| Number of seats | 8              |
|-----------------|----------------|
| Number of axles | 2              |
| Engine number   | 65194031891686 |