





report date: 2024-03-28

## General information

Make	VOLVO
Model	S40 E4 D SE S40
Colour	Silver
Year of manufacture	2005
Top speed	130 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	134 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	148 g/km
CO2 label	F



CarCheck.co.uk page 1/13



report date: 2024-03-28

## Internet history

## Entry 1

Date 2021-12-16

Pictures 24

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

# MOT history

MOT expiry date	2024-05-03
MOT pass rate	84 %
MOT passed	16
Failed MOT tests	3
Total advice items	13
Total items failed	6

MOT #19	2023-05-04 12:32
MOT test number	900981531181
Result	✓ Passed
Next expiry date	2024-05-03
Advice Front Coil spring corroded both fronts corroded slightly (5.3.1 (b) (i))	

MOT #18	2	022-04-07 14:15
MOT test	number	132760624315
Result		✓ Passed
<b>Minor</b> middle.sm	Nearside Front Windscreen damaged but not adversely affecting driver's view zone mall chip/crack (3.2 (a) (i))	B. left of
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge bald on inner edge	(5.2.3 (e))
Advice	Nearside Front Lower Coil spring corroded lower coil corroded (5.3.1 (b) (i))	
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge bald on inner edge	e (5.2.3 (e))
Advice	Offside Front Lower Coil spring corroded lower coil corroded (5.3.1 (b) (i))	

MOT #17	2021-04-13 13:07
MOT test number	660870136100
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-28

**MOT #16** 2021-04-13 08:31

MOT test number 608757616860

Result X Failed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Offside Front Tyre tread depth below requirements of 1.6mm on cords on inner tread (5.2.3 (e))

**MOT #15** 2020-04-16 14:33

**MOT test number** 539057506453

**Result** ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #14** 2020-04-15 14:07

**MOT test number** 380225007946

**Result** X Failed

**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Offside Rear Inner Tyre tread depth below requirements of 1.6mm on cords (5.2.3 (e))

Fail Nearside Rear Inner Tyre tread depth below requirements of 1.6mm on cords (5.2.3 (e))

**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2019-04-08 16:40

**MOT test number** 508271934957

**Result** 
✓ Passed

**MOT #12** 2018-04-04 07:29

**MOT test number** 417862886512

**Result** 
✓ Passed

CarCheck.co.uk page 4/13



MOT #11

MOT #6

Result

**Notice** 

**MOT** test number

VN05AYW

report date: 2024-03-28

2017 04 24 07:09

2012-04-26 16:38

379247912138

✓ Passed

MOT #11	2017-04-24 07:08
MOT test number	431404155399
Result	✓ Passed
MOT #10	2016-04-18 07:23
MOT test number	221991889995
Result	✓ Passed
MOT #9	2015-04-14 18:19
MOT test number	656234005173
Result	✓ Passed
Notice Child seat fitted not allowing full inspection of adult belt	
MOT #8	2014-04-15 17:53
MOT test number	865435204135
Result	✓ Passed
MOT #7	2013-04-30 09:33
MOT test number	925960623158
Result	✓ Passed

MOT #5	2011-04-27 13:53
MOT test number	258927511455
Result	<b>✓</b> Passed

Engine covers fitted obscuring some components in the engine bay

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #4		2010-04-27 14:17
MOT test number		142527010167
Result		<b>✓</b> Passed
MOT #3		2009-04-29 15:33
MOT test number		682389019101
Result		<b>x</b> Failed
Pass with rectification	Offside Headlamp aim too low (1.8)	
Pass with rectification	Nearside Headlamp aim too low (1.8)	

MOT #2	2009-04-29 15:33
MOT test number	222219819491
Result	✓ Passed
MOT #1	2008-04-24 17:13
MOT test number	734235418106
Result	✓ Passed

CarCheck.co.uk page 6/13





report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	3 May 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

## Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

$\sim$		ner	h	: -+		
	W I	1er	m	ısı	O	IV

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full		
***************************************		
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this VOLVO had different number plates.		
Number of plates		
Current registration	UK ZIS	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-28

### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-04-29
Last registration	2023-05-04
Complete history	See info



Registration #1	2005-04-29	20 mi
Registration #2	2008-04-24	14.488 mi
Registration #3	2009-04-29	26.474 mi
Registration #4	2010-04-27	38.686 mi
Registration #5	2011-04-27	51.246 mi
Registration #6	2012-04-26	66.493 mi
Registration #7	2013-04-30	76.840 mi
Registration #8	2014-04-15	82.791 mi
Registration #9	2015-04-14	89.866 mi
Registration #10	2016-04-18	97.232 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.79 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.117 au

More info >

CarCheck.co.uk page 12/13



VNO5AYW
report date: 2024-03-28

Car features

S0225	Air conditionin
50295	
50482	
60501	
60566	
60567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4468 mm
Wheel base	2640 mm
Kerb weight	1457 kg
Max. allowed weight	1940 kg

# Additional information

Fuel tank capacity	52 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 13/13

Number of axles 2
Engine number 4003248