



PEUGEOT



WR58FWV

report date: 2024-03-28

General information

Make	PEUGEOT
Model	107 URBAN
Colour	Grey
Year of manufacture	2008
Top speed	100 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg
CO2 emission	108 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-03
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-10-15
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	46
Total items failed	24

MOT #20	2023-10-13 08:50
MOT test number	903583209678
Result	✓ Passed
Next expiry date	2024-10-15
Advice	Nearside Rear Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))
Advice	Offside Rear Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))

MOT #19	2023-10-11 11:12
MOT test number	378729557584
Result	✗ Failed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))
Advice	Offside Rear Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))
Fail	Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Advice	Nearside Rear Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))

MOT #18	2022-10-15 07:56
MOT test number	154151923539
Result	✓ Passed

Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1

(b) (i))

**MOT #17**

2021-10-12 10:38

MOT test number

696617563175

Result

✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #16**

2021-09-28 09:58

MOT test number

879455420439

Result

✗ Failed

Fail Nearside Rear Brake pipe excessively corroded main (1.1.11 (c))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Rear Brake pipe excessively corroded main (1.1.11 (c))**Advice** Nearside Rear parking brake efficiency low requires adjustment or repair.**Fail** Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**MOT #15**

2020-10-14 11:45

MOT test number

665617579679

Result

✓ Passed

Advice N/S/R TYRE WORN**Advice** BOTH FRONT TYRES WORN INNER EDGE**Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**MOT #14**

2019-10-16 09:24

MOT test number

448165744065

Result

✓ Passed



MOT #13	2019-03-14 17:46
MOT test number	697592454263
Result	✓ Passed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner surface (1.1.14 (a) (ii))
Advice	Front windscreen wiper blade smearing screen
Advice	Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner surface (1.1.14 (a) (ii))
Advice	Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

MOT #12	2019-03-11 11:54
MOT test number	541094388077
Result	✗ Failed

Advice Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner surface (1.1.14 (a) (ii))

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords inner edge (5.2.3 (d) (i))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Fail Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner surface (1.1.14 (a) (ii))

Fail Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))

Advice Front windscreen wiper blade smearing screen

Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #11** 2018-03-15 16:12**MOT test number** 645498325367**Result** ✓ Passed**MOT #10** 2018-03-15 10:45**MOT test number** 461786825476**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside Rear tyre 2.1mm tread and wearing uneven**Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Rear tyre 2mm tread and wearing uneven**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Front Body insecure and dangerous to other road users bumper (6.1.B.1b)**MOT #9** 2017-03-23 14:14**MOT test number** 168673248544**Result** ✓ Passed**Advice** Nearside of vehicle damaged inc front bumper slight loose

**MOT #8**

2017-03-23 12:10

MOT test number

219780125182

Result

✗ Failed

Fail

Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

Fail

Offside Front Front position lamp(s) not working (1.1.A.3b)

Fail

Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail

Offside Front Tyre has ply or cords exposed (4.1.D.1b)

Fail

Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

Advice

Nearside of vehicle damaged inc front bumper slight loose

MOT #7

2016-03-15 14:52

MOT test number

874112520862

Result

✓ Passed

Advice

Nearside Front Body has slight displacement of the body relative to the chassis bumper panel (6.1.B.1a)

MOT #6

2016-03-15 14:52

MOT test number

575597358587

Result

✗ Failed

Pass with rectification

Nearside Windscreen washer provides insufficient washer liquid (8.2.3)

Advice

Nearside Front Body has slight displacement of the body relative to the chassis bumper panel (6.1.B.1a)

Pass with rectification

Offside Windscreen washer provides insufficient washer liquid (8.2.3)

**MOT #5** 2014-10-31 12:00**MOT test number** 699264904331**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Nearside front tyre worn smooth on inner edge**Advice** Nearside Front Body has slight displacement of the body relative to the chassis (6.1.B.1a)**Notice** Windscreen wiper smearing screen**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Offside front tyre worn smooth on inner edge**MOT #4** 2013-11-08 16:00**MOT test number** 709072813388**Result** ✓ Passed**Notice** N/s front bumper not fully secured**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2013-11-08 12:16**MOT test number** 275492613364**Result** ✗ Failed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** N/s front bumper not fully secured**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



MOT #2	2012-10-31 16:48
MOT test number	746055302327
Result	✓ Passed
MOT #1	2011-11-04 15:25
MOT test number	156378801322
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
15 October 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	15 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	WR58FWV
Plate since	2019-09-28
Current registration	WR58FWV
Plate since	2019-09-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-11-12
Last registration	2023-10-13
Complete history	See info



Registration #1	2008-11-12	9 mi
Registration #2	2011-11-04	23.918 mi
Registration #3	2012-10-31	40.756 mi
Registration #4	2013-11-08	49.893 mi
Registration #5	2013-11-08	49.896 mi
Registration #6	2014-10-31	60.034 mi
Registration #7	2016-03-15	78.048 mi
Registration #8	2016-03-15	78.048 mi
Registration #9	2017-03-23	94.906 mi
Registration #10	2017-03-23	94.906 mi
Registration #11	2018-03-15	119.194 mi
Registration #12	2019-03-15	151.217 mi
Registration #13	2019-03-15	151.217 mi
Registration #14	2019-03-15	151.217 mi
Registration #15	2019-03-15	151.217 mi
Registration #16	2019-03-15	151.217 mi
Registration #17	2019-03-15	151.217 mi
Registration #18	2019-03-15	151.217 mi
Registration #19	2019-03-15	151.217 mi
Registration #20	2019-03-15	151.217 mi
Registration #21	2019-03-15	151.217 mi
Registration #22	2019-03-15	151.217 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	790 kg
Max. allowed weight	1180 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Engine number	5912945