



AV60NBO

report date: 2024-03-29

General information

Make	MAZDA
Model	CX-7 D SPORT TECH
Colour	White
Year of manufacture	2011
Top speed	124 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.184 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	42.8 mpg
Consumption combined	37.7 mpg
CO2 emission	199 g/km
CO2 label	J





Internet history

Entry 1

Date 2021-08-03

Pictures 5

Listing price [View report](#)



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-22
MOT pass rate	58 %
MOT passed	11
Failed MOT tests	8
Total advice items	30
Total items failed	9

MOT #19	2023-06-23 15:55
MOT test number	384696392451
Result	✓ Passed
Next expiry date	2024-06-22

MOT #18	2023-06-22 10:14
MOT test number	564717899659
Result	✗ Failed
Fail	Nearside Front Outer Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #17	2022-11-14 10:57
MOT test number	256490954284
Result	✓ Passed

MOT #16	2021-11-19 17:00
MOT test number	764834549398
Result	✓ Passed

MOT #15	2021-11-18 15:50
MOT test number	657231775256
Result	✗ Failed
Fail	Windscreen washer not working (3.5 (a))

**MOT #14**

2021-02-04 12:21

MOT test number

785231563251

Result

✓ Passed

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge wearing on outer edge (5.2.3 (e))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor

Power steering fluid level below minimum (2.1.5 (b) (i))

MOT #13

2021-02-04 12:21

MOT test number

661641648646

Result

✗ Failed

Pass with rectification

Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor

Power steering fluid level below minimum (2.1.5 (b) (i))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge wearing on outer edge (5.2.3 (e))

**MOT #12** 2020-02-17 16:13**MOT test number** 983199351693**Result** ✓ Passed**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))**Minor** Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))**Advice** Nearside Rear Nail in tyre**MOT #11** 2019-01-24 14:07**MOT test number** 565730873194**Result** ✓ Passed**MOT #10** 2019-01-22 08:47**MOT test number** 557483447045**Result** ✗ Failed**Fail** Nearside Rear Rear reflector defective or damaged by more than 50% of the reflecting surface (4.8.1 (a) (ii))**MOT #9** 2018-02-09 09:39**MOT test number** 232646335004**Result** ✓ Passed**MOT #8** 2018-02-09 09:39**MOT test number** 389681679395**Result** ✗ Failed**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)

**MOT #7** 2017-01-26 16:42**MOT test number** 147239325677**Result** ✓ Passed**MOT #6** 2016-02-03 10:30**MOT test number** 310563331403**Result** ✓ Passed**Advice** N/s/ front bumper damage**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #5** 2016-02-01 16:13**MOT test number** 571863069542**Result** ✗ Failed**Fail** Nearside Headlamp not working on main beam (1.7.5a)**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** N/s/ front bumper damage**MOT #4** 2015-01-21 13:49**MOT test number** 647581625062**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Off side wiper blade deteriorating slightly**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Parking brake lever has little reserve travel (3.1.6b)

**MOT #3** 2015-01-20 12:05**MOT test number** 726990425097**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Off side wiper blade deteriorating slightly**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #2** 2014-01-22 09:48**MOT test number** 935232624062**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #1** 2014-01-22 09:48**MOT test number** 575232824002**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
22 June 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	22 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2011-01-31
Last registration	2023-06-23
Complete history	See info



Registration #1	2011-01-31	21 mi
Registration #2	2014-01-22	38.128 mi
Registration #3	2015-01-20	20.560 mi
Registration #4	2015-01-21	50.267 mi
Registration #5	2016-02-01	57.311 mi
Registration #6	2016-02-03	57.322 mi
Registration #7	2017-01-26	63.044 mi
Registration #8	2018-02-09	68.492 mi
Registration #9	2018-02-09	68.492 mi
Registration #10	2019-01-22	73.738 mi
Registration #11	2019-01-22	73.738 mi
Registration #12	2019-01-22	73.738 mi
Registration #13	2019-01-22	73.738 mi
Registration #14	2019-01-22	73.738 mi
Registration #15	2019-01-22	73.738 mi
Registration #16	2019-01-22	73.738 mi
Registration #17	2019-01-22	73.738 mi
Registration #18	2019-01-22	73.738 mi
Registration #19	2019-01-22	73.738 mi
Registration #20	2019-01-22	73.738 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	76%
Children	79%
Pedestrian	43%
Safety systems	71%
Overall rating	70%
Video	see crash video



Dimensions & weight

Width	1870 mm
Height	1645 mm
Length	4700 mm
Wheel base	2750 mm
Max. allowed weight	2430 kg

Additional information

Fuel tank capacity	69 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	R210287355