



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	I800 CRDI STYLE
Colour	Silver
Year of manufacture	2012
Top speed	112 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	168 BHP
Max. torque	440 Nm at 2.500 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	38.7 mpg
Consumption combined	32.1 mpg
CO2 emission	231 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-01-31
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2022-01-14
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	15
Total items failed	9

MOT #12	2020-12-23 17:49
MOT test number	560484990540
Result	✓ Passed
Next expiry date	2022-01-14

MOT #11	2020-01-15 10:36
MOT test number	358719520628
Result	✓ Passed

MOT #10	2020-01-14 13:28
MOT test number	487286398692
Result	✗ Failed

- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #9** 2018-10-25 11:04**MOT test number** 379083132903**Result** ✓ Passed**Advice** Offside Rear Coolant leak heater**Advice** Brake disc worn, but not excessively both side front (1.1.14 (a) (i))**Advice** Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.14 (a) (ii))**MOT #8** 2017-10-13 12:00**MOT test number** 786806857634**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**Advice** Offside Rear Coolant leak rear heater**MOT #7** 2016-10-18 10:34**MOT test number** 274649424088**Result** ✓ Passed**Advice** Emissions clean handbrake travel**MOT #6** 2016-04-19 14:37**MOT test number** 805176875085**Result** ✓ Passed

**MOT #5** 2016-04-19 08:51**MOT test number** 765939359578**Result** ✗ Failed

- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)

**MOT #4** 2015-10-06 11:22**MOT test number** 356584522691**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.2b)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.2b)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Handbrake travel engine cover diesel emissions too clean
- Advice** Nearside Tyre worn close to the legal limit (4.1.E.2b)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.2b)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #3** 2015-04-07 13:09**MOT test number** 157327095490**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #2** 2014-10-08 12:19**MOT test number** 905331784255**Result** ✓ Passed



MOT #1	2014-04-09 17:03
MOT test number	307339494077
Result	✓ Passed



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-28
Current registration	
Plate since	2019-09-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-06-01
Last registration	2020-12-23
Complete history	<a href="#">See info</a>



Registration #1	2012-06-01	22 mi
Registration #2	2014-04-09	32.996 mi
Registration #3	2014-10-08	39.181 mi
Registration #4	2015-04-07	52.957 mi
Registration #5	2015-10-06	72.067 mi
Registration #6	2016-04-19	87.490 mi
Registration #7	2016-04-19	87.490 mi
Registration #8	2016-04-19	87.490 mi
Registration #9	2016-04-19	87.490 mi
Registration #10	2016-04-19	87.490 mi
Registration #11	2016-04-19	87.490 mi
Registration #12	2016-04-19	87.490 mi
Registration #13	2016-04-19	87.490 mi
Registration #14	2016-04-19	87.490 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1925 mm
Length	5125 mm
Wheel base	3200 mm
Kerb weight	2270 kg
Max. allowed weight	3030 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8

Engine number	D4CBC995094
---------------	-------------