




General information

|                     |  |
|---------------------|--|
| Make                | MINI   |
| Model               | COUNTRYMAN COOPER SD ALL4 AUTO<br>COOPER SD ALL4 |
| Colour              | Red  |
| Year of manufacture | 2012   |
| Top speed           | 120 mph  |
| 0 - 60 mph          | 9.5 seconds                                      |
| Gearbox             | 6 speed automatic                                |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 143 BHP             |
| Max. torque             | 305 Nm at 1.750 rpm |
| Engine capacity         | 1.995 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 36.7 mpg            |
| Consumption extra urban | 55.4 mpg            |
| Consumption combined    | 46.3 mpg            |
| CO2 emission            | 160 g/km            |
| CO2 label               | G                   |






Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2022-02-21                  |
| Pictures      | 6                           |
| Listing price | <a href="#">View report</a> |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-09-09 |
| MOT pass rate      | 77 %       |
| MOT passed         | 10         |
| Failed MOT tests   | 3          |
| Total advice items | 18         |
| Total items failed | 1          |

|                  |   |
|------------------|---|
| MOT #13          | 2023-09-09 09:21  |
| MOT test number  | 252775402042  |
| Result           | ✓ Passed  |
| Next expiry date | 2024-09-09  |
| Advice           | Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e)) |

|                 |   |
|-----------------|---|
| MOT #12         | 2022-09-10 09:29  |
| MOT test number | 967005858776  |
| Result          | ✓ Passed  |
| Advice          | Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))           |
| Advice          | Nearside Front Tyre slightly damaged/cracking or perishing inner edge also delaminated (5.2.3 (d) (ii)) |
| Advice          | Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))            |

|                 |                  |
|-----------------|------------------|
| MOT #11         | 2021-09-10 13:53 |
| MOT test number | 282179564451     |
| Result          | ✓ Passed         |

**MOT #10** 2021-09-02 11:13**MOT test number** 938348071175**Result** ✗ Failed

- MAJOR** Steering linkage ball joint has excessive play o/s front lower (2.1.3 (b) (i))
- MAJOR** Suspension component pin or bush excessively worn front wish bone bushes (5.3.4 (a) (i))
- MAJOR** Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt o/s front outer (6.1.7 (g) (ii))

**MOT #9** 2020-09-02 08:32**MOT test number** 129476354878**Result** ✓ Passed

- Advice** Steering linkage ball joint has slight play o/s front lower only just acceptable (2.1.3 (b) (i))
- Minor** Windscreen wiper blade defective (3.4 (b) (i))

**MOT #8** 2019-08-27 09:07**MOT test number** 807971185040**Result** ✓ Passed

- Advice** Emissions to lean to pick up readings
- Advice** Brake pad(s) wearing thin rear (1.1.13 (a) (ii))

**MOT #7** 2018-08-09 16:18**MOT test number** 567610246069**Result** ✓ Passed**MOT #6** 2018-08-09 10:21**MOT test number** 220439650780**Result** ✗ Failed

- MAJOR** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i))

**MOT #5** 2017-08-31 08:13**MOT test number** 783527168522**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2016-08-13 12:44**MOT test number** 272007790444**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Front suspension has slight deterioration of the bonding between metal and flexible material of an upper support bearing (2.5.B.3a)**Advice** Offside Rear Anti-roll bar rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Front suspension has slight deterioration of the bonding between metal and flexible material of an upper support bearing (2.5.B.3a)**MOT #3** 2015-09-05 09:26**MOT test number** 541692695887**Result** ✓ Passed**MOT #2** 2015-07-30 15:03**MOT test number** 917911615220**Result** ✓ Passed**MOT #1** 2015-07-30 15:03**MOT test number** 419281415254**Result** ✗ Failed**Pass with rectification** Registration plate lamp not working (1.1.C.1d)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
9 September 2024

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 September         |
| <b>Days left</b>        | 125                             |
| <b>MOT expiry date</b>  | 9 September 2024                |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |            |
|--|------------|
| <b>Vehicle class</b>                           | 49         |
| <b>Band</b>                                    | G          |
| <b>Single payment (12 months)</b>              | £ 240,00,- |
| <b>Single six month payment</b>                | £ 132,00,- |
| <b>Total payable by 12 monthly instalments</b> | £ 252,00,- |



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |            |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this MINI had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration |            |
| Plate since          | 2024-03-29 |
| Current registration |            |
| Plate since          | 2024-03-29 |

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

|                   |          |      |
|-------------------|----------|------|
| Finance company   | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type    | XXXXXXXX | XXXX |
| Agreement term    | XXXXXXXX | XXXX |
| Agreement number  | XXXXXXXX | XXXX |
| Contact info      | XXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 14                       |
| First mileage registration | 2012-07-21               |
| Last registration          | 2023-09-09               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2012-07-21 | 19 mi     |
| Registration #2  | 2015-07-30 | 15.614 mi |
| Registration #3  | 2015-09-05 | 43.760 mi |
| Registration #4  | 2016-08-13 | 24.290 mi |
| Registration #5  | 2017-08-31 | 35.752 mi |
| Registration #6  | 2018-08-09 | 47.121 mi |
| Registration #7  | 2018-08-09 | 47.121 mi |
| Registration #8  | 2019-09-09 | 55.277 mi |
| Registration #9  | 2019-09-09 | 55.277 mi |
| Registration #10 | 2019-09-09 | 55.277 mi |
| Registration #11 | 2019-09-09 | 55.277 mi |
| Registration #12 | 2019-09-09 | 55.277 mi |
| Registration #13 | 2019-09-09 | 55.277 mi |
| Registration #14 | 2019-09-09 | 55.277 mi |

More info >



Car features

The MINI factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 84%                             |
| Children       | 83%                             |
| Pedestrian     | 63%                             |
| Safety systems | 71%                             |
| Overall rating | 78%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1789 mm |
| Height              | 1561 mm |
| Length              | 4110 mm |
| Wheel base          | 2595 mm |
| Kerb weight         | 1420 kg |
| Max. allowed weight | 1880 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 47 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 5                |

|               |          |
|---------------|----------|
| Engine number | 70898013 |
|---------------|----------|