



report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT 350 LWB HR P/V 115
Colour	White
Year of manufacture	2010
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	310 Nm at 1.750 rpm
Engine capacity	2.402 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2023-04-18
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	42
Total items failed	20

MOT #14 2022-03-21 12:36

MOT test number 877247057210

Result ✓ Passed

Next expiry date 2023-04-18

- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Prop shaft bearing damaged
- Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Brake pipe corroded, covered in grease or other material o/s + n/s (1.1.11 (c))

MOT #13 2022-03-18 10:26

MOT test number 304577813936

Result ✗ Failed

- Advice** Prop shaft bearing damaged
- Fail** Nearside Rear Outer Suspension spring mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))
- Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Fail** Reversing lamp inoperative (4.6.1 (a))
- Advice** Front Brake pipe corroded, covered in grease or other material o/s + n/s (1.1.11 (c))



MOT #12	2021-04-19 09:48
MOT test number	599163178193
Result	✓ Passed
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Prop shaft bearing casing damaged

**MOT #11**

2021-04-13 07:46

MOT test number

571406080164

Result**✗ Failed****Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Prop shaft bearing casing damaged**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Fuel cap/sealing device ineffective (6.1.3 (b) (i))**Minor** Nearside Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Offside Headlamp aim too low (4.1.2 (a))**Fail** Stop lamp(s) all not working (4.3.1 (a) (iii))**Fail** Bonnet primary retaining device ineffective (3.1 (c))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #10** 2019-08-20 13:31**MOT test number** 499451219260**Result** ✓ Passed

- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #9 2019-08-20 11:21**MOT test number** 740517593759**Result** ✗ Failed

- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Offside Front Road wheel fixing missing (5.2.1 (a) (i))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps Both (4.7.1 (b) (ii))

MOT #8 2018-08-21 15:36**MOT test number** 810603674351**Result** ✓ Passed

- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #7** 2018-08-21 15:36**MOT test number** 872354823008**Result** ✗ Failed**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #6** 2017-08-23 12:59**MOT test number** 934886623706**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #5** 2016-08-15 09:46**MOT test number** 638315721668**Result** ✓ Passed**Advice** Nearside Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)**Advice** Offside Rear Nail in tyre**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

**MOT #4**

2016-08-15 09:46

MOT test number

369956875888

Result

✗ Failed

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Rear Nail in tyre**MOT #3**

2015-07-24 17:56

MOT test number

868465905276

Result

✓ Passed

Notice Front and rear brake discs worn/lipped**Notice** Brake pedal rubber split**Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**MOT #2**

2014-07-29 17:01

MOT test number

225540914219

Result

✓ Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Front brake disc worn/lipped**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #1**

2013-07-27 10:37

MOT test number

318148303414

Result

✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
1 May 2023

✕
MOT

Expired:
18 April 2023

Tax status	Expired at 1 May 2023
Days left	363 days too late
MOT expiry date	18 April 2023
Full MOT history	See MOT history



Damage history


Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-07-31
Last registration	2022-03-21
Complete history	See info



Registration #1	2010-07-31	15 mi
Registration #2	2013-07-27	73.632 mi
Registration #3	2014-07-29	83.112 mi
Registration #4	2015-07-24	90.917 mi
Registration #5	2016-08-15	98.232 mi
Registration #6	2016-08-15	98.232 mi
Registration #7	2017-08-23	108.276 mi
Registration #8	2018-08-21	121.443 mi
Registration #9	2019-08-21	131.277 mi
Registration #10	2020-08-21	141.111 mi
Registration #11	2021-08-21	150.945 mi
Registration #12	2022-03-21	160.779 mi
Registration #13	2022-03-21	160.779 mi
Registration #14	2022-03-21	160.779 mi
Registration #15	2022-03-21	160.779 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2360 mm
Height	2601 mm
Length	5680 mm
Kerb weight	1790 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	AT18351