





report date: 2024-03-29

General information

| Make | LAND ROVER |
|---------------------|------------------------------|
| Model | DEFENDER TD XS STATION WAGON |
| Colour | Grey |
| Year of manufacture | 2013 |
| Top speed | 90 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 90 kW / 123 HP / 122 BHP |
|-------------------------|--------------------------|
| Max. torque | 360 Nm at 2.000 rpm |
| Engine capacity | 2.198 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 24.1 mpg |
| Consumption extra urban | 30.1 mpg |
| Consumption combined | 27.7 mpg |
| CO2 emission | 269 g/km |
| CO2 label | M |



CarCheck.co.uk page 1/11




Internet history


Entry 1

Date 2021-08-28

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



J22RAT

report date: 2024-03-29

| B 4 | \sim $-$ | | |
|-------|-------------|------|--------|
| 10.71 | $^{\prime}$ | hic | tory |
| 101 | C I | 1115 | I OI V |
| | • | | , |

| MOT expiry date | 2024-08-08 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 8 |
| Failed MOT tests | 2 |
| Total advice items | 7 |
| Total items failed | 2 |

| MOT #10 | 2023-07-27 11:28 |
|------------------|------------------|
| MOT test number | 403133538080 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-08 |

| MOT #9 | | 2022-08-09 15:59 |
|------------|--|------------------|
| MOT test i | number | 397499141210 |
| Result | | ✓ Passed |
| Advice | Steering box has seepage (2.1.1 (e) (i)) | |
| Advice | Oil leak, but not excessive oil leak on engine (8.4.1 (a) (i)) | |

| MOT #8 | 2021-07-21 08:08 |
|-----------------|------------------|
| MOT test number | 698774961159 |
| Result | ✓ Passed |

| MOT #7 | 2020-11-11 14:39 |
|-----------------|------------------|
| MOT test number | 242554111515 |
| Result | ✓ Passed |

| MOT #6 | 2019-11-22 14:58 |
|-----------------|------------------|
| MOT test number | 991483443524 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



MOT test number

Result

Advice

Brake hose has slight corrosion to ferrule rear brake hoses (1.1.12 (f) (i))

Advice

Slight damage to nearside front seat belt webbing

Advice

Front Brake hose has slight corrosion to ferrule both front brake hoses (1.1.12 (f) (i))

MOT #4

MOT test number

196294880575

Result

Advice Nearside Front Seat belt damaged but webbing not significantly weakened ON LIMIT. (5.2.2a)

MOT test number

Result

Advice Nearside Front Seat belt damaged but webbing not significantly weakened ON LIMIT. (5.2.2a)

Fail Offside Rear Passenger's seat cannot be secured in the upright position. (6.2.A.2)

 MOT #2
 2016-11-15 16:23

 MOT test number
 732825145597

 Result
 ✓ Passed

 MOT #1
 2016-11-15 10:29

 MOT test number
 627764931265

 Result
 X Failed

 Fail

 Rear Upper Fuel hose leaking tank breather (7.2.3)

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 August |
|------------------|----------------------|
| Days left | 93 |
| MOT expiry date | 8 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 39 |
|---------------------------|------------|
| Standard rate (12 months) | £ 275,00,- |
| Standard rate (6 months) | £ 151,25,- |

CarCheck.co.uk page 5/11



Damage history


Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

| Date | |
|----------|--|
| Category | |
| Туре | |

Damage 2

| Damage 2 | |
|----------|--|
| Date | |
| Category | |



Extra LAND ROVER salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| e when metery | |
|---|-------------|
| For how long did the current and previous owner(s) have this LAND ROVER? How many o ROVER have? Check it in the premium report and see all owner registrations. Download to | |
| ******** | |
| | |
| | |
| ******** | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this LAND ROVER had different number plates. | |
| Number of plates | , |
| Current registration | NK NK |
| Plate since | |
| Current registration | SIE UK |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 12 |
| First mileage registration | 2013-11-29 |
| Last registration | 2023-07-27 |
| Complete history | See info |



| Registration #1 | 2013-11-29 | 11 mi |
|------------------|------------|-----------|
| Registration #2 | 2016-11-15 | 11.393 mi |
| Registration #3 | 2016-11-15 | 11.393 mi |
| Registration #4 | 2017-11-27 | 16.643 mi |
| Registration #5 | 2017-11-27 | 16.643 mi |
| Registration #6 | 2018-11-21 | 20.772 mi |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | n |

More info >

CarCheck.co.uk page 10/11



| | | _ | | |
|------|--------|--------|------|-----|
| luma | ncior | ור א. | MOIO | nt. |
| | ensior | ואט כו | WEIG | HL |
| | | | | |

| Width | 1790 mm |
|---------------------|---------|
| Height | 2128 mm |
| Length | 3880 mm |
| Wheel base | 2360 mm |
| Kerb weight | 1875 kg |
| Max. allowed weight | 2505 kg |

Additional information

| Fuel tank capacity | 60 I |
|--------------------|-------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 3 |
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | 121026083529DT224 |

CarCheck.co.uk page 11/11