





report date: 2024-03-29

General information

Make	FIAT
Model	DOBLO 16V MAXI MULTIJET COMBI
Colour	Black
Year of manufacture	2016
Top speed	102 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	290 Nm at 1.500 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	57.7 mpg
Consumption combined	50.4 mpg
CO2 emission	148 g/km
CO2 label	F



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2022-04-03

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

B 4	\sim $-$			
10.71	α	- h	sto	rv
101	() I		510	II V
	•		-	. ,

MOT expiry date	2025-04-03
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	13
Total items failed	0

MOT #7	2024-03-16 11:22
MOT test number	558536981482
Result	✓ Passed
Next expiry date	2025-04-03

MOT #6	2023-03-04 10:39
MOT test number	907679910798
Result	✓ Passed
Advice Rear exhaust box damaged	

MOT #5	2022-04-04 10:59
MOT test number	672923743322
Result	✓ Passed
MOT #4	2021-03-08 08:30
MOT test number	979775501338
Result	✓ Passed
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #3 2020-02-19 12:40

MOT test number 649249487250

Result ✓ Passed

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Rear xhaust box corroding and damaged

Advice Nearside Rear of van damaged

MOT #2 2020-02-17 13:52

MOT test number 442719164417

Result × Failed

MAJOR Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Rear xhaust box corroding and damaged

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Rear of van damaged

MOT #1 2019-02-13 13:50

MOT test number 100165857067

Advice Engine cover fitted obscuring some engine bay components

Advice Parking brake lever has little reserve travel

Advice Undertray fitted obscuring some underside components

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

CarCheck.co.uk page 4/11



GN16LWW report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 May
Days left	366
MOT expiry date	3 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report I	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	NE AIR
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-03-02
Last registration	2024-03-16
Complete history	See info



Registration #1	2016-03-02	25 mi
Registration #2	2019-02-13	82.053 mi
Registration #3	2020-02-17	107.915 mi
Registration #4	2020-02-19	108.106 mi
Registration #5	2021-03-08	113.964 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		10,100 es

More info >

CarCheck.co.uk page 10/11



GN16LWW report date: 2024-03-29

Car features

The FIAT factory car options list is only available in the premium report.		
S0225	Air conditioning	
S0295		
S0482		
S0501		
S0566		
S0567		

View the complete FIAT factory list for this vehicle <u>here</u>.

More info >

Safety ratings

S0569

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1832 mm
Height	1880 mm
Length	4740 mm
Kerb weight	1545 kg
Max. allowed weight	2270 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number Carcheck.co.uk	7658047 page 11/11