





report date: 2024-03-28

General information

Make	ТОУОТА
Model	RAV-4 VVTI XTR
Colour	Grey
Year of manufacture	2007
Top speed	109 mph
0 - 60 mph	12.0 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	150 BHP
Max. torque	194 Nm at 4.000 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	24.4 mpg
Consumption extra urban	38.2 mpg
Consumption combined	31.4 mpg
CO2 emission	212 g/km
CO2 label	K



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history


Entry 1

Date 2021-12-20

Pictures 55

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-07-07
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	22
Total items failed	3

MOT #17	2023-07-03 13:51
MOT test number	188246011371
Result	✓ Passed
Next expiry date	2024-07-07

MOT #16	2022-07-04 13:45
MOT test number	343864183387
Result	✓ Passed
Advice Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))	

MOT #15	2021-06-23 14:50
MOT test number	187345787589
Result	✓ Passed
MOT #14	2021-06-23 14:50
MOT test number	164717593722
Result	X Failed
Pass with rectification (b) (ii))	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4

MOT #13	2020-06-26 15:06
MOT test number	879206949583
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #12 2019-07-01 15:35 436800301186 **MOT** test number Result ✓ Passed **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i)) Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Offside Rear Coil spring corroded (5.3.1 (b) (i)) Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice**

MOT #11	2018-07-07 10:24
MOT test number	391125159044
Result	✓ Passed
MOT #10	2017-07-05 14:10
MOT test number	861538139048

Result

✓ Passed

Advice Offside Rear coil spring corroded (2.4.C.1b)

Advice Nearside Rear coil spring corroded (2.4.C.1b)

MOT #9	2016-07-08 12:20
MOT test number	263308100539
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	

CarCheck.co.uk page 4/13



Advice

HD57MHM

report date: 2024-03-28

MOT test number

Result

Advice (3.5.1i)

Advice Nearside Rear Brake pad(s) wearing thin on limit (3.5.1g)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened corroded disc face (3.5.1i)

MOT #7

MOT test number

915191034261

Result

✓ Passed

Offside Rear Brake pad(s) wearing thin on limit (3.5.1g)

MOT test number

Result

Advice Nearside front brake fluctuating, but not excessively (3.7.B.3)

Notice Front brakes pitted on face

Advice Offside front brake fluctuating, but not excessively (3.7.B.3)

MOT #5 2013-09-09 10:31 **MOT** test number 806772553227 Result × Failed **Notice** Front brakes pitted on face Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2) **Advice** Offside front brake fluctuating, but not excessively (3.7.B.3) Nearside front brake fluctuating, but not excessively (3.7.B.3) Advice **Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #4	2012-11-08 11:21
MOT test number	638173012393
Result	✓ Passed
MOT #3	2011-11-25 11:28
MOT test number	138719621376
Result	✓ Passed
MOT #2	2011-11-25 11:28
MOT test number	685789621361
Result	★ Failed
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #1	2010-11-23 11:13
MOT test number	311657620337
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 December
Days left	216
MOT expiry date	7 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

HD57MHM

report date: 2024-03-28

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

More info >

Plate changes

ober of plates

faste since

See in this check if this TOYOTA had different number plates.

UK UK

UK UK

More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-11-30
Last registration	2023-07-03
Complete history	See info



Registration #1	2007-11-30	29 mi
Registration #2	2010-11-23	34.444 mi
Registration #3	2011-11-25	45.174 mi
Registration #4	2012-11-08	55.221 mi
Registration #5	2013-09-09	65.145 mi
Registration #6	2013-09-09	65.146 mi
Registration #7	2014-08-19	70.519 mi
Registration #8	2015-08-17	74.552 mi
Registration #9	2016-07-08	77.704 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		71.777 au

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1720 mm
Length	4395 mm
Wheel base	2560 mm
Kerb weight	1560 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Engine number

1AZ5678590