



report date: 2024-03-28

General information

Make	VOLVO
Model	XC70 D SE AWD
Colour	Silver
Year of manufacture	2008
Top speed	121 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	163 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	45.6 mpg
Consumption combined	37.7 mpg
CO2 emission	199 g/km
CO2 label	J






Internet history

Entry 1

Date	2021-06-29
Pictures	36
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-10
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	35
Total items failed	11

MOT #18	2024-01-24 15:00
MOT test number	916566248685
Result	✓ Passed
Next expiry date	2025-02-10
Advice	Offside Play in steering rack inner joint(s)
Advice	Plastic sill covers fitted
Advice	Nearside Play in steering rack inner joint(s)

MOT #17	2023-02-01 15:33
MOT test number	377823264172
Result	✓ Passed
Advice	Advise undertrays and sill covers fitted
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Play in steering rack inner joint(s)
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16**

2023-02-01 11:22

MOT test number

976895998783

Result**✗ Failed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Advise undertrays and sill covers fitted**Advice** Play in steering rack inner joint(s)**Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #15**

2022-02-10 15:03

MOT test number

681678315014

Result**✓ Passed****Advice** Advise undertrays and sill covers fitted**MOT #14**

2022-02-01 13:49

MOT test number

730359813708

Result**✗ Failed****Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Advise undertrays and sill covers fitted**Fail** Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Rear Exhaust system insecure (6.1.2 (a))**MOT #13**

2021-02-11 12:06

MOT test number

672921124035

Result**✓ Passed**

**MOT #12** 2020-01-27 14:35**MOT test number** 142675674534**Result** ✓ Passed**MOT #11** 2020-01-27 11:27**MOT test number** 716015202585**Result** ✗ Failed**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Side repeater not working (4.4.1 (a) (ii))**MOT #10** 2019-01-24 13:37**MOT test number** 451022951445**Result** ✓ Passed**MOT #9** 2019-01-24 10:03**MOT test number** 720272255783**Result** ✗ Failed**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #8** 2018-01-27 12:41**MOT test number** 931666145243**Result** ✓ Passed**MOT #7** 2017-01-27 10:21**MOT test number** 418528171069**Result** ✓ Passed

**MOT #6**

2016-01-22 11:11

MOT test number

368974570092

Result

✓ Passed

- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened inner face (3.5.1i)
- Advice** Play in osr and nsr drop links
- Advice** Nearside Front Tyre worn close to the legal limit void of tread on inner shoulder (4.1.E.1)
- Advice** Exhaust rear heat shield slightly loose
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened inner face (3.5.1i)
- Advice** Auxiliary belt cracking

MOT #5

2015-01-30 14:26

MOT test number

589130435022

Result

✓ Passed

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #4** 2014-02-01 11:14**MOT test number** 137232034441**Result** ✓ Passed**Advice** Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)**Advice** Offside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #3** 2013-01-22 13:10**MOT test number** 155622523438**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2012-09-07 17:13**MOT test number** 706731452287**Result** ✓ Passed**Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1a)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1b)**MOT #1** 2011-10-12 13:06**MOT test number** 707725381277**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
10 February 2025

Tax status	Valid until 1 July
Days left	63
MOT expiry date	10 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-09-20
Last registration	2024-01-24
Complete history	See info



Registration #1	2008-09-20	9 mi
Registration #2	2011-10-12	74.946 mi
Registration #3	2012-09-07	78.249 mi
Registration #4	2013-01-22	79.325 mi
Registration #5	2014-02-01	82.400 mi
Registration #6	2015-01-30	85.841 mi
Registration #7	2016-01-22	89.730 mi
Registration #8	2017-01-27	93.785 mi
Registration #9	2018-01-27	97.962 mi
Registration #10	2019-01-24	110.019 mi
Registration #11	2020-01-24	110.019 mi
Registration #12	2021-01-24	110.019 mi
Registration #13	2022-01-24	110.019 mi
Registration #14	2023-01-24	110.019 mi
Registration #15	2024-01-24	110.019 mi
Registration #16	2025-01-24	110.019 mi
Registration #17	2026-01-24	110.019 mi
Registration #18	2027-01-24	110.019 mi
Registration #19	2028-01-24	110.019 mi
Registration #20	2029-01-24	110.019 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2142 mm
Height	1713 mm
Length	4628 mm
Wheel base	2774 mm
Kerb weight	1843 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	659998