





General information

Make	HONDA
Model	ACCORD I-DTEC EX GT
Colour	Silver
Year of manufacture	2009
Top speed	129 mph
0 - 60 mph	9.6 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.1 mpg
CO2 emission	170 g/km
CO2 label	Н





d our review mmend us to

Internet history Entry 1 Date 2021-12-05 Pictures 12 Listing price View report AutoTrader Free AA HIGHLY RATED **Highly Rated** Breakdown Cover' AutoTrader When you buy through AA Cars 2019 FOR OUR

CUSTOMER

SERVICE 2021

source: cargurus.co.uk

6

Cars Visit theAAcars.com

CarCheck.co.uk



MOT history

MOT expiry date	2025-01-14
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	12
Total items failed	6

MOT #16	2024-01-15 12:02
MOT test number	226378933775
Result	✓ Passed
Next expiry date 2025-01-1	
Advice Front Tyre worn close to legal limit/worn on edge BOTH (5.2.3 (e))	

МОТ #15	2023-01-12 16:26
MOT test number	258769230246
Result	✓ Passed

MOT #14	2022-01-14 11:35
MOT test number	913859663310
Result	✓ Passed

MOT #13	2021-04-07 12:49
MOT test number	498108562586
Result	✓ Passed
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	





MOT #12		2021-04-07 12:49
MOT test number		849898730026
Result		🗙 Failed
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt		
Pass with rectification	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
Pass with rectification	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #11	2020-02-15 15:53
MOT test number	622730194314
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

МОТ #10	2020-02-15 13:55
MOT test number	977026473928
Result	🗙 Failed
Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)))
Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or lig (4.7.1 (b) (i))	ght sources
Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (i	i))
Fail Offside Front Position lamp not working (4.2.1 (a) (ii))	
мот #9	2019-02-08 14:54
MOT test number	247103337363
Result	🗸 Passed

МОТ #8	2018-04-09 08:34
MOT test number	132646957890
Result	✓ Passed





MOT #7	2017-03-16 11:10
MOT test number	959745299722
Result	✓ Passed
МОТ #6	2016-04-14 10:27
MOT test number	124739058328
Result	✓ Passed
MOT #5	2016-04-14 10:27
MOT test number	293356165440
Result	× Failed

Pass with rectification Nearside Front position lamp(s) not working (1.1.A.3b)

MOT #4	20	015-04-15 10:11
MOT test number 9683258		968325805138
Result		✓ Passed
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)	

MOT #3	2014-04-29 16:16
MOT test number	899909314138
Result	✓ Passed
MOT #2	2013-08-29 14:18

MOT test number	127341143226
Result	✓ Passed





MOT #1		2012-08-30 09:34
MOT test	number	375603742490
Result		✓ Passed
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)	



Tax & MOT check

Tax due: 1 January 2025	✓ Taxed	Expires: 14 January 2025	√ мот
Tax status			Valid until 1 January
Days left			247
MOT expiry date			14 January 2025
Full MOT history			See MOT history
Tax calculation			

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-





Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

Extra HONDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this HONDA had different number plat	es.
Number of plates	
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



RO59MVL report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-09-15
Last registration	2024-01-15
Complete history	See info



Registration #1	2009-09-15	19 mi
Registration #2	2012-08-30	25.158 mi
Registration #3	2013-08-29	37.153 mi
Registration #4	2014-04-29	44.304 mi
Registration #5	2015-04-15	58.279 mi
Registration #6	2016-04-14	80.829 mi
Registration #7	2016-04-14	80.829 mi
Registration #8	2017-03-16	95.767 mi
Registration #9	2018-04-09	108.291 mi
Registration #10		11.777 est
Registration #11		11.707 est
Registration #12		11.777 est
Registration #13		11.707 est
Registration #14		11.777 est
Registration #15		11.707 est
Registration #16		0.207 est
Registration #17		11.777 mi
Registration #18		11.117 est



RO59MVL report date: 2024-03-28

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1840 mm
Height	1440 mm
Length	4726 mm
Wheel base	2705 mm
Kerb weight	1593 kg
Additional information	
Additional information Fuel tank capacity	65 l
	65 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection