



P4I7RHM

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	SHARAN VR6 HLINE
Colour	Green
Year of manufacture	1996
Top speed	141 mph
0 - 60 mph	7.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	174 BHP
Max. torque	235 Nm at 4.200 rpm
Engine capacity	2.792 cc
Cylinders	6
Fuel type	Petrol







Internet history

Entry 2



Date	2021-12-19
Pictures	8
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-08-17
Pictures	9
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2022-03-18
MOT pass rate	77 %
MOT passed	17
Failed MOT tests	5
Total advice items	9
Total items failed	11

MOT #22	2021-03-08 11:34
MOT test number	609478650245
Result	✓ Passed
Next expiry date	2022-03-18
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn outer tread (5.2.3 (e))
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #21	2020-03-12 11:12
MOT test number	594526801936
Result	✓ Passed
Advice	Slight oil leak from underside of engine.

MOT #20	2019-03-19 10:46
MOT test number	224749934376
Result	✓ Passed

MOT #19	2018-03-19 11:09
MOT test number	308603594237
Result	✓ Passed

**MOT #18** 2017-03-08 11:41**MOT test number** 984756003176**Result** ✓ Passed**MOT #17** 2016-03-10 12:09**MOT test number** 332803644922**Result** ✓ Passed**MOT #16** 2015-07-24 11:50**MOT test number** 305625605404**Result** ✓ Passed**Advice** Nearside Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**MOT #15** 2014-07-24 15:05**MOT test number** 618135104283**Result** ✓ Passed**MOT #14** 2014-07-24 10:07**MOT test number** 966545604225**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Fail** Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

**MOT #13** 2013-07-10 12:00**MOT test number** 385571893113**Result** ✓ Passed**MOT #12** 2012-07-24 16:03**MOT test number** 209806602232**Result** ✓ Passed**MOT #11** 2011-07-26 10:06**MOT test number** 336687301276**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2011-03-17 15:30**MOT test number** 398826771089**Result** ✓ Passed**MOT #9** 2010-07-27 09:43**MOT test number** 270568300243**Result** ✓ Passed**MOT #8** 2010-07-27 09:43**MOT test number** 830958000276**Result** ✗ Failed**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)

**MOT #7** 2009-07-27 11:07**MOT test number** 501438009288**Result** ✓ Passed**Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**MOT #6** 2008-07-18 15:13**MOT test number** 681460108215**Result** ✓ Passed**MOT #5** 2008-07-18 10:50**MOT test number** 224670908228**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #4** 2007-07-18 09:55**MOT test number** 480059597160**Result** ✓ Passed**MOT #3** 2007-07-18 09:55**MOT test number** 780399097101**Result** ✗ Failed**Pass with rectification** Rear Registration plate lamp not working (1.1.5c)**MOT #2** 2006-07-13 12:12**MOT test number** 604764296156**Result** ✓ Passed



MOT #1	2006-07-13 12:12
MOT test number	761954196136
Result	✗ Failed
Pass with rectification	Rear Registration plate lamp not working (1.1.5c)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	1996-08-14
Last registration	2021-03-08
Complete history	See info



Registration #1	1996-08-14	24 mi
Registration #2	2006-07-13	72.701 mi
Registration #3	2007-07-18	76.131 mi
Registration #4	2008-07-18	82.524 mi
Registration #5	2008-07-18	82.524 mi
Registration #6	2009-07-27	85.720 mi
Registration #7	2010-07-27	90.221 mi
Registration #8	2011-03-17	91.551 mi
Registration #9	2011-07-26	94.290 mi
Registration #10	2012-07-24	97.587 mi
Registration #11	2013-07-10	101.401 mi
Registration #12	2014-07-10	105.215 mi
Registration #13	2015-07-10	109.029 mi
Registration #14	2016-07-10	112.843 mi
Registration #15	2017-07-10	116.657 mi
Registration #16	2018-07-10	120.471 mi
Registration #17	2019-07-10	124.285 mi
Registration #18	2020-07-10	128.099 mi
Registration #19	2021-03-08	131.913 mi
Registration #20	2021-03-08	131.913 mi
Registration #21	2021-03-08	131.913 mi
Registration #22	2021-03-08	131.913 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	AAA191094