





General information

Make	VOLKSWAGEN
Model	CADDY C20 LIFE TDI
Colour	Purple
Year of manufacture	2016
Top speed	106 mph
0 - 60 mph	12.1 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	101 BHP
Max. torque	250 Nm at 1.300 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	54.3 mpg
CO2 emission	136 g/km
CO2 label	E







Internet history


Entry 2

Date

Pictures

2023-12-13

9



source: g3remarketing.co.uk

Entry 1	
Date	2022-02-11
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-16
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	11
Total items failed	4

MOT #7	2023-04-24 10:25
MOT test number	325304152018
Result	✓ Passed
Next expiry date 2024-0	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #6	2022-05-17 13:54
MOT test number	765612504390
Result	✓ Passed

MOT #5	2021-10-06 10:15
MOT test number	416657825743
Result	✓ Passed
Advice Handbrake traveller getting high.	
Advice Front Brake disc worn, but not excessively both (1.1.	14 (a) (i))
Advice Vehicle fitted with under shield limiting view on som	e components



NK66BKU report date: 2024-03-28

MOT #4		2020-10-08 15:59
MOT test	number	291858585067
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #3	2020-10-08 11:22
MOT test number	136426114644
Result	🗙 Failed
Fail Nearside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))	
Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
FailOffside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #2		2019-07-16 12:01
MOT test	number	312252578144
Result		✓ Passed
Advice (5.2.3 (e))	Nearside Front Tyre worn close to legal limit/worn on edge 3mm	n tread and worn on inner egde
MOT #1		2019-07-10 15:52
MOT test	numbor	516489413676

MOT test number	516489413676
Result	🗙 Failed
Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm tread and worn (5.2.3 (e))	ı on inner egde
Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Advice TPMS light on	



Tax & MOT check

Taxed Tax due: 1 December 2024	MOT Expires: 16 May 2024
Tax status	Valid until 1 December
Days left	217
MOT expiry date	16 May 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Demons 2	AMPLE
Damage 2	6
Date	1.4
Category	AMPL
Туре	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Format maintration	
Carrient registration	
Parla since	





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow



NK66BKU report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-09-06
Last registration	2023-04-24
Complete history	<u>See info</u>



Registration #1	2016-09-06	24 mi
Registration #2	2019-07-10	29.006 mi
Registration #3	2019-07-16	29.006 mi
Registration #4	2020-10-08	40.786 mi
Registration #5	2020-10-08	40.787 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 esi

More info >





Car features

S0225	Air conditioning
\$0295	
\$0482	
\$0501	
50566	
\$0567	
S0569	

Safety ratings

NCAP rating	
Adult	84%
Children	78%
Pedestrian	58%
Safety systems	68%
Overall rating	74%
Video	see crash video



Dimensions & weight	
Width	1793 mm
Height	1831 mm
Length	4878 mm
Kerb weight	577 kg
Max. allowed weight	2360 kg
Additional information	
Fuel tank capacity	60 I

Fuel тапк сарасіту	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
CarCheck.co.uk	page 11/11

Engine number

DFSD068978