





General information

| Make | KIA |
|---------------------|-------------------|
| Model | VENGA 2 |
| Colour | Silver |
| Year of manufacture | 2016 |
| Top speed | 112 mph |
| 0 - 60 mph | 11.1 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 123 BHP |
|-------------------------|---------------------|
| Max. torque | 156 Nm at 4.200 rpm |
| Engine capacity | 1.591 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 32.8 mpg |
| Consumption extra urban | 54.3 mpg |
| Consumption combined | 43.5 mpg |
| CO2 emission | 150 g/km |
| CO2 label | F |





Internet history Entry 2 2024-03-29 Date Pictures 2 Listing price View report This dealer has AA This dealer has AA signed up to our signed up to our Dealer Promise. Dealer Promise. Free history check
6 months (minimum) MOT
Free 12 months Breakdown cover Free history check
6 months (minimum) MOT
Free 12 months Breakdown cover aacars.com 6 aacars.com 6 source: cargurus.co.uk Entry 1 Date 2021-06-14 **Pictures** 1

View report

Listing price



source: autotrader.co.uk



MOT history

| MOT expiry date | 2024-07-16 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 5 |
| Failed MOT tests | 0 |
| Total advice items | 0 |
| Total items failed | 0 |

| MOT #5 | 2023-06-27 08:30 |
|------------------|------------------|
| MOT test number | 539240293450 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-16 |

| MOT #4 | 2022-07-14 09:51 |
|-----------------|------------------|
| MOT test number | 552761691169 |
| Result | ✓ Passed |

| MOT #3 | 2021-06-28 15:56 |
|-----------------|------------------|
| MOT test number | 510387189981 |
| Result | ✓ Passed |

| MOT #2 | 2020-07-17 08:49 |
|-----------------|------------------|
| MOT test number | 219214863176 |
| Result | ✓ Passed |
| | |

| MOT #1 | 2019-06-21 14:57 |
|-----------------|------------------|
| MOT test number | 205953121079 |
| Result | ✓ Passed |





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-----------|
| Date | FE CO |
| Category | Lashe |
| Туре | |
| Damage 2 | AMPLE |
| Damaye 2 | e e et al |
| Date | 1. |
| Category | AMP |
| Туре | |

Extra KIA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.11.111 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 11 711 |





Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| *********** | |
| ******** | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this KIA had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Carrent registration | |
| Plate since | |
| | |





Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 8 |
| First mileage registration | 2016-07-18 |
| Last registration | 2023-06-27 |
| Complete history | See info |



| Registration #1 | 2016-07-18 | 9 mi |
|-----------------|------------|------------|
| Registration #2 | 2019-06-21 | 7.102 mi |
| Registration #3 | 2020-07-17 | 15.057 mi |
| Registration #4 | | 11.777 est |
| Registration #5 | | 11.777 mi |
| Registration #6 | | 11.777 esi |
| Registration #7 | | 11.777 mi |
| Registration #8 | | 11.117 esi |





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| S0482 | |
| \$0501 | |
| S0566 | |
| \$0567 | |
| \$0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 89% |
| Children | 85% |
| Pedestrian | 64% |
| Safety systems | 71% |
| Overall rating | 81% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|-----------------------|
| Width | 1765 mm |
| Height | 1600 mm |
| Length | 4075 mm |
| Wheel base | 2615 mm |
| Kerb weight | 1410 kg |
| Max. allowed weight | 1780 kg |
| Additional information | |
| Fuel tank capacity | 50 |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 9/9 |

| Number of axles | 2 |
|-----------------|--------------|
| Engine number | G4FCFZ589529 |