




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOUAREG V6 R-LINE TDI BLUEMOTION TECHNOLOGY
Colour	White
Year of manufacture	2016
Top speed	140 mph
0 - 100 km/h	7.3 seconds
0 - 60 mph	7.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	193 kW / 263 HP / 258 BHP
Max. torque	580 Nm at 1.750 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	42.8 mpg
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 2

Date	2021-12-02
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2021-11-19
Pictures	19
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-11-23
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	4
Total items failed	5

MOT #7 2023-11-24 10:53

MOT test number 609084562325

Result ✓ Passed

Next expiry date 2024-11-23

Advice Underside of vehicle muddy /undertrays fitted**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))

MOT #6 2023-11-23 13:22

MOT test number 159566771898

Result ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Underside of vehicle muddy /undertrays fitted**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #5 2022-10-20 09:54

MOT test number 623355136406

Result ✓ Passed



MOT #4	2021-11-04 15:23
MOT test number	302000716610
Result	✓ Passed
MOT #3	2021-11-04 09:22
MOT test number	484815077866
Result	✗ Failed
<div><div>Fail</div>Rear fog lamp not working (4.5.1 (a) (ii))</div>	
MOT #2	2020-11-16 11:45
MOT test number	494487258559
Result	✓ Passed
MOT #1	2019-11-11 15:05
MOT test number	867863080747
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
23 November 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	23 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 HX66LNM
Plate since	2019-06-29
Current registration	 HX66LNM
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-11-17
Last registration	2023-11-24
Complete history	See info



Registration #1	2016-11-17	25 mi
Registration #2	2019-11-11	32.510 mi
Registration #3	2020-11-16	34.621 mi
Registration #4	2021-11-04	39.120 mi
Registration #5	2021-11-04	39.120 mi
Registration #6	2022-11-20	39.120 mi
Registration #7	2022-11-20	39.120 mi
Registration #8	2022-11-20	39.120 mi
Registration #9	2023-11-24	39.120 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2208 mm
Height	1732 mm
Length	4889 mm
Wheel base	2893 mm
Kerb weight	2185 kg
Max. allowed weight	2880 kg

Additional information

Fuel tank capacity	85 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CVVA059204