



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	LAGUNA DYNAMIQUE DCI FAP ECO2
Colour	Silver
Year of manufacture	2009
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	53.3 mpg
CO2 emission	140 g/km
CO2 label	E





MOT history

MOT expiry date	2021-08-11
MOT pass rate	60 %
MOT passed	9
Failed MOT tests	6
Total advice items	42
Total items failed	18

MOT #152020-08-04 11:20

MOT test number931147587818

Result✓ Passed

Next expiry date2021-08-11

- Advice

Central Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice

Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice

Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #14**

2019-08-12 13:13

MOT test number

233097562384

Result

✓ Passed

Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Offside Front Inner Tyre worn close to legal limit/worn on edge Tyre tread at 3mm (5.2.3 (e))

Advice

Nearside Front Upper Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

Advice

Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice

Rear Outer Brake pad(s) wearing thin pads at 2.5mm (1.1.13 (a) (ii))

Advice

Central Rear Brake pipe corroded, covered in grease or other material pipe at rear flexi covered in grease center section (1.1.11 (c))

MOT #13

2019-07-18 10:23

MOT test number

935085497112

Result

✗ Failed

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail

Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Pass with rectification

Headlamp aim too low BOTH FRONT (4.1.2 (a))

Fail

Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice

Brake pipe corroded, covered in grease or other material both front to rear @ rear (1.1.11 (c))

Fail

Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

**MOT #12**

2018-07-25 09:58

MOT test number

603547734092

Result

✓ Passed

- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Engine covers and under trays fitted
- Advice** Brake pipe corroded, covered in grease or other material both front to rear at rear (1.1.11 (c))
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both lower foremost bushes (5.3.4 (a) (i))
- Advice** Injection system fault on dash
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #11

2017-07-25 14:37

MOT test number

161404308302

Result

✓ Passed

- Advice** Both rear axle bushes deteriorated
- Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement both (2.4.G.2)

MOT #10

2017-07-25 10:36

MOT test number

930270559385

Result

✗ Failed

- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)
- Advice** Both rear axle bushes deteriorated
- Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement both (2.4.G.2)

**MOT #9**

2017-06-16 14:59

MOT test number

969983375137

Result**✗ Failed****Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Offside rear tyre has a screw in it**Fail** Rear brake application uneven (3.7.B.2)**MOT #8**

2016-06-14 13:59

MOT test number

708255804461

Result**✓ Passed****Advice** CHILD SEATS FITTED TO REAR UNABLE TO CARRY OUT FULL INSPECTION**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #7**

2016-06-14 10:31

MOT test number

826677556341

Result**✗ Failed**

Fail Offside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Fail Offside Rear Registration plate lamp not working (1.1.C.1d)

Advice Offside Rear Shock absorber has a light misting of oil (2.7.3)

Fail Nearside Front Headlamp aim too high (1.8)

Fail Nearside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Fail Nearside Rear Registration plate lamp not working (1.1.C.1d)

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice CHILD SEATS FITTED TO REAR UNABLE TO CARRY OUT FULL INSPECTION

Fail Offside Front Headlamp aim too high (1.8)

MOT #6

2015-06-15 08:27

MOT test number

688266765198

Result**✓ Passed**

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice Nail in offside rear tyre

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #5** 2015-06-13 13:00**MOT test number** 665334365168**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Nail in offside rear tyre**MOT #4** 2014-09-23 15:19**MOT test number** 767586264270**Result** ✓ Passed**MOT #3** 2013-10-22 15:59**MOT test number** 547215093271**Result** ✓ Passed**Notice** Particulate filter pressure pipe split**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)**MOT #2** 2013-10-22 15:59**MOT test number** 476425293286**Result** ✗ Failed**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Notice** Particulate filter pressure pipe split**MOT #1** 2012-10-02 16:52**MOT test number** 359726272443**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
14 August 2020

✕
MOT

Expired:
11 August 2021

Tax status	Expired at 14 August 2020
Days left	1355 days too late
MOT expiry date	11 August 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36
Agreement number	123456789
Contact info	01234 567890

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-10-26
Last registration	2020-08-04
Complete history	See info



Registration #1	2009-10-26	12 mi
Registration #2	2012-10-02	89.677 mi
Registration #3	2013-10-22	117.129 mi
Registration #4	2014-09-23	122.539 mi
Registration #5	2015-06-13	129.262 mi
Registration #6	2015-06-15	129.262 mi
Registration #7	2016-06-14	133.753 mi
Registration #8	2016-06-14	133.758 mi
Registration #9	2016-06-14	133.758 mi
Registration #10	2016-06-14	133.758 mi
Registration #11	2016-06-14	133.758 mi
Registration #12	2016-06-14	133.758 mi
Registration #13	2016-06-14	133.758 mi
Registration #14	2016-06-14	133.758 mi
Registration #15	2016-06-14	133.758 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1811 mm
Height	1445 mm
Length	4801 mm
Wheel base	2758 mm
Kerb weight	1483 kg
Max. allowed weight	2051 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	C000385