



report date: 2024-03-29

General information

Make	VOLVO
Model	S60 D2 SE LUX
Colour	Black
Year of manufacture	2015
Top speed	121 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	78.5 mpg
Consumption combined	72.4 mpg
CO2 emission	103 g/km
CO2 label	B





Internet history

Entry 2


Date	2022-05-03
Pictures	10
Listing price	View report



source: [yesauto.com](#)

Entry 1

Date	2022-04-30
Pictures	11
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2025-03-25
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	16
Total items failed	2

MOT #9	2024-03-12 10:05
MOT test number	953603545882
Result	✓ Passed
Next expiry date	2025-03-25
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #8	2023-03-20 10:09
MOT test number	913316197208
Result	✓ Passed
Advice	Front Track rod end ball joint has slight play both sides (2.1.3 (b) (i))

MOT #7	2022-03-10 09:14
MOT test number	500152215241
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 215/50/17 (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6** 2022-03-07 12:54**MOT test number** 830475168132**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 215/50/17 (5.2.3 (e))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #5** 2021-03-11 09:47**MOT test number** 315804884939**Result** ✓ Passed**MOT #4** 2020-03-17 15:53**MOT test number** 567472452301**Result** ✓ Passed**Advice** Rear brakes binding slightly**MOT #3** 2020-03-17 11:59**MOT test number** 670123421888**Result** ✗ Failed**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure 215/50/17 (5.2.3 (d) (ii))**Advice** Rear brakes binding slightly**MOT #2** 2019-03-08 12:57**MOT test number** 914212871946**Result** ✓ Passed



MOT #1	2018-03-14 09:33
MOT test number	257431949031
Result	✓ Passed
Advice	Rear inner brake pads wearing low



Tax & MOT check

✓
Taxed

Tax due:
1 May 2024

✓
MOT

Expires:
25 March 2025

Tax status	Valid until 1 May
Days left	3
MOT expiry date	25 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YY15CVM
Plate since	2015-09-29
Current registration	YY15CVM
Plate since	2015-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-03-26
Last registration	2024-03-12
Complete history	See info



Registration #1	2015-03-26	21 mi
Registration #2	2018-03-14	38.489 mi
Registration #3	2019-03-08	47.990 mi
Registration #4	2020-03-17	57.224 mi
Registration #5	2020-03-17	57.224 mi
Registration #6	2021-03-11	61.104 mi
Registration #7	2022-03-20	65.277 mi
Registration #8	2022-03-20	65.277 mi
Registration #9	2022-03-20	65.277 mi
Registration #10	2022-03-20	65.277 mi
Registration #11	2022-03-20	65.277 mi
Registration #12	2024-03-12	69.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2097 mm
Height	1484 mm
Length	4635 mm
Wheel base	2715 mm
Kerb weight	1544 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	4171507