





report date: 2024-03-29

General information

Make	TOYOTA
Model	VERSO D-4D TR
Colour	Red
Year of manufacture	2011
Top speed	115 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	310 Nm at 1.800 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/15



report date: 2024-03-29

Internet history

Entry 2

Date 2022-02-18

Pictures 20

Listing price <u>View report</u>










source: yesauto.com

Entry 1

Date	2021-08-19
Pictures	21

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-29

MOT history

MOT expiry date	2025-03-14
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	53
Total items failed	4

MOT #12		2024-03-15 18:27
MOT test	number	900990130359
Result		✓ Passed
Next expi	ry date	2025-03-14
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1	.11 (c))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1	.1.11 (c))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened	d (1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weaken	ed (1.1.14 (a) (ii))

MOT #11	2023-01-17 09):22
MOT test	number 1153624003	325
Result	✓ Pas	sed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		ŀ
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

CarCheck.co.uk page 3/15



report date: 2024-03-29

MOT #10 2022-01-08 15:46

MOT test number 670955679691

Result ✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Brake pipe corroded, covered in grease or other material both side (1.1.11 (c))

MOT #9 2022-01-08 15:46

MOT test number 395960309833

Result X Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Rear Brake pipe corroded, covered in grease or other material both side (1.1.11 (c))

MOT #8 2020-12-09 11:54

MOT test number 730361827483

Result

Passed

Advice Offside Rear Brake pipe corroded, covered in grease or other material between brake hoses (1.1.11 (c))

Advice Items i n boot

Advice Engine covers and under trays fitted

Minor Front Windscreen wiper blade defective both starting to smear slightly (3.4 (b) (i))

Advice Rear wiper blade split

MOT #7 2019-06-20 16:33

MOT test number 101658068511

Result ✓ Passed

CarCheck.co.uk page 4/15



report date: 2024-03-29

MOT #6 2018-01-25 13:49

MOT test number 726924167880

Result ✓ Passed

Advice

Brake disc worn, pitted or scored, but not seriously weakened rear brake discs inner surface

(3.5.1i)

 MOT #5
 2017-02-04 15:29

 MOT test number
 927844485944

Advice Oil leak

Advice 3rd row seats folded away with items in boot

Advice Exhaust middle support bracket corroded off

Advice Engine covers and under trays fitted

MOT #4 2017-02-04 10:28

MOT test number 414083164199

Result X Failed

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

Advice 3rd row seats folded away with items in boot

Advice Oil leak

Advice Exhaust middle support bracket corroded off

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Engine covers and under trays fitted

CarCheck.co.uk page 5/15



report date: 2024-03-29

MOT #3 2016-02-05 16:37

MOT test number 919972733462

✓ Passed Result Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1) Advice Advice Sill covers fitted Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1) Advice Engine covers fitted Advice Nearside Rear Tyre worn close to the legal limit 2.5mm (4.1.E.1) Advice Under-trays fitted

CarCheck.co.uk page 6/15



Advice

Advice

Sill covers fitted

ND61AWY

report date: 2024-03-29

MOT #2 2016-02-05 10:08

MOT test number 673979769892

Result **X** Failed Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2) Advice Nearside wiper blade split Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Offside Front Brake pad(s) wearing thin (3.5.1g) Advice Engine covers fitted Advice Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1) Nearside Headlamp insecure (1.7.3) Fail **Advice** Under-trays fitted Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Nearside Front Brake pad(s) wearing thin (3.5.1g) Advice Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1) Advice Nearside Front bumper insecure

Nearside Rear Tyre worn close to the legal limit 2.5mm (4.1.E.1)

CarCheck.co.uk page 7/15



report date: 2024-03-29

MOT #1 2015-02-05 16:01 **MOT test number** 628906635030 Result ✓ Passed Notice Under-trays fitted obscuring some underside components Notice Sill covers fitted Advice Nearside Front Brake pad(s) wearing thin (3.5.1g) Notice Engine covers fitted obscuring some components in the engine bay Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 8/15



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	14 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 9/15



report date: 2024-03-29

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



Plate since

ND61AWY

report date: 2024-03-29

More info >

Owner history	
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full r	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK UK

CarCheck.co.uk page 12/15



report date: 2024-03-29

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-12-23
Last registration	2024-03-15
Complete history	See info



Registration #1	2011-12-23	20 mi
Registration #2	2015-02-05	20.742 mi
Registration #3	2016-02-05	34.562 mi
Registration #4	2016-02-05	34.563 mi
Registration #5	2017-02-04	53.230 mi
Registration #6	2017-02-04	53.230 mi
Registration #7	2018-01-25	66.290 mi
Registration #8	2019-06-20	76.123 mi
Registration #9		9.77 es
Registration #10		11.777 es
Registration #11		9.777 es
Registration #12		11.777 es
Registration #13		9.777 es
Registration #14		0.00 44
Registration #15		11,177 es

More info >

CarCheck.co.uk page 14/15



ND61AWY report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

More info >

Safety ratings

NCAP rating	****
Adult	89%
Children	75%
Pedestrian	69%
Safety systems	86%
Overall rating	82%
Video	see crash video

View the complete TOYOTA factory list for this vehicle here.



Dimensions & weight

Width	1790 mm
Height	1620 mm
Length	4440 mm
Wheel base	2780 mm
Kerb weight	1625 kg
Max. allowed weight	2260 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 15/1

Number of axles 2

Engine number 1AD5604578