




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN SE TDI
Colour	Red
Year of manufacture	2012
Top speed	114 mph
0 - 100 km/h	12.8 seconds
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	77 kW / 105 HP / 103 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 2


Date	2021-10-23
Pictures	24
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-09-14
Pictures	53
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-01-13
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	18
Total items failed	6

MOT #12 2024-01-12 10:03

MOT test number 827583661239

Result ✓ Passed

Next expiry date 2025-01-13

Advice Front Lower Suspension arm pin or bush worn but not resulting in excessive movement n/s and o/s (5.3.4 (a) (i))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Nearside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))

Advice Undetected peak exhaust emissions

MOT #11 2023-01-09 10:20

MOT test number 527860971849

Result ✓ Passed

Advice Undetected peak exhaust emissions

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement n/s and o/s (5.3.4 (a) (i))

MOT #10 2022-01-10 09:51

MOT test number 437667149087

Result ✓ Passed

Advice UNDETECTED PEAK EXHAUST EMISSIONS

**MOT #9** 2021-01-07 14:24**MOT test number** 200840047021**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge Wearing low inside edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Worn smooth inside and outside tread (5.2.3 (e))**MOT #8** 2021-01-04 16:10**MOT test number** 133487238537**Result** ✗ Failed**Minor** Nearside Rear Tyre obviously under inflated (5.2.3 (l))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Rear Service brake lagging in operation (1.2.1 (d))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge Wearing low inside edge (5.2.3 (e))**Fail** Nearside Front Service brake lagging in operation (1.2.1 (d))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Worn smooth inside and outside tread (5.2.3 (e))**Advice** Brake disc worn, pitted or scored, but not seriously weakened Both rear pitted (1.1.14 (a) (ii))**MOT #7** 2020-01-14 10:17**MOT test number** 808105753175**Result** ✓ Passed

**MOT #6** 2020-01-08 12:15**MOT test number** 146938276369**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Smooth inner edge and close to wear bars - 205/55/16 (5.2.3 (e))**MOT #5** 2019-01-07 15:15**MOT test number** 630039063253**Result** ✓ Passed**MOT #4** 2019-01-07 12:20**MOT test number** 214988320502**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed 205/55/16 (5.2.3 (d) (ii))**Advice** Nearside Front Tyre wearing low inside tread**MOT #3** 2018-01-10 12:36**MOT test number** 139406375893**Result** ✓ Passed**MOT #2** 2016-10-11 09:52**MOT test number** 909894653809**Result** ✓ Passed**Advice** SMALL CHIP ON WINDSCREEN**Advice** Nearside Front WHEEL RIM DAMAGED



MOT #1	2015-11-02 13:55
MOT test number	180128459309
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
13 January 2025

Tax status	Valid until 1 November
Days left	186
MOT expiry date	13 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 SW62DLF
Plate since	2019-06-29
Current registration	 SW62DLF
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-12-19
Last registration	2024-01-12
Complete history	See info



Registration #1	2012-12-19	14 mi
Registration #2	2015-11-02	33.495 mi
Registration #3	2016-10-11	43.778 mi
Registration #4	2018-01-10	61.488 mi
Registration #5	2019-01-07	81.729 mi
Registration #6	2019-01-07	81.729 mi
Registration #7	2020-01-08	103.832 mi
Registration #8	2020-01-14	103.832 mi
Registration #9	2020-01-20	150,000 (estimated)
Registration #10	2020-02-01	150,000 (estimated)
Registration #11	2020-02-15	150,000 (estimated)
Registration #12	2020-03-01	150,000 (estimated)
Registration #13	2020-03-15	150,000 (estimated)
Registration #14	2020-04-01	150,000 (estimated)
Registration #15	2024-01-12	150,000 (estimated)

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1474 mm
Length	4397 mm
Wheel base	2678 mm
Kerb weight	1539 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles

2

Engine number

CAYCK90899