




report date: 2024-03-29

General information

Make	VAUXHALL
Model	VIVARO 2900 SPORTIVE S/S L2H1 2900 SPORTIVE S/S
Colour	White
Year of manufacture	2019
Top speed	90 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	101 BHP
Max. torque	270 Nm at 1.600 rpm
Engine capacity	1.499 cc
Cylinders	4
Fuel type	Diesel
Consumption combined	38.2 mpg
CO2 emission	135 g/km
CO2 label	E





## Internet history

## Entry 4

Date	2021-12-14
Pictures	10
Listing price	<a href="#">View report</a>

source: [autoonline.co.uk](https://autoonline.co.uk)

## Entry 3

Date	2021-11-20
Pictures	16
Listing price	<a href="#">View report</a>

source: [yesauto.com](https://yesauto.com)

## Entry 2

Date	2021-11-18
Pictures	0
Listing price	<a href="#">View report</a>

source: [heycar.co.uk](https://heycar.co.uk)

## Entry 1

Date	2021-11-16
Pictures	8
Listing price	<a href="#">View report</a>

Nationwide  
Contactless  
Delivery  
+ Online Click &  
Collect Available  
Today



VAUXHALL



CONTACT US NOW

PHONE EMAIL LIVE CHAT APPLE CHAT

FACEBOOK TWITTER

There are many ways you can  
contact Pentagon Motor Group



GAP  
INSURANCE

AVAILABLE ON  
THIS VEHICLE



source: [cargurus.co.uk](http://cargurus.co.uk)



MOT history

MOT expiry date	2025-01-30
MOT pass rate	67 %
MOT passed	2
Failed MOT tests	1
Total advice items	7
Total items failed	4

MOT #3	2024-01-31 11:35
MOT test number	808808440701
Result	✓ Passed
Next expiry date	2025-01-30
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside sliding door does not close properly but is secure

MOT #2	2024-01-31 09:25
MOT test number	537547968040
Result	✗ Failed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside sliding door does not close properly but is secure
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Offside Headlamp insecure (4.1.1 (c))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Front Tyre worn close to legal limit/worn on edge both, worn outer edges (5.2.3 (e))
Fail	Nearside Headlamp insecure (4.1.1 (c))
Fail	Central Seat belt buckle missing (7.1.2 (d))



MOT #1	2022-11-08 09:20
MOT test number	156327285038
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
30 January 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	30 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 320,00,-
<b>Standard rate (6 months)</b>	£ 176,00,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history


For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>DS69ZYN</b>
Plate since	2024-03-29
Current registration	 <b>DS69ZYN</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2019-10-28
Last registration	2024-01-31
Complete history	<a href="#">See info</a>



Registration #1	2019-10-28	23 mi
Registration #2	2020-05-28	25,000 mi
Registration #3	2020-10-28	25,000 mi
Registration #4	2021-05-28	25,000 mi
Registration #5	2021-10-28	25,000 mi
Registration #6	2022-05-28	25,000 mi
Registration #7	2022-10-28	25,000 mi
Registration #8	2023-05-28	25,000 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1920 mm
Height	1935 mm
Length	5309 mm
Kerb weight	1770 kg
Max. allowed weight	2830 kg

Additional information

Number of seats	3
Number of axles	2
Engine number	10Q4DK0012698 O4B