





General information

Make	NISSAN
Model	X-TRAIL DCI N-CONNECTA
Colour	Blue
Year of manufacture	2018
Top speed	116 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	128 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	62.8 mpg
Consumption combined	57.6 mpg
CO2 emission	133 g/km
CO2 label	E







Internet history


Entry 3

Date

Pictures

2023-12-13

8



source: g3remarketing.co.uk

Entry 2	
Date	2021-11-08
Pictures	4
Listing price	View report



source: autotrader.co.uk

Entry 1	
Date	2021-11-01
Pictures	4
Listing price	View report







new cars coming soon. Tree car finance check in under 50 seconds.

source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-06
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	12
Total items failed	2

MOT #5	2023-10-17 11:04
MOT test number	649988938455
Result	✓ Passed
Next expiry date	2024-11-06

MOT #4		2022-11-03 17:04
MOT test	number	170685635135
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	





MOT #3	2022-11-03 10:22
MOT test number	294665442527
Result	🗙 Failed
Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Nearside Front Shock absorbers has negligible damping effect (5.3.2 (d))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #2		2021-11-07 17:09
MOT test i	number	899160361409
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #1	2021-04-27 10:16
MOT test number	619038782521
Result	✓ Passed
Advice Nearside Rear Nail in tyre non repairable puncture.	



Tax & MOT check

✓ Taxed	✓ MOT
Tax due: 1 April 2025	Expires: 6 November 2024
Tax status	Valid until 1 April
Days left	336
MOT expiry date	6 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	н
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-07-23
Last registration	2023-10-17
Complete history	See info



Registration #1	2018-07-23	21 mi
Registration #2	2021-04-27	10.626 mi
Registration #3		11.777 mi
Registration #4	2021-11-07	12.558 mi
Registration #5		11.777 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		10.300 est





Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
0569	

Safety ratings

NCAP rating	****
Adult	86%
Children	83%
Pedestrian	75%
Safety systems	75%
Overall rating	81%
Video	see crash video



Dimensions & weight	
Width	1820 mm
Height	1740 mm
Length	4690 mm
Wheel base	2705 mm
Kerb weight	1505 kg
Max. allowed weight	2260 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 11/11