



report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | VOLKSWAGEN |
| Model | BEETLE 8V |
| Colour | Yellow |
| Year of manufacture | 2003 |
| Top speed | 111 mph |
| 0 - 60 mph | 12.3 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 102 BHP |
| Max. torque | 147 Nm at 3.800 rpm |
| Engine capacity | 1.596 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 26.9 mpg |
| Consumption extra urban | 47.1 mpg |
| Consumption combined | 36.7 mpg |
| CO2 emission | 185 g/km |
| CO2 label | I |





Internet history

Entry 2


| | |
|---------------|-----------------------------|
| Date | 2021-02-05 |
| Pictures | 1 |
| Listing price | View report |



source: autoonline.co.uk

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-01-21 |
| Pictures | 12 |
| Listing price | View report |



source: yesauto.com



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-12-11 |
| MOT pass rate | 74 % |
| MOT passed | 17 |
| Failed MOT tests | 6 |
| Total advice items | 49 |
| Total items failed | 23 |

| | |
|------------------|--|
| MOT #23 | 2023-11-24 12:36 |
| MOT test number | 869419234114 |
| Result | ✓ Passed |
| Next expiry date | 2024-12-11 |
| Advice | Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |

| | |
|-----------------|--|
| MOT #22 | 2023-11-21 14:22 |
| MOT test number | 309345879231 |
| Result | ✗ Failed |
| Advice | Exhaust mounting defective (6.1.2 (a)) |
| Fail | Offside Front Seat belt anchorage prescribed area strength or continuity significantly reduced outer sil (7.1.1 (a) (i)) |
| Fail | Brake pedal has insufficient reserve travel (1.1.2 (a)) |
| Fail | Nearside Front Subframe mounting prescribed area excessively corroded significantly reducing structural strength outer sil (5.3.6 (a) (i)) |
| Fail | Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii)) |
| Advice | Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Throttle sticks on |
| Fail | Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii)) |

**MOT #21** 2022-12-12 16:01**MOT test number** 351384666789**Result** ✓ Passed**MOT #20** 2022-12-01 14:49**MOT test number** 165628359843**Result** ✗ Failed

Fail Offside Rear Inner Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))

Fail Nearside Front Suspension component ball joint excessively worn (5.3.4 (a) (i))

Fail Nearside Rear Inner Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))

Fail Offside Front Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

MOT #19 2021-11-05 12:19**MOT test number** 667601265784**Result** ✓ Passed

**MOT #18**

2021-11-01 06:57

MOT test number

861408173666

Result**✗ Failed****Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps near and offside (4.7.1 (b) (ii))**Fail** Power steering malfunctioning (2.1.5 (a))**Advice** Power steering fluid reservoir insecure**Fail** Offside Side repeater not working (4.4.1 (a) (ii))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))**Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #17**

2019-12-19 12:48

MOT test number

691880464091

Result

✓ Passed

- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust back box leak
- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #16

2019-01-03 17:08

MOT test number

390133556968

Result

✓ Passed

- Advice** Nearside Rear Shock absorbers has slight external damage to the casing corrosion (5.3.2 (b))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Shock absorbers has slight external damage to the casing corrosion (5.3.2 (b))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #15**

2019-01-03 13:45

MOT test number

165476109306

Result**✗ Failed****Advice** Nearside Rear Shock absorbers has slight external damage to the casing corrosion (5.3.2 (b))**Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Rear Shock absorbers has slight external damage to the casing corrosion (5.3.2 (b))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #14**

2018-01-04 14:54

MOT test number

598623995961

Result**✓ Passed****Advice** Rear Shock absorber has slight corrosion to the casing BOTH SIDES (2.7.2a)**Advice** Front Brake pipe slightly corroded BOTH SIDES (3.6.B.2c)**MOT #13**

2018-01-04 13:58

MOT test number

763280931241

Result**✗ Failed****Fail** Offside Rear coil spring broken (2.4.C.1a)**Advice** Rear Shock absorber has slight corrosion to the casing BOTH SIDES (2.7.2a)**Advice** Front Brake pipe slightly corroded BOTH SIDES (3.6.B.2c)

**MOT #12** 2016-09-19 13:15**MOT test number** 438457807345**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has slight corrosion to the casing (2.7.2a)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Rear Shock absorber has slight external damage to the casing (2.7.2a)**MOT #11** 2016-09-19 09:02**MOT test number** 489291623516**Result** ✗ Failed**Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)**Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Offside Rear Shock absorber has slight external damage to the casing (2.7.2a)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Rear Shock absorber has slight corrosion to the casing (2.7.2a)**MOT #10** 2015-09-25 10:31**MOT test number** 116963174938**Result** ✓ Passed**Advice** Offside Front Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)**MOT #9** 2014-10-02 14:01**MOT test number** 269625174271**Result** ✓ Passed

**MOT #8** 2013-09-12 12:02**MOT test number** 266005753291**Result** ✓ Passed**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Notice** Vehicle's internal headlight adjuster altered to recheck lights**MOT #7** 2012-09-28 11:02**MOT test number** 548802872277**Result** ✓ Passed**MOT #6** 2011-09-30 11:41**MOT test number** 399493471490**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** N/S mirror damaged**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2010-09-13 11:50**MOT test number** 690776050217**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #4** 2009-10-01 10:08**MOT test number** 931134879203**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** N/S mirror damaged**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Centre Exhaust has part of the system slightly deteriorated (7.1.1a)**MOT #3** 2008-09-22 10:37**MOT test number** 254196768286**Result** ✓ Passed**MOT #2** 2007-10-01 10:32**MOT test number** 711334877221**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #1** 2006-09-18 14:38**MOT test number** 652851866205**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
11 December 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 June |
| Days left | 34 |
| MOT expiry date | 11 December 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | I |
| Single payment (12 months) | £ 320,00,- |
| Single six month payment | £ 176,00,- |
| Total payable by 12 monthly instalments | £ 336,00,- |



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | NU53MWV |
| Plate since | 2019-06-29 |
| Current registration | NU53MWV |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 26 |
| First mileage registration | 2003-09-17 |
| Last registration | 2023-11-24 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2003-09-17 | 28 mi |
| Registration #2 | 2006-09-18 | 21.814 mi |
| Registration #3 | 2007-10-01 | 29.021 mi |
| Registration #4 | 2008-09-22 | 34.702 mi |
| Registration #5 | 2009-10-01 | 38.721 mi |
| Registration #6 | 2010-09-13 | 42.919 mi |
| Registration #7 | 2011-09-30 | 47.084 mi |
| Registration #8 | 2012-09-28 | 51.933 mi |
| Registration #9 | 2013-09-12 | 57.134 mi |
| Registration #10 | 2014-10-02 | 61.060 mi |
| Registration #11 | 2015-09-25 | 65.618 mi |
| Registration #12 | 2016-09-19 | 70.185 mi |
| Registration #13 | 2016-09-19 | 70.185 mi |
| Registration #14 | 2016-09-19 | 70.185 mi |
| Registration #15 | 2016-09-19 | 70.185 mi |
| Registration #16 | 2016-09-19 | 70.185 mi |
| Registration #17 | 2016-09-19 | 70.185 mi |
| Registration #18 | 2016-09-19 | 70.185 mi |
| Registration #19 | 2016-09-19 | 70.185 mi |
| Registration #20 | 2016-09-19 | 70.185 mi |
| Registration #21 | 2016-09-19 | 70.185 mi |
| Registration #22 | 2016-09-19 | 70.185 mi |
| Registration #23 | 2016-09-19 | 70.185 mi |
| Registration #24 | 2016-09-19 | 70.185 mi |
| Registration #25 | 2016-09-19 | 70.185 mi |
| Registration #26 | 2016-09-19 | 70.185 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

| | |
|-------------|---------|
| Width | 1724 mm |
| Height | 1498 mm |
| Length | 4081 mm |
| Wheel base | 2508 mm |
| Kerb weight | 1385 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 55 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 2 |
| Number of axles | 2 |

Engine number

BFS 009754