



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 R-DESIGN
Colour	Grey
Year of manufacture	2012
Top speed	130 mph
0 - 60 mph	8.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.2 mpg
CO2 emission	177 g/km
CO2 label	I



Internet history

Entry 1

Date	2021-07-07
Pictures	4
Listing price	View report



source: **autotrader.co.uk**



MOT history

MOT expiry date	2024-07-22
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	20
Total items failed	11

MOT #13 2023-07-20 13:48

MOT test number 564128829003

Result ✓ Passed

Next expiry date 2024-07-22

Minor Offside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #12 2023-07-20 10:41

MOT test number 207694639998

Result ✗ Failed

Minor Offside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #11 2022-07-12 09:43

MOT test number 599914364930

Result ✓ Passed

**MOT #10** 2022-07-12 09:43**MOT test number** 916623852563**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #9** 2021-07-23 12:54**MOT test number** 875478198487**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play drop link (5.3.4 (a) (i))**Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #8** 2020-12-17 08:49**MOT test number** 731639351783**Result** ✓ Passed

**MOT #7**

2020-12-04 14:00

MOT test number

628494431476

Result**✗ Failed**

- Fail** Offside Front Tyre(s) of different sizes are fitted on the same axle. different size (5.2.3 (b))
- Fail** Exhaust hydrocarbon content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn rear of arm (5.3.4 (a) (i))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn rear of arm (5.3.4 (a) (i))

MOT #6

2019-09-13 15:29

MOT test number

143831022178

Result**✓ Passed**

- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush (5.3.4 (a) (i))

MOT #5

2018-09-17 16:20

MOT test number

779918555727

Result**✓ Passed**

- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #4** 2017-11-01 12:39**MOT test number** 259813231147**Result** ✓ Passed**Advice** Both rear tyres nearing legal minimum**MOT #3** 2016-10-06 12:12**MOT test number** 509192732237**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2016-10-06 12:12**MOT test number** 966519704865**Result** ✗ Failed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2015-10-03 11:29**MOT test number** 584356551181**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
22 July 2024

Tax status	Valid until 1 March
Days left	307
MOT expiry date	22 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	CT12KZO
Plate since	2019-09-28
Current registration	CT12KZO
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-06-28
Last registration	2023-07-20
Complete history	See info



Registration #1	2012-06-28	13 mi
Registration #2	2015-10-03	23.562 mi
Registration #3	2016-10-06	32.436 mi
Registration #4	2016-10-06	32.436 mi
Registration #5	2017-11-01	45.007 mi
Registration #6	2018-09-17	54.102 mi
Registration #7	2019-09-13	64.506 mi
Registration #8	2020-12-04	66.157 mi
Registration #9	2023-07-20	66.157 mi
Registration #10	2023-07-20	66.157 mi
Registration #11	2023-07-20	66.157 mi
Registration #12	2023-07-20	66.157 mi
Registration #13	2023-07-20	66.157 mi
Registration #14	2023-07-20	66.157 mi
Registration #15	2023-07-20	66.157 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1329 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1097033