



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 2300 L2H1 CDTI S/S ECOFLEX
Colour	Blue
Year of manufacture	2015
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	57.6 mpg
CO2 emission	129 g/km
CO2 label	D





MOT history

MOT expiry date	2024-09-06
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	15
Total items failed	0

MOT #9	2023-08-29 09:09
MOT test number	527897624842
Result	✓ Passed
Next expiry date	2024-09-06
Advice	Tyre worn close to legal limit/worn on edge n/s/f o/s/f (5.2.3 (e))
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #8	2022-09-07 16:04
MOT test number	443769470879
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2022-09-07 08:04**MOT test number** 706585564291**Result** ✗ Failed**MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Brake lever has abnormal movement of levers indicating excessive wear or maladjustment (1.1.15 (f))**MOT #6** 2021-07-22 13:53**MOT test number** 687480243707**Result** ✓ Passed**MOT #5** 2020-07-06 13:45**MOT test number** 541343702119**Result** ✓ Passed**Advice** Nearside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #4** 2019-09-13 14:06**MOT test number** 893289023006**Result** ✓ Passed



MOT #3	2019-07-02 14:24
MOT test number	699229731725
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Offside Headlamp not working on main beam (4.1.1 (a) (ii))
Advice	Nearside Rear Nail in tyre

MOT #2	2018-11-08 09:44
MOT test number	812507182178
Result	✓ Passed

MOT #1	2018-11-02 15:44
MOT test number	679914585369
Result	✗ Failed
MAJOR	Rear Engine mounting damaged or deteriorated resulting in excessive movement (6.1.8 (a) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
6 September 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	6 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	FP65UUN
Plate since	2019-06-29
Current registration	FP65UUN
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-11-12
Last registration	2023-08-29
Complete history	See info



Registration #1	2015-11-12	13 mi
Registration #2	2018-11-02	27.119 mi
Registration #3	2018-11-08	27.120 mi
Registration #4	2019-07-02	30.130 mi
Registration #5	2019-09-13	30.130 mi
Registration #6	2019-09-13	30.130 mi
Registration #7	2019-09-13	30.130 mi
Registration #8	2019-09-13	30.130 mi
Registration #9	2019-09-13	30.130 mi
Registration #10	2019-09-13	30.130 mi

More info >



Dimensions & weight

Width	2119 mm
Height	1880 mm
Length	4740 mm
Kerb weight	1330 kg
Max. allowed weight	2385 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	263A20005486430 LN9