



report date: 2024-03-29

## General information

Make	VOLVO
Model	V60 D3 ES
Colour	White
Year of manufacture	2013
Top speed	127 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	136 BHP
Max. torque	350 Nm at 2.250 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-10-04
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-12-21
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	17
Total items failed	4

MOT #11	2023-12-21 15:29
MOT test number	396945202428
Result	✓ Passed
Next expiry date	2024-12-21

MOT #10	2022-12-16 15:29
MOT test number	571861686778
Result	✓ Passed
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT #9	2022-12-16 11:33
MOT test number	869431874844
Result	✗ Failed
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Fail	Offside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
Fail	Nearside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Fail	Front Windscreen washer not working (3.5 (a))

**MOT #8** 2021-12-17 11:07**MOT test number** 214554475922**Result** ✓ Passed**MOT #7** 2020-12-03 13:53**MOT test number** 756159070857**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #6** 2019-06-22 09:17**MOT test number** 866722984798**Result** ✓ Passed**MOT #5** 2018-04-30 08:28**MOT test number** 842167134611**Result** ✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #4** 2017-05-20 11:00**MOT test number** 626129482842**Result** ✓ Passed**Advice** Small cut to n/s/f tyre on sidewall**Advice** Child Seat fitted not allowing full inspection of adult belt both rear**MOT #3** 2016-05-10 10:46**MOT test number** 613783871006**Result** ✓ Passed**MOT #2** 2016-01-08 14:58**MOT test number** 427241058720**Result** ✓ Passed**Advice** N/s front tyre has light sidewall damage**MOT #1** 2016-01-08 13:04**MOT test number** 536234233094**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** N/s front tyre has light sidewall damage



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
21 December 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	215
<b>MOT expiry date</b>	21 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-01-25
Last registration	2023-12-21
Complete history	<a href="#">See info</a>



Registration #1	2013-01-25	7 mi
Registration #2	2016-01-08	78.548 mi
Registration #3	2016-01-08	78.548 mi
Registration #4	2016-05-10	82.293 mi
Registration #5	2017-05-20	89.956 mi
Registration #6	2018-04-30	96.869 mi
Registration #7	2019-06-22	106.483 mi
Registration #8	2019-06-22	106.483 mi
Registration #9	2019-06-22	106.483 mi
Registration #10	2019-06-22	106.483 mi
Registration #11	2019-06-22	106.483 mi
Registration #12	2019-06-22	106.483 mi
Registration #13	2019-06-22	106.483 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2097 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1632 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	1263673
---------------	---------