





report date: 2024-03-29

General information

| Make | ТОУОТА |
|---------------------|----------------|
| Model | VERSO D-4D TR |
| Colour | Blue |
| Year of manufacture | 2009 |
| Top speed | 115 mph |
| 0 - 60 mph | 11.3 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 125 BHP |
|-------------------------|---------------------|
| Max. torque | 310 Nm at 1.800 rpm |
| Engine capacity | 1.998 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 44.1 mpg |
| Consumption extra urban | 61.4 mpg |
| Consumption combined | 53.3 mpg |
| CO2 emission | 143 g/km |
| CO2 label | F |



CarCheck.co.uk page 1/14



report date: 2024-03-29

Internet history

Entry 1

Date 2021-09-18

Pictures 39

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT history

| MOT expiry date | 2024-09-16 |
|--------------------|------------|
| MOT pass rate | 65 % |
| MOT passed | 13 |
| Failed MOT tests | 7 |
| Total advice items | 16 |
| Total items failed | 17 |

| MOT #20 | | 2023-09-13 09:19 |
|---|--|---------------------------|
| MOT test | number | 711560205038 |
| Result | | ✓ Passed |
| Next expiry date 2024-09-16 | | 2024-09-16 |
| Advice Rear Suspension component corroded but not seriously weakened rear beam axle (5.3.3 (b) (i)) | | peam axle (5.3.3 (b) (i)) |
| Advice | Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1. | 14 (a) (ii)) |

| MOT #19 | 2023-09-12 09:46 | |
|---|------------------------|--|
| MOT test number | 802570307789 | |
| Result | X Failed | |
| Fail Offside Front Tyre has ply or cords exposed 205 55 R16 91V (5.2.3 (d) (ii)) | | |
| Pass with rectification Offside Front Headlamp aim too low (4.1.2 (a)) | | |
| Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) | | |
| Fail Offside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents (5.3.4 (b) (ii)) | s the ingress of dirt | |
| Advice Rear Suspension component corroded but not seriously weakened rear bea | m axle (5.3.3 (b) (i)) | |

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT test number

Result

Advice Central Rear Child Seat fitted not allowing full inspection of adult belt

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT test number

204868115973

Result

Advice Central Rear Child Seat fitted not allowing full inspection of adult belt

Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Rear Direction indicator incorrect colour O/S/R + N/S/R (4.4.3 (a))

 MOT #16
 2021-09-17 13:26

 MOT test number
 786887349620

 Result
 ✓ Passed

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #15 2021-09-16 16:22 **MOT** test number 522408781382 Result × Failed Fail Offside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i)) Fail Nearside Headlamp aim too low (4.1.2 (a)) Registration plate lamp inoperative in the case of a single lamp or all lamps BOTH (4.7.1 (b) (ii)) Fail Nearside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i)) Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 Fail (b) (ii)) **Advice** Rear wiper split + washer in op Fail Offside Headlamp aim too high (4.1.2 (a)) Fail Windscreen wiper does not clear the windscreen effectively BOTH (3.4 (b) (ii))

MOT #14

MOT test number

Francisco

Minor
(i))

2021-08-28 11:45

574876555497

Passed

Passed

Minor
(i))

MOT test number

647687150602

Result

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Pass with rectification Offside Position lamp not working (4.2.1 (a) (ii))

 MOT #12
 2020-08-29 11:40

 MOT test number
 335712990948

 Result
 ✓ Passed

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #11 2019-08-28 10:38

MOT test number 180757399168

Result
✓ Passed

MOT #10 2019-08-28 10:38

MOT test number 225543096332

Result X Failed

Pass with rectification Offside Rear Registration plate lamp does not illuminate simultaneously with the

position lamps (4.7.2 (a))

MOT #9 2018-08-28 16:31

MOT test number 966315031204

Result ✓ Passed

MOT #8 2017-08-30 10:56

MOT test number 408641774449

Result

Passed

Advice Rear both tyres cracking slightly on outer wall

Advice Offside Front Front suspension has slight movement at a suspension ball joint (2.5.A.1c)

Advice Offside Front tyre wearing from inner edge

MOT #7 2016-08-30 12:37

MOT test number 811446983136

Result

Passed

MOT #6 2016-08-30 12:37

MOT test number 626440633002

Result ★ Failed

Pass with rectification Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification Offside Front Headlamp not working on dipped beam (1.7.5a)

CarCheck.co.uk page 6/14



report date: 2024-03-29

| MOT #5 | 2015-08-17 15:40 |
|-----------------|------------------|
| MOT test number | 307862294566 |
| Result | ✓ Passed |

MOT #4 2014-07-28 11:06
MOT test number 869009404211

Result ✓ Passed

MOT #3 2014-07-25 16:42

MOT test number 998896304235

Result X Failed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #2 2013-08-15 11:27

MOT test number 819907923259

MOT #1 2012-08-20 13:00

MOT test number 255823132230

Result

Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 7/14



report date: 2024-03-29

Tax & MOT check





Expires: 16 September 2024

| Tax status | Valid until 1 February |
|------------------|------------------------|
| Days left | 278 |
| MOT expiry date | 16 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | F |
| Single payment (12 months) | £ 200,00,- |
| Single six month payment | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

Owner history

| For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full | | TA |
|---|-----------|----|
| | | |
| | | |
| | | |
| | | |
| ******* | | |
| | | |
| ************* | | |
| | More info | > |
| Plate changes | | |
| See in this check if this TOYOTA had different number plates. | | |
| Number of plates | | |
| Current registration | UK UK | |
| Plate since | | |
| Current registration | UK UK | |
| Plate since | | |
| | More info | > |

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 22 |
| First mileage registration | 2009-10-26 |
| Last registration | 2023-09-13 |
| Complete history | See info |



| Registration #1 | 2009-10-26 | 10 mi |
|------------------|------------|-----------|
| Registration #2 | 2012-08-20 | 35.557 mi |
| Registration #3 | 2013-08-15 | 38.898 mi |
| Registration #4 | 2014-07-25 | 42.490 mi |
| Registration #5 | 2014-07-28 | 42.493 mi |
| Registration #6 | 2015-08-17 | 46.109 mi |
| Registration #7 | 2016-08-30 | 49.834 mi |
| Registration #8 | 2016-08-30 | 49.834 mi |
| Registration #9 | 2017-08-30 | 53.605 mi |
| Registration #10 | 2018-08-28 | 57.284 mi |
| Registration #11 | 2019-08-28 | 60.872 mi |
| Registration #12 | | 11.777 es |
| Registration #13 | | 9.77 66 |
| Registration #14 | | 71.777 es |
| Registration #15 | | 9.77 66 |
| Registration #16 | | 71.777 es |
| Registration #17 | | 9.77 66 |
| Registration #18 | | 71.777 es |
| Registration #19 | | 9.70 es |
| Registration #20 | | 11.777 es |
| Registration #21 | | 11.777 es |
| Registration #22 | | 71.777 66 |
| | | |

More info >

CarCheck.co.uk page 13/14



RO59WXE
report date: 2024-03-29

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1790 mm |
|---------------------|---------|
| Height | 1620 mm |
| Length | 4440 mm |
| Wheel base | 2780 mm |
| Kerb weight | 1625 kg |
| Max. allowed weight | 2260 kg |

Additional information

| Fuel delivery | Direct Injection | |
|-----------------------------------|------------------|-----------|
| Number of doors | 5 | |
| Number of seats | 7 | |
| Number of axles Carcheck.co.uk | 2 p | age 14/14 |