



KRIOOSN


report date: 2024-03-29

General information

Make	AUDI
Model	A4 TDI SE
Colour	Black
Year of manufacture	2010
Top speed	143 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	350 Nm at 2.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	40.4 mpg
Consumption combined	57.7 mpg
CO2 emission	144 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-01-27
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-06-14
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	40
Total items failed	2

MOT #13	2023-06-15 15:27
MOT test number	910563118635
Result	✓ Passed
Next expiry date	2024-06-14
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement All (5.3.4 (a) (i))
Advice	Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #12**

2023-06-14 10:41

**MOT test number**

488722101407

**Result****✗ Failed****MAJOR** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Headlamp levelling device inoperative (4.1.5 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement All (5.3.4 (a) (i))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**MAJOR** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Rear Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Exhaust system insecure (6.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Rear Upper Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #11**

2022-06-13 14:26

**MOT test number**

891137657403

**Result****✓ Passed****MOT #10**

2021-03-02 16:00

**MOT test number**

179315341842

**Result****✓ Passed****Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #9**

2020-03-31 11:11

**MOT test number**

415636347599

**Result**

✓ Passed

**Advice** Slight corrosion on both front top strut mountings**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** O/s front washer jet slightly off set**MOT #8**

2020-03-31 09:11

**MOT test number**

491919369553

**Result**

✗ Failed

**Advice** Slight corrosion on both front top strut mountings**DANGEROUS** Front Undertray likely to become detached (6.2.1 (a) (ii))**Advice** O/s front washer jet slightly off set**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #7**

2019-04-02 10:55

**MOT test number**

742656533308

**Result**

✓ Passed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Play in steering rack inner joint(s)**Advice** Offside Rear Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6** 2018-03-29 11:19**MOT test number** 939988197920**Result** ✓ Passed**Advice** O/s rear tyre worn close to the legal limit on the outer edge**Advice** Both rear brake discs corroded**Advice** Front no plate damaged**Advice** Cooling fan bearing worn**MOT #5** 2017-03-17 10:02**MOT test number** 130226967813**Result** ✓ Passed**MOT #4** 2015-06-02 14:23**MOT test number** 385333555105**Result** ✓ Passed**MOT #3** 2015-05-19 16:46**MOT test number** 297439835143**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2014-05-13 10:59**MOT test number** 878113634171**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Nearside Front Front wheel bearing has slight play (2.5.A.3c)



MOT #1	2013-05-21 10:30
MOT test number	246711843145
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2024

✓  
**MOT**  
**Expires:**  
14 June 2024

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	3
<b>MOT expiry date</b>	14 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-






Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-07-05
Last registration	2023-06-15
Complete history	<a href="#">See info</a>



Registration #1	2010-07-05	20 mi
Registration #2	2013-05-21	43.613 mi
Registration #3	2014-05-13	63.785 mi
Registration #4	2015-05-19	85.389 mi
Registration #5	2015-06-02	85.389 mi
Registration #6	2017-03-17	116.701 mi
Registration #7	2018-03-29	129.812 mi
Registration #8	2019-04-02	140.052 mi
Registration #9	2020-05-20	151.277 mi
Registration #10	2021-05-20	162.502 mi
Registration #11	2022-05-20	173.727 mi
Registration #12	2023-05-20	184.952 mi
Registration #13	2024-05-20	196.177 mi
Registration #14	2025-05-20	207.402 mi
Registration #15	2026-05-20	218.627 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	84%
Pedestrian	39%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1854 mm
Height	1383 mm
Length	4625 mm
Wheel base	2751 mm
Kerb weight	1660 kg
Max. allowed weight	2155 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	CAH 104183