



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	5008 HDI ACTIVE
Colour	Grey
Year of manufacture	2011
Top speed	115 mph
0 - 60 mph	12.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 3

Date 2022-05-26

Pictures 9

Listing price [View report](#)



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 2

Date 2021-10-16

Pictures 17

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date 2021-08-05

Pictures 19

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-04-27
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	21
Total items failed	8

MOT #14	2023-04-28 09:30
MOT test number	143987222206
Result	✓ Passed
Next expiry date	2024-04-27
Minor	Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #13	2022-09-08 10:53
MOT test number	193341289691
Result	✓ Passed
Advice	Front tyres x 2 edges worn

MOT #12	2021-07-14 12:15
MOT test number	140782845616
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #11**

2021-07-14 12:15

MOT test number

313668108981

Result**✗ Failed****Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Pass with rectification** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10**

2021-06-24 08:09

MOT test number

810903024520

Result**✗ Failed****Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively Split (3.4 (b) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Bald on inner edge (5.2.3 (e))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively Split (3.4 (b) (ii))**Advice** Diesel fuel Injector "chuffing"**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Bald on inner edge (5.2.3 (e))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #9** 2020-06-13 08:53**MOT test number** 144408763922**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2019-06-14 13:52**MOT test number** 788787121481**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2.1mm (5.2.3 (e))**MOT #7** 2018-06-16 09:30**MOT test number** 756663645051**Result** ✓ Passed**MOT #6** 2017-06-03 09:26**MOT test number** 511123916205**Result** ✓ Passed**MOT #5** 2017-06-03 09:26**MOT test number** 662450481950**Result** ✗ Failed**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #4** 2016-06-07 15:55**MOT test number** 859554581121**Result** ✓ Passed



MOT #3	2016-06-07 09:12
MOT test number	161684606642
Result	✗ Failed
Fail	Offside Front Tyre has ply or cords exposed (4.1.D.1b)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #2	2015-06-06 10:06
MOT test number	899907055112
Result	✓ Passed

MOT #1	2014-05-29 09:29
MOT test number	969639744128
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed

Tax due:
1 January 2025

✗
MOT

Expired:
27 April 2024

Tax status	Valid until 1 January
Days left	246
MOT expiry date	27 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	EF11OKS
Plate since	2019-03-29
Current registration	EF11OKS
Plate since	2019-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In kilometers
Mileage registrations	18
First mileage registration	2011-06-10
Last registration	2023-04-28
Complete history	See info



Registration #1	2011-06-10	27 mi
Registration #2	2014-05-29	28.517 mi
Registration #3	2015-06-06	38.185 mi
Registration #4	2016-06-07	48.222 mi
Registration #5	2016-06-07	48.250 mi
Registration #6	2017-06-03	59.227 mi
Registration #7	2017-06-03	59.227 mi
Registration #8	2018-06-16	69.624 mi
Registration #9	2019-06-14	78.939 mi
Registration #10	2020-06-03	88.254 mi
Registration #11	2021-06-03	97.569 mi
Registration #12	2022-06-03	106.884 mi
Registration #13	2023-04-28	116.199 mi
Registration #14	2023-04-28	116.199 mi
Registration #15	2023-04-28	116.199 mi
Registration #16	2023-04-28	116.199 mi
Registration #17	2023-04-28	116.199 mi
Registration #18	2023-04-28	116.199 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	79%
Pedestrian	37%
Safety systems	97%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2118 mm
Height	1638 mm
Length	4530 mm
Wheel base	2727 mm
Kerb weight	1699 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	JBER3007432