





### General information

Make	AUDI
Model	A3 TFSI SPORT
Colour	Grey
Year of manufacture	2016
Top speed	136 mph
0 - 100 km/h	8.1 seconds
0 - 60 mph	8.1 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	110 kW / 150 HP / 148 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.395 cc
Cylinders	4
Fuel type	Petrol
Consumption city	48.7 mpg
Consumption extra urban	68.9 mpg
Consumption combined	60.1 mpg
CO2 emission	108 g/km
CO2 label	В







# Internet history

Entry	1

Date


2021-09-17

Pictures

Listing price

View report

4



source: autotrader.co.uk



### MOT history

MOT expiry date	2024-11-18
MOT pass rate	56 %
MOT passed	5
Failed MOT tests	4
Total advice items	21
Total items failed	0

MOT #9	2023-11-15 10:06
MOT test number	726181413991
Result	✓ Passed
Next expiry date	2024-11-18

MOT #8	2022-11-19 13:45
MOT test number	637244866675
Result	🗸 Passed
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	)

MOT #7	2022-11-09 15:2	B
MOT test	number 38692751244	L
Result	× Failed	k
<b>MAJOR</b> (5.3.4 (a)	Nearside Front Suspension arm pin or bush excessively worn lower arm rear bush protruding arm (i))	
Advice	Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
MAJOR	Offside Front Suspension arm pin or bush excessively worn lower arm rear bush protruding arm	

(5.3.4 (a) (i))

MOT #6	2021-11-15 15:56
MOT test number	415026797335
Result	✓ Passed





MOT #5		2021-09-30 18:11
MOT test	number	595972995484
Result		🗙 Failed
<b>MAJOR</b> (4.8.1 (a) (	Nearside Rear Rear reflector defective or damaged by more than 50% of the (ii))	e reflecting surface
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))		
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (	(a) (ii))
Advice	Nearside Rear tail light cluster is damaged	

MOT #4	2021-03-04 12:57	
MOT test	number 717710371574	
Result	✓ Passed	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	dvice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

MOT #3		2021-03-04 11:53
MOT test numbe	er	151384353296
Result		🗙 Failed
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
DANGEROUS	Nearside Front Tyre tread depth below requirements of 1.6mm (	5.2.3 (e))
Advice Nears	side Rear Brake disc worn, pitted or scored, but not seriously weak	xened (1.1.14 (a) (ii))
DANGEROUS	Offside Front Tyre tread depth below requirements of 1.6mm (5.	2.3 (e))

MOT #2	2020-02-27 15:03
MOT test number	133952669280
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	





MOT #1		2020-02-27 11:42
MOT test numbe	er	195396212381
Result		🗙 Failed
DANGEROUS	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
DANGEROUS	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))		
DANGEROUS	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	



Tax & MOT check

✓ Taxed Tax due: 1 November 2024	✓ MOT Expires: 18 November 2024
Tax status	Valid until 1 November
Days left	187
MOT expiry date	18 November 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





#### Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

#### Extra AUDI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
***********	
*******	
*******	
***********	
*******	
	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Rinda since	





#### Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >





# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-09-01
Last registration	2023-11-15
Complete history	See info



Registration #1	2016-09-01	14 mi
Registration #2	2020-02-27	35.968 mi
Registration #3	2020-02-27	35.975 mi
Registration #4	2021-03-04	48.402 mi
Registration #5	2021-03-04	48.409 mi
Registration #6		11.777 est
Registration #7		11.117 esi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.117 esi

More info  $\rightarrow$ 





### Car features

S0225	Air conditioning
\$0295	
50482	
50501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	95%
Children	87%
Pedestrian	74%
Safety systems	86%
Overall rating	88%
Video	see crash video



Dimensions & weight	
Width	1777 mm
Height	1421 mm
Length	4237 mm
Wheel base	2601 mm
Kerb weight	1195 kg
Max. allowed weight	1760 kg
Additional information	
Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles	2
Engine number	CZEA254132