



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX URBAN FOX
Colour	Silver
Year of manufacture	2007
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E







Internet history

Entry 1

Date	2021-02-06
Pictures	8
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2024-10-05
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	9
Total items failed	10

MOT #18	2023-10-06 16:24
MOT test number	921936738613
Result	✓ Passed
Next expiry date	2024-10-05

MOT #17	2023-09-30 11:39
MOT test number	733716711242
Result	✗ Failed
Fail	Brake hydraulic reservoir fluid level significantly below minimum level (1.1.10 (d) (ii))
Minor	Brake fluid warning lamp illuminated (1.1.10 (f))
Fail	Nearside Front Direction indicator incorrect colour white (4.4.3 (a))
Fail	Brake performance unable to be tested due to condition of braking system/fluid leak (1.2.1 (g))
Advice	Front bonnet secondary/safety catch seized-unseized and lubricated
Fail	Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))

MOT #16	2022-10-03 15:50
MOT test number	256178412192
Result	✓ Passed

**MOT #15** 2022-10-03 09:29**MOT test number** 853505663726**Result** ✗ Failed**Fail** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #14** 2021-05-24 13:14**MOT test number** 178278769326**Result** ✓ Passed**MOT #13** 2021-05-21 13:56**MOT test number** 307198397041**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #12** 2020-09-07 11:56**MOT test number** 556952247951**Result** ✓ Passed**MOT #11** 2019-09-04 09:43**MOT test number** 966916348059**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



<b>MOT #10</b>	2018-08-28 08:58
----------------	------------------

<b>MOT test number</b>	748231542064
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
---------------	---

<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
---------------	--

<b>MOT #9</b>	2017-09-01 08:38
---------------	------------------

<b>MOT test number</b>	844894869116
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #8</b>	2016-09-01 10:07
---------------	------------------

<b>MOT test number</b>	765358136277
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #7</b>	2015-09-11 08:49
---------------	------------------

<b>MOT test number</b>	860410270431
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #6</b>	2014-09-10 08:57
---------------	------------------

<b>MOT test number</b>	126393454227
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #5</b>	2013-08-30 10:03
---------------	------------------

<b>MOT test number</b>	888392543299
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2012-08-23 12:00
---------------	------------------

<b>MOT test number</b>	735966832298
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

**MOT #3** 2011-08-26 12:19**MOT test number** 687548331287**Result** ✓ Passed

**Advice** Nearside Radius arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #2** 2011-08-26 12:19**MOT test number** 729028731256**Result** ✗ Failed

**Advice** Nearside Radius arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

**Pass with rectification** Offside Radius arm rubber mounting deteriorated resulting in excessive movement (2.4.G.2)

**MOT #1** 2010-09-03 11:29**MOT test number** 174516840253**Result** ✓ Passed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
5 October 2024

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	337
<b>MOT expiry date</b>	5 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 YX57WVS
Plate since	2019-03-29
Current registration	 YX57WVS
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2007-09-20
Last registration	2023-10-06
Complete history	<a href="#">See info</a>



Registration #1	2007-09-20	12 mi
Registration #2	2010-09-03	20.812 mi
Registration #3	2011-08-26	26.975 mi
Registration #4	2012-08-23	33.295 mi
Registration #5	2013-08-30	38.345 mi
Registration #6	2014-09-10	44.620 mi
Registration #7	2015-09-11	50.740 mi
Registration #8	2016-09-01	56.765 mi
Registration #9	2017-09-01	62.790 mi
Registration #10	2018-09-01	68.815 mi
Registration #11	2019-09-01	74.840 mi
Registration #12	2020-09-01	80.865 mi
Registration #13	2021-09-01	86.890 mi
Registration #14	2022-09-01	92.915 mi
Registration #15	2023-10-06	98.940 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BMD 375475