



report date: 2024-03-28

General information

Make	KIA
Model	SEDONA GS
Colour	Silver
Year of manufacture	2007
Top speed	120 mph
0 - 60 mph	15.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	182 BHP
Max. torque	343 Nm at 4.500 rpm
Engine capacity	2.902 cc
Cylinders	4
Fuel type	Diesel
Consumption city	23.0 mpg
Consumption extra urban	40.4 mpg
Consumption combined	31.4 mpg
CO2 emission	237 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-07-09
Pictures	33
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)



## MOT history

MOT expiry date	2024-06-12
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	43
Total items failed	15

**MOT #21** 2023-06-12 11:49**MOT test number** 117183264470**Result** Passed**Next expiry date** 2024-06-12

**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**MOT #20** 2022-06-13 10:59**MOT test number** 205851881734**Result** Passed

**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**MOT #19** 2021-07-14 10:15**MOT test number** 198482613613**Result** Passed

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #18** 2021-07-14 07:45**MOT test number** 492076163488**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Steering locking device missing (2.1.3 (d))**MOT #17** 2020-08-25 10:21**MOT test number** 873399282441**Result** ✓ Passed**MOT #16** 2020-08-25 08:21**MOT test number** 101756084673**Result** ✗ Failed**Fail** Nearside Rear Service brake excessively binding WONT TURN AT ALL WHEEL BEARING TO CHECKED ON RETEST (1.2.1 (f))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #15** 2019-08-29 12:01**MOT test number** 651986279546**Result** ✓ Passed**MOT #14** 2018-08-09 14:25**MOT test number** 848225088515**Result** ✓ Passed

**MOT #13** 2018-08-09 10:44**MOT test number** 683698580436**Result** ✗ Failed**Minor** Offside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a))**Fail** Offside Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Rear tyres cracking**Fail** Offside Front Position lamp missing (4.2.1 (a))**MOT #12** 2017-08-22 09:22**MOT test number** 942418123268**Result** ✓ Passed**MOT #11** 2017-08-22 09:22**MOT test number** 293294714148**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Pass with rectification** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #10** 2016-08-31 07:57**MOT test number** 311598410246**Result** ✓ Passed

**MOT #9** 2016-02-09 09:02**MOT test number** 437791133651**Result** ✓ Passed

- Advice** Front discs slightly worn
- Advice** Coil spring corroded both rear (2.4.C.1b)
- Advice** Auto gearbox / cooler area oil leak
- Advice** Both rear tyres wearing slightly on inner edges

**MOT #8** 2016-02-06 09:54**MOT test number** 528206704365**Result** ✗ Failed

- Advice** Auto gearbox / cooler area oil leak
- Advice** Coil spring corroded both rear (2.4.C.1b)
- Advice** Both rear tyres wearing slightly on inner edges
- Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)
- Advice** Front discs slightly worn

**MOT #7** 2015-02-06 11:09**MOT test number** 595517435046**Result** ✓ Passed

- Notice** Under-trays fitted obscuring some underside components

**MOT #6**

2014-08-22 10:33

**MOT test number**

398964834288

**Result**

✓ Passed

- Notice** Both front disc inner faces slightly worn
- Notice** O/s/r tyre wearing slightly uneven
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Vehicle's internal headlight adjuster altered to recheck lights
- Notice** Very slight movement in n/s inner rack joint
- Notice** O/s/r brake sticking slightly
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Under-trays fitted obscuring some underside components

**MOT #5**

2013-08-20 10:22

**MOT test number**

198822633288

**Result**

✓ Passed

- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #4** 2013-08-19 17:01**MOT test number** 105841033281**Result** ✗ Failed

- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Front discs slightly worn and corroded
- Notice** Both front tyres worn on inner edge
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Notice** Rack damp
- Notice** Rear a/c pipes leaking

**MOT #3** 2012-08-06 17:07**MOT test number** 186819712229**Result** ✓ Passed

- Notice** Offside and nearside wiperblades smear slightly
- Notice** Under-trays fitted obscuring some underside components
- Notice** Child seat fitted not allowing full inspection of adult belt
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Front Brake pad(s) wearing thin (3.5.1g)



**MOT #2** 2012-08-06 10:47**MOT test number** 628739312274**Result** ✗ Failed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Offside and nearside wiperblades smear slightly
- Fail** Offside Stop lamp not working (1.2.1b)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Power steering fluid level low, but not below minimum (2.3.1)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Fail** Offside Rear Passenger's seat insecure (6.2.A.1)
- Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #1** 2011-08-15 13:45**MOT test number** 108657121252**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
12 June 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	12 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	L
<b>Single payment (12 months)</b>	£ 675,00,-
<b>Single six month payment</b>	£ 371,25,-
<b>Total payable by 12 monthly instalments</b>	£ 708,75,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	<b>LB57GPU</b>
Plate since	2019-03-28
Current registration	<b>LB57GPU</b>
Plate since	2019-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-12-12
Last registration	2023-06-12
Complete history	<a href="#">See info</a>



Registration #1	2007-12-12	25 mi
Registration #2	2011-08-15	34.491 mi
Registration #3	2012-08-06	40.672 mi
Registration #4	2012-08-06	40.673 mi
Registration #5	2013-08-19	46.298 mi
Registration #6	2013-08-20	46.298 mi
Registration #7	2014-08-22	56.296 mi
Registration #8	2015-02-06	58.466 mi
Registration #9	2016-02-06	64.602 mi
Registration #10	2016-02-09	64.602 mi
Registration #11	2016-08-31	68.806 mi
Registration #12	2017-08-22	79.559 mi
Registration #13	2018-08-22	89.559 mi
Registration #14	2019-08-22	99.559 mi
Registration #15	2020-08-22	109.559 mi
Registration #16	2021-08-22	119.559 mi
Registration #17	2022-08-22	129.559 mi
Registration #18	2023-08-22	139.559 mi
Registration #19	2024-08-22	149.559 mi
Registration #20	2025-08-22	159.559 mi
Registration #21	2026-08-22	169.559 mi
Registration #22	2027-08-22	179.559 mi
Registration #23	2028-08-22	189.559 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1985 mm
Height	1815 mm
Length	4810 mm
Wheel base	2890 mm
Kerb weight	2189 kg
Max. allowed weight	2920 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7



<b>Number of axles</b>	2
<b>Engine number</b>	J3763968