



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 LX
Colour	Silver
Year of manufacture	-
Top speed	106 mph
0 - 60 mph	13.2 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	75 BHP
Max. torque	111 Nm at 2.600 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.2 mpg
Consumption extra urban	50.4 mpg
Consumption combined	39.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-10
Pictures	10
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #24	2022-11-02 12:19
MOT test number	222556225641
Result	✓ Passed
Next expiry date	2023-11-01
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Rear Seat belt slightly damaged (7.1.2 (b) (i))
Advice	Front Side repeater slightly discoloured Both sides (4.4.3 (a))

MOT #23	2022-11-01 13:08
MOT test number	820140564646
Result	✗ Failed
Fail	Nearside Front Upper Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Nearside Rear Seat belt slightly damaged (7.1.2 (b) (i))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Fail	Offside Rear Brake load sensing valve seized but ABS functioning (1.1.17 (c) (i))
Advice	Front Side repeater slightly discoloured Both sides (4.4.3 (a))

MOT #22	2021-08-21 14:54
MOT test number	723239055211
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Underbody corrosion
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Minor	Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #21** 2020-08-12 12:40**MOT test number** 275505777412**Result** ✓ Passed**Advice** Nearside Front Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Central Front Oil leak, but not excessive (8.4.1 (a) (i))**MOT #20** 2020-08-11 08:53**MOT test number** 638529792409**Result** ✗ Failed**Advice** Nearside Front Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Nearside Front Lower Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Central Front Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Rear Brake load sensing valve seized and ABS not fitted or inoperative (1.1.17 (c) (ii))**MOT #19** 2019-07-31 13:14**MOT test number** 472071562578**Result** ✓ Passed**MOT #18** 2019-07-31 10:36**MOT test number** 679100743324**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))**MOT #17** 2018-07-24 15:21**MOT test number** 674781416921**Result** ✓ Passed

**MOT #16** 2018-07-24 10:34**MOT test number** 798255577597**Result** ✗ Failed**Fail** Emissions not tested (8.2.1.2 (d))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Central Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))**MOT #15** 2017-07-19 10:58**MOT test number** 678598888032**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #14** 2017-07-19 10:58**MOT test number** 333557476902**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #13** 2016-07-21 11:14**MOT test number** 165362046980**Result** ✓ Passed**MOT #12** 2016-07-20 13:28**MOT test number** 138565410256**Result** ✗ Failed**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)



MOT #11	2015-07-16 11:54
----------------	------------------

MOT test number	377177195100
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #10	2014-07-16 13:35
----------------	------------------

MOT test number	747907194187
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #9	2013-07-24 15:16
---------------	------------------

MOT test number	545595303223
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #8	2012-07-10 14:51
---------------	------------------

MOT test number	445612792181
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2011-07-19 13:47
---------------	------------------

MOT test number	267690301262
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	--

Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	---

MOT #6	2010-07-27 10:26
---------------	------------------

MOT test number	960598000263
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2009-07-15 14:18
---------------	------------------

MOT test number	273996599160
------------------------	--------------

Result	✓ Passed
---------------	----------



MOT #4	2008-07-23 11:51
MOT test number	190585608273
Result	✓ Passed
MOT #3	2008-07-22 15:43
MOT test number	321514308494
Result	✗ Failed
Fail	Rear Exhaust has a major leak of exhaust gases (7.1.2)
MOT #2	2007-07-03 11:55
MOT test number	621004487138
Result	✓ Passed
MOT #1	2006-07-26 14:31
MOT test number	670707406207
Result	✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2003-08-01
Last registration	2022-11-02
Complete history	See info



Registration #1	2003-08-01	9 mi
Registration #2	2006-07-26	4.626 mi
Registration #3	2007-07-03	7.396 mi
Registration #4	2008-07-22	10.989 mi
Registration #5	2008-07-23	10.989 mi
Registration #6	2009-07-15	13.593 mi
Registration #7	2010-07-27	17.020 mi
Registration #8	2011-07-19	20.532 mi
Registration #9	2012-07-10	24.235 mi
Registration #10	2013-07-24	32.230 mi
Registration #11	2014-07-16	37.321 mi
Registration #12	2015-07-16	41.879 mi
Registration #13	2016-07-20	46.734 mi
Registration #14	2016-07-20	46.734 mi
Registration #15	2016-07-20	46.734 mi
Registration #16	2016-07-20	46.734 mi
Registration #17	2016-07-20	46.734 mi
Registration #18	2016-07-20	46.734 mi
Registration #19	2016-07-20	46.734 mi
Registration #20	2016-07-20	46.734 mi
Registration #21	2016-07-20	46.734 mi
Registration #22	2016-07-20	46.734 mi
Registration #23	2016-07-20	46.734 mi
Registration #24	2016-07-20	46.734 mi
Registration #25	2016-07-20	46.734 mi
Registration #26	2016-07-20	46.734 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	950 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Engine number	FSJ24469875