



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 R-DESIGN
Colour	Black
Year of manufacture	2013
Top speed	130 mph
0 - 60 mph	8.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.2 mpg
CO2 emission	177 g/km
CO2 label	I



Internet history

Entry 2

Date	2022-07-20
Pictures	16
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2022-02-27
Pictures	16
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-12-21
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	17
Total items failed	0

MOT #11 2023-12-22 11:02

MOT test number 761317881583

Result ✓ Passed

Next expiry date 2024-12-21

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bushes (both sides) (5.3.4 (a) (i))**Advice** Brake disc worn, pitted or scored, but not seriously weakened all 4 (due to lack of use) (1.1.14 (a) (ii))

MOT #10 2023-11-01 15:25

MOT test number 533147768170

Result ✗ Failed**MAJOR** Exhaust system insecure tail pipe (6.1.2 (a))**Advice** Rear discs corroded**MAJOR** Central Exhaust has a major leak of exhaust gases silencer (6.1.2 (a))**Advice** Oil leak engine**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #9** 2022-08-18 13:01**MOT test number** 367387257545**Result** ✓ Passed

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement os/ns w/bones (5.3.4 (a) (i))

MOT #8 2022-08-18 09:52**MOT test number** 867896668594**Result** ✗ Failed

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement os/ns w/bones (5.3.4 (a) (i))

MAJOR Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MAJOR Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #7 2021-11-29 08:59**MOT test number** 983117608234**Result** ✓ Passed**MOT #6** 2020-10-29 14:20**MOT test number** 607674907149**Result** ✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #5 2019-10-17 14:26**MOT test number** 835661005246**Result** ✓ Passed**MOT #4** 2019-05-22 09:40**MOT test number** 547611828745**Result** ✓ Passed



MOT #3	2018-05-23 08:25
MOT test number	382412330279
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2	2017-02-08 16:32
MOT test number	481604977282
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2016-03-02 12:09
MOT test number	182344449168
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
21 December 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	21 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YK13OCC
Plate since	2019-09-28
Current registration	YK13OCC
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-03-02
Last registration	2023-12-22
Complete history	See info



Registration #1	2013-03-02	26 mi
Registration #2	2016-03-02	18.235 mi
Registration #3	2017-02-08	24.953 mi
Registration #4	2018-05-23	35.800 mi
Registration #5	2019-05-22	44.373 mi
Registration #6	2019-10-17	46.404 mi
Registration #7	2020-10-29	59.954 mi
Registration #8	2020-10-29	59.954 mi
Registration #9	2020-10-29	59.954 mi
Registration #10	2020-10-29	59.954 mi
Registration #11	2020-10-29	59.954 mi
Registration #12	2020-10-29	59.954 mi
Registration #13	2020-10-29	59.954 mi
Registration #14	2020-10-29	59.954 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1329 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1120703