



General information

Make	FORD
Model	FUSION STYLE CLIMATE
Colour	Green
Year of manufacture	2008
Top speed	102 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	154 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-09-16
Pictures	21
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-08-28
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	53
Total items failed	8

MOT #19	2023-08-29 12:44
MOT test number	842186907195
Result	✓ Passed
Next expiry date	2024-08-28
Minor	Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #18	2022-08-17 11:50
MOT test number	222455447755
Result	✓ Passed
Minor	Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Front Lower Suspension arm corroded but not seriously weakened Both Sides (5.3.3 (b) (i))

**MOT #17**

2021-09-10 07:24

MOT test number

946438881577

Result

✓ Passed

- Advice** Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MOT #16

2020-09-21 09:47

MOT test number

263772821538

Result

✓ Passed

- Advice** Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front wiper blade split
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Power steering pipe corroded
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front wing mirror damaged
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #15**

2019-09-06 15:30

MOT test number

204136226893

Result

✓ Passed

- Advice** Offside Front Tyre slightly damaged/cracking or perishing cracking/perished 195/60R15 (5.2.3 (d) (ii))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced General (6.1.1 (c) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing cracking/perished 195/60R15 (5.2.3 (d) (ii))
- Advice** Power steering pipe/hose slightly corroded pressure and return pipes (2.1.5 (g) (i))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge low on tread approx 3.0mm 195/60R15 (5.2.3 (e))
- Minor** Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))

MOT #14

2019-09-06 08:50

MOT test number

423382546739

Result

✗ Failed

- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge low on tread approx 3.0mm 195/60R15 (5.2.3 (e))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing cracking/perished 195/60R15 (5.2.3 (d) (ii))
- Fail** Offside Front Brake hose ferrule excessively corroded (1.1.12 (f) (i))
- Minor** Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced General (6.1.1 (c) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing cracking/perished 195/60R15 (5.2.3 (d) (ii))
- Advice** Power steering pipe/hose slightly corroded pressure and return pipes (2.1.5 (g) (i))

**MOT #13**

2018-09-14 16:13

MOT test number

270392667569

Result

✓ Passed

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**MOT #12**

2018-09-13 10:35

MOT test number

609523877184

Result

✗ Failed

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Fail** Offside Rear Brake pipe excessively corroded from flexi (1.1.11 (c))**Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Fail** Offside Rear Brake pipe excessively corroded to flexi (1.1.11 (c))**MOT #11**

2017-09-13 08:37

MOT test number

668290109261

Result

✓ Passed

Advice Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Nearside Front tyre outer side wall perished.**Advice** Nearside Front Brake pipe slightly corroded to flexible pipe. (3.6.B.2c)

**MOT #10** 2016-09-12 10:40**MOT test number** 473670695511**Result** ✓ Passed**MOT #9** 2016-09-12 10:40**MOT test number** 289474444435**Result** ✗ Failed**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**MOT #8** 2015-09-21 08:54**MOT test number** 336474339646**Result** ✓ Passed**MOT #7** 2015-09-21 08:54**MOT test number** 173748666055**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**MOT #6** 2014-09-04 16:08**MOT test number** 598957744217**Result** ✓ Passed**MOT #5** 2014-09-04 12:52**MOT test number** 516367744254**Result** ✗ Failed**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Notice** Nearside rear tyre perished

**MOT #4** 2013-09-07 09:08**MOT test number** 575040953240**Result** ✓ Passed**Notice** Rear tyres slightly cracked/perished**MOT #3** 2012-06-28 16:01**MOT test number** 756400982120**Result** ✓ Passed**MOT #2** 2011-06-15 10:19**MOT test number** 688416161146**Result** ✓ Passed**Notice** Front wipers smear the windscreen slightly**Notice** All tyres cracking on edges, no cords visible**MOT #1** 2011-06-15 10:19**MOT test number** 569696561124**Result** ✗ Failed**Notice** Front wipers smear the windscreen slightly**Notice** All tyres cracking on edges, no cords visible**Pass with rectification** Nearside Front Headlamp aim too low and too far to the left. (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
28 August 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	28 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-07-09
Last registration	2023-08-29
Complete history	See info



Registration #1	2008-07-09	12 mi
Registration #2	2011-06-15	7.291 mi
Registration #3	2012-06-28	13.326 mi
Registration #4	2013-09-07	19.480 mi
Registration #5	2014-09-04	23.287 mi
Registration #6	2014-09-04	23.287 mi
Registration #7	2015-09-21	27.063 mi
Registration #8	2015-09-21	27.063 mi
Registration #9	2016-09-12	29.844 mi
Registration #10	2016-09-12	29.844 mi
Registration #11	2016-09-12	29.844 mi
Registration #12	2016-09-12	29.844 mi
Registration #13	2016-09-12	29.844 mi
Registration #14	2016-09-12	29.844 mi
Registration #15	2016-09-12	29.844 mi
Registration #16	2016-09-12	29.844 mi
Registration #17	2016-09-12	29.844 mi
Registration #18	2016-09-12	29.844 mi
Registration #19	2016-09-12	29.844 mi
Registration #20	2016-09-12	29.844 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1199 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	8A48618