



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT TDI SE
Colour	Blue
Year of manufacture	2006
Top speed	114 mph
0 - 60 mph	12.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	157 g/km
CO2 label	G





MOT history

MOT expiry date	2021-01-01
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	24
Total items failed	1

MOT #12 2019-07-02 16:38

MOT test number 971602208542

Result ✓ Passed

Next expiry date 2021-01-01

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #11 2018-06-01 13:57

MOT test number 941408481012

Result ✓ Passed

Advice Front Headlamp has a product on the lens but not seriously reducing light output both o/s and n/s (4.1.4 (b))

Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both o/s and n/s (1.1.14 (a) (ii))

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement both o/s and n/s (5.3.4 (a) (i))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Minor Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #10** 2017-06-09 07:48**MOT test number** 525458155448**Result** ✓ Passed

- Advice** Nearside Front tyre down to 2.1mm
- Advice** Rear tyres worn out on inner edges,advise renewing asap
- Advice** Lip on front discs ,condition of inner pads unknown due to limited vision

MOT #9 2016-06-09 12:49**MOT test number** 374249107096**Result** ✓ Passed

- Advice** Slight perishing of nearside front cv boot

MOT #8 2015-06-11 10:37**MOT test number** 247962465492**Result** ✓ Passed

- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #7 2014-05-21 12:16**MOT test number** 227961644162**Result** ✓ Passed**MOT #6** 2013-05-23 14:45**MOT test number** 756643643156**Result** ✓ Passed

- Notice** Child seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2012-06-13 12:50**MOT test number** 238225062433**Result** ✓ Passed

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2012-06-13 10:08**MOT test number** 739565662188**Result** ✗ Failed

Fail Nearside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2011-05-25 15:13**MOT test number** 169705341141**Result** ✓ Passed**MOT #2** 2010-05-26 16:37**MOT test number** 101096940129**Result** ✓ Passed

Notice N/S/R Tyre worn on inner edge

Notice Cut in N/S/R Tyre

Notice O/S/R Tyre worn on inner edge



MOT #1	2009-02-25 16:06
MOT test number	311366859084
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
17 December 2020

✕
MOT

Expired:
1 January 2021

Tax status	Expired at 17 December 2020
Days left	1229 days too late
MOT expiry date	1 January 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-28
Current registration	 XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2006-03-01
Last registration	2019-07-02
Complete history	See info



Registration #1	2006-03-01	14 mi
Registration #2	2009-02-25	34.269 mi
Registration #3	2010-05-26	45.687 mi
Registration #4	2011-05-25	57.418 mi
Registration #5	2012-06-13	67.229 mi
Registration #6	2012-06-13	67.229 mi
Registration #7	2013-05-23	76.481 mi
Registration #8	2019-07-02	76.481 mi
Registration #9	2019-07-02	76.481 mi
Registration #10	2019-07-02	76.481 mi
Registration #11	2019-07-02	76.481 mi
Registration #12	2019-07-02	76.481 mi
Registration #13	2019-07-02	76.481 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1517 mm
Length	4774 mm
Wheel base	2709 mm
Kerb weight	1653 kg
Max. allowed weight	2100 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BXE 038893