



Mercedes-Benz




report date: 2024-03-29

General information

Make	MERCEDES
Model	CLK CLK200K SPORT
Colour	Silver
Year of manufacture	2008
Top speed	147 mph
0 - 60 mph	9.1 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	181 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	32.5 mpg
CO2 emission	207 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-07-29
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-09
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	22
Total items failed	6

MOT #18	2024-04-09 15:45
MOT test number	266985627957
Result	✓ Passed
Next expiry date	2025-04-09
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))

MOT #17	2024-04-08 09:38
MOT test number	131870764038
Result	✗ Failed
Advice	Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords inner wall (5.2.3 (d) (i))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #16** 2023-04-05 10:18**MOT test number** 241316512564**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #15** 2023-04-05 10:18**MOT test number** 108141968477**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #14** 2022-04-06 09:37**MOT test number** 525754638573**Result** ✓ Passed**MOT #13** 2021-03-17 17:25**MOT test number** 397425281188**Result** ✓ Passed**MOT #12** 2020-03-12 14:56**MOT test number** 503376307600**Result** ✓ Passed**MOT #11** 2019-04-06 07:45**MOT test number** 707599359239**Result** ✓ Passed**Advice** Offside front tyre worn slightly unevenly on inner tread

**MOT #10** 2018-04-07 10:23**MOT test number** 420015978956**Result** ✓ Passed**MOT #9** 2017-04-10 09:29**MOT test number** 376846331036**Result** ✓ Passed**MOT #8** 2016-03-08 09:45**MOT test number** 938258359310**Result** ✓ Passed**Advice** Nearside Front slight damage to the tyre side wall**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #7** 2016-03-03 11:43**MOT test number** 976726822724**Result** ✗ Failed**Advice** Tyre pressure monitoring system warning lamp does not illuminate (4.1.D.4)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Unable to fully inspect front brake pads**Fail** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Nearside Front slight damage to the tyre side wall**MOT #6** 2015-02-05 14:45**MOT test number** 958916535010**Result** ✓ Passed**Notice** Nearside rear tyre worn close to wear marker

**MOT #5** 2014-02-25 14:46**MOT test number** 679926254042**Result** ✓ Passed**Notice** Nearside front tyre has a small split in the inner sidewall.**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #4** 2013-02-19 15:07**MOT test number** 206790253011**Result** ✓ Passed**MOT #3** 2013-02-19 13:19**MOT test number** 607370753095**Result** ✗ Failed**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #2** 2012-02-27 16:17**MOT test number** 108248452486**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #1** 2011-03-01 15:59**MOT test number** 906390161045**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
9 April 2025

Tax status	Valid until 1 August
Days left	94
MOT expiry date	9 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 FL08FZV
Plate since	2019-06-29
Current registration	 FL08FZV
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-03-26
Last registration	2024-04-09
Complete history	See info



Registration #1	2008-03-26	25 mi
Registration #2	2011-03-01	22.173 mi
Registration #3	2012-02-27	30.073 mi
Registration #4	2013-02-19	37.795 mi
Registration #5	2013-02-19	37.795 mi
Registration #6	2014-02-25	44.396 mi
Registration #7	2015-02-05	50.904 mi
Registration #8	2016-03-03	64.086 mi
Registration #9	2016-03-08	64.172 mi
Registration #10	2017-04-10	75.397 mi
Registration #11	2018-05-01	85.557 mi
Registration #12	2019-05-01	95.717 mi
Registration #13	2020-05-01	105.877 mi
Registration #14	2021-05-01	116.037 mi
Registration #15	2022-05-01	126.197 mi
Registration #16	2023-05-01	136.357 mi
Registration #17	2024-05-01	146.517 mi
Registration #18	2025-05-01	156.677 mi
Registration #19	2026-05-01	166.837 mi
Registration #20	2027-05-01	176.997 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1540 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27195531026547