





report date: 2024-03-29

General information

Make	VAUXHALL
Model	ASTRA EMERGENCY SERVICES CDTI
Colour	Silver
Year of manufacture	2018
Top speed	121 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	108 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	85.6 mpg
Consumption combined	78.5 mpg
CO2 emission	96 g/km
CO2 label	A



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 2

Date 2022-01-29

Pictures 32

Listing price <u>View report</u>









source: yesauto.com

Entry 1


Date 2022-01-22

Pictures 5

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2024-10-04
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	9
Total items failed	3

MOT #4	2023-10-03 09:31	
MOT test number	211861178511	
Result	✓ Passed	
Next expiry date	2024-10-04	
Advice Offside Rear Tyre slightly damaged/cracking or perishing plus nail in to	read (5.2.3 (d) (ii))	
Minor Central Windscreen damaged but not adversely affecting driver's view chip in screen (3.2 (a) (i))		
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt		
Advice Nearside Front Outer Tyre has a cut but not deep enough to reach the (d) (i))	e ply or cords sidewall (5.2.3	

MOT #3	2022-10-05 08:46
MOT test number	225548377760
Result	✓ Passed

MOT #2	2022-10-04 13:34
MOT test number	833706609930
Result	≭ Failed
Company Time has a subject to a	

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #1 2021-09-06 15:19

MOT test number 340444646483

Result ✓ Passed **Advice** No emissions detected on free acceleration test Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



MOT

Expires:
4 October 2024

Tax expired: 19 February 2024

Tax status	Expired at 19 February 2024
Days left	71 days too late
MOT expiry date	4 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
First licence fee (12 months)	£ 165,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category

Damage 2

Type

Date

Category

Type



Extra VAUXHALL salvage check



CarCheck.co.uk

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

More info >

Owner history

o micr mistory	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloahere.	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	NK SIN
Plate since	

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-09-30
Last registration	2023-10-03
Complete history	See info



Registration #1	2018-09-30	7 mi
Registration #2	2021-09-06	42.013 mi
Registration #3		11.777 es
Registration #4		0.00 44
Registration #5		11.777 mi
Registration #6		11.777 es
Registration #7		11,177 mi

More info >

CarCheck.co.uk page 10/11





report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	86%
Children	84%
Pedestrian	83%
Safety systems	75%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2042 mm
Height	1510 mm
Length	4702 mm
Max. allowed weight	1930 kg

Additional information

Number of seats	5
Number of axles	2
Engine number	A3173288JCBX0417LWQ

CarCheck.co.uk page 11/11