



report date: 2024-03-28

General information

Make	MINI
Model	COOPER S
Colour	Silver
Year of manufacture	2018
Top speed	146 mph
0 - 60 mph	6.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	189 BHP
Max. torque	280 Nm at 1.250 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	136 g/km
CO2 label	E






Internet history

Entry 3


Date	2022-02-20
Pictures	11
Listing price	View report



source: [autotrader.co.uk](#)

Entry 2

Date	2021-09-12
Pictures	35
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-08-07
Pictures	14
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-01-07
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	12
Total items failed	0

MOT #5	2024-01-08 13:42
MOT test number	503795301351
Result	✓ Passed
Next expiry date	2025-01-07

MOT #4	2022-11-15 10:04
MOT test number	250515015444
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3	2021-07-16 09:09
MOT test number	494673186242
Result	✓ Passed

MOT #2	2021-07-15 13:06
MOT test number	460851429364
Result	✗ Failed
DANGEROUS	Offside Rear Tyre has a lump, caused by separation or partial failure of its structure 205.40.18 86W. Pirelli. RunFlat. (5.2.3 (d) (ii))



MOT #1	2021-06-03 08:22
MOT test number	145518610588
Result	✗ Failed
MAJOR	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
MAJOR	Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b))
Advice	Rear Passenger seat(s) missing at time of test all.
MAJOR	Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords outer sidewall. 225.4.18 88Y. (5.2.3 (d) (i))
MAJOR	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
MAJOR	Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
Advice	Offside Front Tyre worn close to legal limit/worn on edge 225.4.18 88Y. (5.2.3 (e))
MAJOR	Exhaust has a major leak of exhaust gases (6.1.2 (a))



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
7 January 2025

Tax status	Valid until 1 October
Days left	156
MOT expiry date	7 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-06-28
Last registration	2024-01-08
Complete history	See info



Registration #1	2018-06-28	6 mi
Registration #2	2021-06-03	30.490 mi
Registration #3	2021-07-15	32.058 mi
Registration #4	2021-07-16	32.079 mi
Registration #5	2022-06-28	32.277 mi
Registration #6	2022-06-28	32.277 mi
Registration #7	2022-06-28	32.277 mi
Registration #8	2022-06-28	32.277 mi
Registration #9	2024-01-08	32.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	79%
Children	73%
Pedestrian	66%
Safety systems	56%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	1727 mm
Height	1414 mm
Length	3850 mm
Wheel base	2495 mm
Kerb weight	1235 kg
Max. allowed weight	1640 kg

Additional information

Fuel tank capacity	44 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	4
-----------------	---

Number of axles	2
Engine number	F278H691