





### General information

| Make                | HYUNDAI               |
|---------------------|-----------------------|
| Model               | I40 CRDI S BLUE DRIVE |
| Colour              | Black                 |
| Year of manufacture | 2015                  |
| Top speed           | 119 mph               |
| 0 - 60 mph          | 12.4 seconds          |
| Gearbox             | 6 speed Manual        |

## Engine & fuel consumption

| Power                   | 113 BHP             |
|-------------------------|---------------------|
| Max. torque             | 280 Nm at 2.500 rpm |
| Engine capacity         | 1.685 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 57.6 mpg            |
| Consumption extra urban | 74.3 mpg            |
| Consumption combined    | 67.3 mpg            |
| CO2 emission            | 110 g/km            |
| CO2 label               | В                   |







| Internet history |             |
|------------------|-------------|
| Entry 1          |             |
| Date             | 2021-07-10  |
| Pictures         | 0           |
| Listing price    | View report |

source: cargurus.co.uk



## MOT history

| MOT expiry date    | 2024-07-07 |
|--------------------|------------|
| MOT pass rate      | 75 %       |
| MOT passed         | 6          |
| Failed MOT tests   | 2          |
| Total advice items | 0          |
| Total items failed | 2          |

| MOT #8           | 2023-06-29 11:30 |
|------------------|------------------|
| MOT test number  | 865084790670     |
| Result           | ✓ Passed         |
| Next expiry date | 2024-07-07       |

| MOT #7          | 2022-07-06 09:40 |
|-----------------|------------------|
| MOT test number | 856486109827     |
| Result          | ✓ Passed         |

| МОТ #6          | 2021-07-08 13:17 |
|-----------------|------------------|
| MOT test number | 502107864508     |
| Result          | ✓ Passed         |

| MOT #5                  | 2021-07-08 13:17   |
|-------------------------|--|
| MOT test number         | 445767137349   |
| Result                  | × Failed   |
| Pass with rectification | Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 |

(b) (ii))

| МОТ #4          | 2020-08-07 14:39 |
|-----------------|------------------|
| MOT test number | 776921912192     |
| Result          | ✓ Passed         |





| MOT #3  | 2019-08-20 11:38 |
|---|------------------|
| MOT test number   | 237866744627     |
| Result  | ✓ Passed         |
|   |                  |
| MOT #2  | 2018-08-28 13:09 |
| MOT test number   | 653181766038     |
| Result  | ✓ Passed         |
|   |                  |
| MOT #1  | 2018-08-28 12:09 |
| MOT test number   | 153252276975     |
| Result  | 🗙 Failed         |
| <b>Fail</b> Offside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a)) |                  |



Tax & MOT check

| Taxed<br>Tax due:<br>1 July 2024 | ✓<br>MOT<br>Expires:<br>7 July 2024 |
|----------------------------------|-------------------------------------|
| Tax status                       | Valid until 1 July                  |
| Days left                        | 62                                  |
| MOT expiry date                  | 7 July 2024                         |
| Full MOT history                 | See MOT history                     |
| Tax calculation                  |                                     |

| Vehicle class                           | 49             |
|---|----------------|
| Band                                    | В              |
| Single payment (12 months)              | £ 20,00,-      |
| Single six month payment                | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,-      |





### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |         |
|----------|---------|
| Date     | FERRE   |
| Category | Lamp    |
| Туре     |         |
| Damage 2 | AMPLI   |
| Damage 2 | E Stand |
| Date     | *       |
| Category | AMP     |
| Туре     |         |

#### Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4 10.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 10.200 |





### Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second |             |
|--|-------------|
| **********   |             |
|  |             |
| ******   |             |
| ********   |             |
| ********   |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this HYUNDAI had different number plates.   |             |
| Number of plates   |             |
| Current registration   |             |
| Plate since  |             |
| Current registration   |             |
| Rate sizes   |             |





### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |





# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 10         |
| First mileage registration | 2015-09-25 |
| Last registration          | 2023-06-29 |
| Complete history           | See info   |



| Registration #1  | 2015-09-25 | 22 mi      |
|------------------|------------|------------|
| Registration #2  | 2018-08-28 | 41.365 mi  |
| Registration #3  | 2018-08-28 | 41.370 mi  |
| Registration #4  | 2019-08-20 | 53.478 mi  |
| Registration #5  | 2020-08-07 | 64.260 mi  |
| Registration #6  |            | 11.777 esi |
| Registration #7  |            | 11.777 mi  |
| Registration #8  |            | 11.777 esi |
| Registration #9  |            | 11.777 mi  |
| Registration #10 |            | 10.200 est |

More info >





## Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 92%             |
| Children       | 86%             |
| Pedestrian     | 43%             |
| Safety systems | 86%             |
| Overall rating | 80%             |
| Video          | see crash video |



| Dimensions & weight               |                  |
|-----------------------------------|------------------|
| Width                             | 1815 mm          |
| Height                            | 1470 mm          |
| Length                            | 4745 mm          |
| Wheel base                        | 2770 mm          |
| Kerb weight                       | 1601 kg          |
| Max. allowed weight               | 2090 kg          |
| Additional information            |                  |
| Fuel tank capacity                | 70               |
| Fuel delivery                     | Direct Injection |
| Number of doors                   | 4                |
| Number of seats<br>CarCheck.co.uk | 5 page 11/11     |