



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 T5 SE V50
Colour	Green
Year of manufacture	-
Top speed	149 mph
0 - 60 mph	6.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	220 BHP
Max. torque	320 Nm at 1.500 rpm
Cylinders	5
Fuel type	Petrol
Consumption city	22.6 mpg
Consumption extra urban	42.8 mpg
Consumption combined	32.1 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-27
Pictures	23
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #26	2022-03-08 11:30
MOT test number	351437653830
Result	✓ Passed
Next expiry date	2023-03-07

MOT #25	2022-03-07 16:41
MOT test number	875794834005
Result	✗ Failed

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MOT #24	2021-02-12 15:35
MOT test number	267458625340
Result	✓ Passed

MOT #23	2021-02-12 09:51
MOT test number	768858928908
Result	✗ Failed

Fail Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #22	2020-01-27 10:11
MOT test number	241605746186
Result	✓ Passed

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice Exhaust has a minor leak of exhaust gases front flexi (6.1.2 (a))

Advice Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

**MOT #21** 2020-01-27 10:11**MOT test number** 734361612689**Result** ✗ Failed**Advice** Exhaust has a minor leak of exhaust gases front flexi (6.1.2 (a))**Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))**Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**MOT #20** 2019-02-15 10:02**MOT test number** 959329596212**Result** ✓ Passed**Advice** Front Exhaust hanger broken**Advice** Front brakes slight in balance**Advice** Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Central Exhaust hanger corroded

**MOT #19**

2019-02-12 17:40

MOT test number

987000344445

Result**✗ Failed**

- Fail** Nearside Front Position lamp not working (4.2.1 (a))
- Fail** Offside Front Headlamp aim too high (4.1.2 (a))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Fail** Offside Parking brake inoperative on one side (1.4.1 (a))
- Advice** Central Exhaust hanger corroded
- Fail** Offside Front Position lamp not working (4.2.1 (a))
- Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Front Exhaust hanger broken

MOT #18

2018-01-23 11:53

MOT test number

473221881037

Result**✓ Passed**

**MOT #17** 2018-01-23 08:34**MOT test number** 993478303451**Result** ✗ Failed

- Fail** Nearside Rear coil spring broken (2.4.C.1a)
- Fail** Offside Rear Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Rear coil spring broken (2.4.C.1a)
- Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)

MOT #16 2017-01-11 10:52**MOT test number** 735327138403**Result** ✓ Passed**MOT #15** 2016-01-15 10:39**MOT test number** 525830409442**Result** ✓ Passed**MOT #14** 2015-01-15 10:04**MOT test number** 269185915024**Result** ✓ Passed**MOT #13** 2015-01-15 10:04**MOT test number** 666925015053**Result** ✗ Failed

- Pass with rectification** Rear Registration plate lamp not working (1.1.C.1d)

MOT #12 2014-01-27 10:05**MOT test number** 105717924444**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #11	2013-01-23 14:38
----------------	------------------

MOT test number	827793623009
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #10	2013-01-23 14:38
----------------	------------------

MOT test number	728033823055
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Rear Registration plate lamp not working (1.1.C.1d)
--------------------------------	---

MOT #9	2012-02-02 10:37
---------------	------------------

MOT test number	488333132014
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #8	2011-01-27 10:13
---------------	------------------

MOT test number	148107121005
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2011-01-27 10:13
---------------	------------------

MOT test number	899057021030
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Rear Registration plate lamp not working (1.1.C.1d)
--------------------------------	---

MOT #6	2010-01-19 11:34
---------------	------------------

MOT test number	752039010052
------------------------	--------------

Result	✓ Passed
---------------	----------

**MOT #5** 2009-01-30 11:59**MOT test number** 934720239087**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Registration plate lamp not working (1.1.5c)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2009-01-30 11:59**MOT test number** 714730039028**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2008-01-30 17:27**MOT test number** 751030538035**Result** ✓ Passed**Notice** Both rear tyres blocking**Notice** Front wiper blades smear**MOT #2** 2008-01-30 17:27**MOT test number** 221770438006**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too far to the right (1.8)**Notice** Front wiper blades smear**Notice** Both rear tyres blocking



MOT #1	2007-06-07 09:27
MOT test number	712098157118
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-04-19
Last registration	2022-03-08
Complete history	See info



Registration #1	2004-04-19	20 mi
Registration #2	2007-06-07	34.758 mi
Registration #3	2008-01-30	34.937 mi
Registration #4	2009-01-30	48.306 mi
Registration #5	2010-01-19	61.937 mi
Registration #6	2011-01-27	72.761 mi
Registration #7	2012-02-02	86.017 mi
Registration #8	2013-01-23	100.443 mi
Registration #9	2014-01-27	115.800 mi
Registration #10	2015-01-15	130.245 mi
Registration #11	2016-01-15	147.503 mi
Registration #12	2017-01-11	161.221 mi
Registration #13	2018-01-11	175.000 mi
Registration #14	2019-01-11	188.779 mi
Registration #15	2020-01-11	202.558 mi
Registration #16	2021-01-11	216.337 mi
Registration #17	2022-01-11	230.116 mi
Registration #18	2023-01-11	243.895 mi
Registration #19	2024-01-11	257.674 mi
Registration #20	2025-01-11	271.453 mi
Registration #21	2026-01-11	285.232 mi
Registration #22	2027-01-11	299.011 mi
Registration #23	2028-01-11	312.790 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4514 mm
Wheel base	2640 mm
Kerb weight	1451 kg
Max. allowed weight	2000 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	3548650