



report date: 2024-03-28

## General information

Make	VOLVO
Model	V60 D3 MOMENTUM
Colour	Grey
Year of manufacture	2018
Top speed	127 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	148 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	72.4 mpg
Consumption combined	2.8 mpg
CO2 emission	117 g/km
CO2 label	C





Internet history

Entry 1

Date	2022-05-29
Pictures	11
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-08-29
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	4
Total items failed	5

## MOT #5 2023-08-29 16:15

MOT test number 483806967465

Result ✓ Passed

Next expiry date 2024-08-29

**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

## MOT #4 2023-08-29 09:09

MOT test number 853360576481

Result ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

## MOT #3 2022-08-30 07:53

MOT test number 330687203334

Result ✓ Passed



MOT #2	2022-08-27 11:06
MOT test number	500753774851
Result	✗ Failed
<div><div>Fail</div>Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))</div>	

MOT #1	2021-09-30 10:39
MOT test number	224844080415
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
29 August 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	29 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>First licence fee (12 months)</b>	£ 210,00,-
<b>First licence fee diesel non RDE2 tested (12 months)</b>	£ 255,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 <b>PO68UWJ</b>
Plate since	2019-09-29
Current registration	 <b>PO68UWJ</b>
Plate since	2019-09-29

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-10-28
Last registration	2023-08-29
Complete history	<a href="#">See info</a>



Registration #1	2018-10-28	7 mi
Registration #2	2021-09-30	43.214 mi
Registration #3	2022-08-27	47.853 mi
Registration #4		
Registration #5		
Registration #6		
Registration #7		

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1916 mm
Height	1433 mm
Length	4761 mm
Wheel base	2872 mm
Kerb weight	1620 kg
Max. allowed weight	2190 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	2810176