



**YRIOAWH**

report date: 2024-03-29

General information

Make	AUDI
Model	A6 TDI LE MANS
Colour	Black
Year of manufacture	2010
Top speed	135 mph
0 - 60 mph	8.9 seconds
Gearbox	7 speed CVT

Engine & fuel consumption

Power	168 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	48.7 mpg
CO2 emission	153 g/km
CO2 label	G





Internet history

Entry 3

Date	2021-07-13
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)

Entry 2

Date	2021-07-11
Pictures	0
Listing price	<a href="#">View report</a>

source: [cargurus.co.uk](#)

Entry 1

Date	2021-06-16
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-05-03
MOT pass rate	59 %
MOT passed	10
Failed MOT tests	7
Total advice items	37
Total items failed	15

MOT #17	2023-05-04 14:03
MOT test number	596078033197
Result	✓ Passed
Next expiry date	2024-05-03
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2022-02-15 12:39
MOT test number	782438702717
Result	✓ Passed

MOT #15	2022-02-15 11:01
MOT test number	838199705127
Result	✗ Failed
Fail	Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
Fail	Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Offside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))

**MOT #14**

2020-11-20 15:45

**MOT test number**

947612699470

**Result**

✓ Passed

**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #13**

2020-11-18 09:57

**MOT test number**

541655591463

**Result**

✗ Failed

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Central Rear Seat belt not functioning as intended (7.1.2 (c))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Front passenger door hinge insecure (6.2.3 (c) (ii))**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 255/35/19 (5.2.3 (d) (i))**MOT #12**

2019-05-15 11:29

**MOT test number**

468434860854

**Result**

✓ Passed

**MOT #11**

2019-05-15 09:44

**MOT test number**

367003248191

**Result**

✗ Failed

**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Central Rear Seat belt buckle not functioning as intended (7.1.2 (d))**Pass with rectification** Offside Headlamp aim too low and too far to the right. (4.1.2 (a))

**MOT #10**

2018-05-04 12:51

**MOT test number**

301608949987

**Result**

✓ Passed

**Advice** Both front tyres have inner tread wear**Advice** Engine and under body covers fitted**MOT #9**

2018-05-03 12:43

**MOT test number**

342397383837

**Result**

✗ Failed

**Advice** Both front tyres have inner tread wear**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Advice** Rear pads low offside inner pad approx 2-3mm**Fail** Nearside Headlamp aim not tested (1.8.A.1c)**Advice** Engine and under body covers fitted**Fail** Nearside Headlamp not working on main beam (1.7.5a)**Advice** Front pads getting low**MOT #8**

2017-04-05 11:34

**MOT test number**

789204017211

**Result**

✓ Passed

**Advice** Nearside Rear Tyre worn close to the legal limit 255/35r19. advise renewal ASAP. (4.1.E.1)**Advice** Unable to inspect engine compartment fully due to engine covers fitted.**Advice** Offside Rear Tyre worn close to the legal limit 255/35r19. advise renewal ASAP. (4.1.E.1)**Advice** Unable to inspect underside of vehicle fully due to under-body covers fitted.

**MOT #7** 2017-04-05 11:34**MOT test number** 943847173529**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit 255/35r19. advise renewal ASAP. (4.1.E.1)**Advice** Unable to inspect engine compartment fully due to engine covers fitted.**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Offside Rear Tyre worn close to the legal limit 255/35r19. advise renewal ASAP. (4.1.E.1)**Advice** Unable to inspect underside of vehicle fully due to under-body covers fitted.**MOT #6** 2016-04-07 15:30**MOT test number** 432649099060**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit 255/35r19 (4.1.E.1)**Advice** Unable to inspect engine compartment fully due to engine covers fitted.**Advice** Unable to inspect underside of vehicle fully due to under-body covers fitted.**MOT #5** 2016-04-07 15:30**MOT test number** 856989597491**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit 255/35r19 (4.1.E.1)**Pass with rectification** Offside Front Headlamp aim too high (1.8)**Advice** Unable to inspect underside of vehicle fully due to under-body covers fitted.**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**Advice** Unable to inspect engine compartment fully due to engine covers fitted.

**MOT #4** 2015-03-18 14:54**MOT test number** 729777575099**Result** ✓ Passed**Notice** Both rear tyres are stepped on inner edge**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2014-03-21 13:04**MOT test number** 765660984058**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** All tyres has slight cuts on outer side walls (curb damage)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Both rear tyres starting to crack in between tread**MOT #2** 2013-03-20 10:38**MOT test number** 589849873076**Result** ✓ Passed**Notice** Damage to NSF tyre outer side wall, not deep enough to reach the ply or cords.**MOT #1** 2013-03-20 10:38**MOT test number** 318179173084**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Notice** Damage to NSF tyre outer side wall, not deep enough to reach the ply or cords.



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2025

✓  
**MOT**  
**Expires:**  
3 May 2024

Tax status	Valid until 1 May
Days left	367
MOT expiry date	3 May 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	YR10AWH
Plate since	2024-03-29
Current registration	YR10AWH
Plate since	2024-03-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-03-25
Last registration	2023-05-04
Complete history	<a href="#">See info</a>



Registration #1	2010-03-25	18 mi
Registration #2	2013-03-20	43.352 mi
Registration #3	2014-03-21	58.815 mi
Registration #4	2015-03-18	73.401 mi
Registration #5	2016-04-07	84.205 mi
Registration #6	2016-04-07	84.205 mi
Registration #7	2017-04-05	101.926 mi
Registration #8	2017-04-05	101.926 mi
Registration #9	2018-05-03	118.949 mi
Registration #10	2018-05-04	118.974 mi
Registration #11	2019-05-02	118.974 mi
Registration #12	2019-05-02	118.974 mi
Registration #13	2019-05-02	118.974 mi
Registration #14	2019-05-02	118.974 mi
Registration #15	2019-05-02	118.974 mi
Registration #16	2019-05-02	118.974 mi
Registration #17	2019-05-02	118.974 mi
Registration #18	2019-05-02	118.974 mi
Registration #19	2019-05-02	118.974 mi
Registration #20	2019-05-02	118.974 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2030 mm
Height	1459 mm
Length	4927 mm
Wheel base	2843 mm
Kerb weight	1590 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number

CAH 108769