



report date: 2024-03-28

General information

Make	JAGUAR
Model	XJ V6 SPORT
Colour	Red
Year of manufacture	2006
Top speed	144 mph
0 - 60 mph	6.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	231 BHP
Max. torque	284 Nm at 3.000 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Petrol
Consumption city	19.0 mpg
Consumption extra urban	36.2 mpg
Consumption combined	27.4 mpg
CO2 emission	249 g/km
CO2 label	L






Internet history

Entry 1

Date	2021-01-31
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-11-24
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	26
Total items failed	10

MOT #21	2023-11-06 13:21
MOT test number	613109013949
Result	✓ Passed
Next expiry date	2024-11-24
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #20	2022-11-03 13:32
MOT test number	851100421448
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Nearside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #19	2021-11-02 12:53
MOT test number	279280974279
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #18**

2020-11-25 16:29

MOT test number

492062897852

Result

✓ Passed

Advice Brake disc worn, pitted or scored, but not seriously weakened BOTH rear brake discs shows signs of wear on faces (1.1.14 (a) (ii))

Advice Oil leak

MOT #17

2020-11-19 12:55

MOT test number

160938013872

Result

✗ Failed

Fail Dipswitch does not operate immediately when selected on main beam (4.1.3 (b))

Fail Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt BOTH rear stabilizer bar dust covers (5.3.4 (b) (ii))

Fail Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

Advice Brake disc worn, pitted or scored, but not seriously weakened BOTH rear brake discs shows signs of wear on faces (1.1.14 (a) (ii))

Fail Offside Rear Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt link bar (5.3.4 (b) (ii))

Advice Oil leak

MOT #16

2019-12-18 08:48

MOT test number

204418532874

Result

✓ Passed

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Rear Lower Suspension component pin or bush slightly worn Lower hub bush worn (5.3.4 (a) (i))

Advice Offside Rear Lower Suspension component pin or bush slightly worn Lower hub bush worn (5.3.4 (a) (i))

MOT #15

2019-01-09 11:16

MOT test number

884573731019

Result

✓ Passed

Minor

Offside Rear Suspension rod ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #14** 2019-01-09 11:16**MOT test number** 351297686797**Result** ✗ Failed**Minor** Offside Rear Suspension rod ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Pass with rectification** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #13** 2018-01-08 13:02**MOT test number** 302817198212**Result** ✓ Passed**MOT #12** 2017-01-10 10:22**MOT test number** 381842717339**Result** ✓ Passed**Advice** Nearside Front tyre has damage too the outer sidewall**MOT #11** 2017-01-10 10:22**MOT test number** 708318635083**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Nearside Front tyre has damage too the outer sidewall**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**MOT #10** 2016-01-27 14:16**MOT test number** 207465144876**Result** ✓ Passed

**MOT #9** 2016-01-27 11:53**MOT test number** 347383731535**Result** ✗ Failed**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Fail** Nearside Rear Tyre has ply or cords exposed Outer Wall (4.1.D.1b)**MOT #8** 2015-01-22 11:24**MOT test number** 516302725094**Result** ✓ Passed**MOT #7** 2014-02-21 11:12**MOT test number** 469482654097**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #6** 2013-02-11 09:34**MOT test number** 249232243012**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #5** 2013-02-06 16:14**MOT test number** 158137333491**Result** ✗ Failed

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #4** 2012-02-08 12:29**MOT test number** 366679832020**Result** ✓ Passed**Notice** Nearside rear tyre has a cut on the tread but not yet to the cord .**MOT #3** 2011-02-16 16:05**MOT test number** 575297041028**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2010-09-08 13:43**MOT test number** 964711850216**Result** ✓ Passed**MOT #1** 2009-09-10 15:00**MOT test number** 373063859239**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
24 November 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	24 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-28
Current registration	*****
Plate since	2023-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-09-01
Last registration	2023-11-06
Complete history	See info



Registration #1	2006-09-01	29 mi
Registration #2	2009-09-10	32.618 mi
Registration #3	2010-09-08	35.624 mi
Registration #4	2011-02-16	35.899 mi
Registration #5	2012-02-08	44.265 mi
Registration #6	2013-02-06	50.275 mi
Registration #7	2013-02-11	50.275 mi
Registration #8	2014-02-21	56.889 mi
Registration #9	2015-01-22	63.950 mi
Registration #10	2016-01-27	72.115 mi
Registration #11	2016-01-27	72.115 mi
Registration #12	2017-01-10	77.970 mi
Registration #13	2018-01-10	83.830 mi
Registration #14	2018-01-10	83.830 mi
Registration #15	2018-01-10	83.830 mi
Registration #16	2018-01-10	83.830 mi
Registration #17	2018-01-10	83.830 mi
Registration #18	2018-01-10	83.830 mi
Registration #19	2018-01-10	83.830 mi
Registration #20	2018-01-10	83.830 mi
Registration #21	2018-01-10	83.830 mi
Registration #22	2018-01-10	83.830 mi
Registration #23	2018-01-10	83.830 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1483 mm
Length	4716 mm
Wheel base	2710 mm
Kerb weight	1605 kg
Max. allowed weight	2105 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	536960409WB