



TOYOTA




report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VVTI T3
Colour	Blue
Year of manufacture	2005
Top speed	118 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	150 Nm at 3.800 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.4 mpg
CO2 emission	168 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-09-01
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-11-07
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	20
Total items failed	3

MOT #20	2023-11-08 12:13
MOT test number	324320670762
Result	✓ Passed
Next expiry date	2024-11-07

MOT #19	2023-11-04 10:53
MOT test number	466255736185
Result	✗ Failed
<b>Advice</b> Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))	
<b>Advice</b> Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))	
<b>MAJOR</b> Emissions unable to be completed as gas analyser not working (8.2.1.2 (d))	

MOT #18	2022-09-08 16:44
MOT test number	708047714103
Result	✓ Passed
<b>Advice</b> Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))	
<b>Advice</b> Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive subframe mounting (5.3.6 (a) (i))	
<b>Advice</b> Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))	
<b>Advice</b> Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive subframe mounting (5.3.6 (a) (i))	

**MOT #17** 2021-09-09 13:29**MOT test number** 483631273410**Result** ✓ Passed**MOT #16** 2021-09-09 13:29**MOT test number** 726571287191**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too high and too far to the right. (4.1.2 (a))**Pass with rectification** Nearside Front Service brake excessively binding (1.2.1 (f))**MOT #15** 2020-10-13 15:24**MOT test number** 759230911641**Result** ✓ Passed**MOT #14** 2019-09-17 11:43**MOT test number** 870914997875**Result** ✓ Passed**MOT #13** 2018-09-19 11:11**MOT test number** 704531268329**Result** ✓ Passed**MOT #12** 2018-09-18 14:42**MOT test number** 892016271062**Result** ✗ Failed**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**MAJOR** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #11** 2017-09-12 14:55**MOT test number** 668990538211**Result** ✓ Passed**Advice** Really dark sun strip across drivers side front window, still able to see all mirrors**MOT #10** 2017-09-12 08:38**MOT test number** 260962870242**Result** ✗ Failed**Advice** Really dark sun strip across drivers side front window, still able to see all mirrors**Fail** Offside front brake binding (3.7.B.1)**MOT #9** 2016-09-13 08:40**MOT test number** 562370475005**Result** ✓ Passed**Advice** Nearside headlight has sun-damage starting to affect light pattern**Advice** Offside Front Door glass has black tape obscuring view through top of glass**MOT #8** 2015-09-02 16:07**MOT test number** 345772854054**Result** ✓ Passed**Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)**Advice** Offside Front Brake hose slightly chafed (3.6.B.4d)**Advice** Nearside Front Brake hose slightly chafed (3.6.B.4d)**MOT #7** 2014-09-04 11:32**MOT test number** 839857044244**Result** ✓ Passed**Advice** Offside coil spring corroded (2.4.C.1b)

**MOT #6** 2013-09-04 13:07**MOT test number** 606997743232**Result** ✓ Passed**MOT #5** 2012-09-03 10:06**MOT test number** 287957742249**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2011-09-06 13:02**MOT test number** 877259441265**Result** ✓ Passed**MOT #3** 2010-09-16 13:41**MOT test number** 760949250246**Result** ✓ Passed**Notice** Rear brake discs rusting**MOT #2** 2009-09-16 11:10**MOT test number** 723799159211**Result** ✓ Passed**MOT #1** 2008-09-23 13:54**MOT test number** 864387168265**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
7 November 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	7 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	<b>VX55KTA</b>
Plate since	2019-09-28
Current registration	<b>VX55KTA</b>
Plate since	2019-09-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-09-29
Last registration	2023-11-08
Complete history	<a href="#">See info</a>



Registration #1	2005-09-29	24 mi
Registration #2	2008-09-23	25.786 mi
Registration #3	2009-09-16	32.647 mi
Registration #4	2010-09-16	38.552 mi
Registration #5	2011-09-06	43.654 mi
Registration #6	2012-09-03	48.055 mi
Registration #7	2013-09-04	52.275 mi
Registration #8	2014-09-04	56.158 mi
Registration #9	2015-09-02	59.671 mi
Registration #10	2016-09-13	62.494 mi
Registration #11	2017-09-12	63.744 mi
Registration #12	2018-09-12	65.000 mi
Registration #13	2019-09-12	66.256 mi
Registration #14	2020-09-12	67.512 mi
Registration #15	2021-09-12	68.768 mi
Registration #16	2022-09-12	70.024 mi
Registration #17	2023-09-12	71.280 mi
Registration #18	2023-11-08	72.536 mi
Registration #19		
Registration #20		
Registration #21		
Registration #22		

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1215 kg
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	3ZZU675172