



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	COUPE SIII
Colour	Black
Year of manufacture	2009
Top speed	129 mph
0 - 60 mph	9.3 seconds
Gearbox	4 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	186 Nm at 4.500 rpm
Engine capacity	1.975 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.3 mpg
CO2 emission	193 g/km
CO2 label	J






Internet history

Entry 1

Date	2022-02-02
Pictures	5
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-31
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	21
Total items failed	25

MOT #16	2024-01-24 08:55
MOT test number	148017014396
Result	✓ Passed
Next expiry date	2025-01-31
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))



MOT #15

2024-01-17 14:00

MOT test number

558568377303

Result		✗ Failed
Fail	Brake disc in such a condition that it is seriously weakened Both rears, (1.1.14 (a) (ii))	
Fail	Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))	
Fail	Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))	
Fail	Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail	Power steering pipe/hose leaking (2.1.5 (a))	
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Fail	Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))	
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail	Position lamp not working Both fronts (4.2.1 (a) (ii))	

**MOT #14**

2023-01-30 12:34

**MOT test number**

200841297403

**Result**

✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear inner brake pads possible wearing thin
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Power steering pipe/hose has slight seepage (2.1.5 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13**

2022-02-01 16:47

**MOT test number**

697206721213

**Result**

✓ Passed

- Advice** Tyre slightly damaged/cracking or perishing cracking edges (5.2.3 (d) (ii))

**MOT #12**

2021-09-09 08:02

**MOT test number**

282441357299

**Result**

✓ Passed

**MOT #11**

2020-09-17 10:58

**MOT test number**

530211840169

**Result**

✓ Passed

**MOT #10**

2020-09-16 10:29

**MOT test number**

547846720780

**Result****✗ Failed**

- Fail** Nearside Front Inner Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Electrical wiring insulation in such a condition there is an imminent risk of fire or formation of sparks front cross member radiator support impact damage crushing wiring harness (4.11 (c) (iii))
- Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Front Direction indicator incorrect colour wing (4.4.3 (a))
- Fail** Offside Front Inner Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Clutch fluid pot below min level
- Advice** Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Nail in tyre
- Fail** Nearside Front Direction indicator incorrect colour wing (4.4.3 (a))

**MOT #9**

2019-03-04 16:58

**MOT test number**

817709698322

**Result****✓ Passed**

**MOT #8** 2019-03-04 12:08**MOT test number** 637473150608**Result** ✗ Failed

- Fail** Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Rear Rear fog lamp not working (4.5.1 (a) (ii))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**MOT #7** 2018-03-06 11:04**MOT test number** 206717744024**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2017-03-06 12:34**MOT test number** 272985068630**Result** ✓ Passed**MOT #5** 2017-03-06 12:34**MOT test number** 223068314603**Result** ✗ Failed

- Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)
- Pass with rectification** Rear Rear fog lamp not working (1.3.2b)



MOT #4	2016-06-01 10:15
MOT test number	698125868441
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #3	2014-11-07 14:39
MOT test number	165201214307
Result	✓ Passed

MOT #2	2013-09-04 10:41
MOT test number	539447843276
Result	✓ Passed

MOT #1	2012-08-29 11:37
MOT test number	347382442287
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
31 January 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	31 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EX59FKU
Plate since	2019-09-29
Current registration	EX59FKU
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-09-03
Last registration	2024-01-24
Complete history	<a href="#">See info</a>



Registration #1	2009-09-03	7 mi
Registration #2	2012-08-29	8.045 mi
Registration #3	2013-09-04	10.428 mi
Registration #4	2014-11-07	15.300 mi
Registration #5	2016-06-01	22.461 mi
Registration #6	2017-03-06	23.876 mi
Registration #7	2017-03-06	23.876 mi
Registration #8	2018-03-06	25.842 mi
Registration #9	2019-03-04	31.917 mi
Registration #10	2020-03-04	35.377 mi
Registration #11	2021-03-04	35.377 mi
Registration #12	2022-03-04	35.377 mi
Registration #13	2023-03-04	35.377 mi
Registration #14	2024-01-24	35.377 mi
Registration #15	2024-01-24	35.377 mi
Registration #16	2024-01-24	35.377 mi
Registration #17	2024-01-24	35.377 mi
Registration #18	2024-01-24	35.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1312 kg
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G4GC8245389