



report date: 2024-03-28

General information

Make	KIA
Model	OPTIMA PHEV
Colour	Silver
Year of manufacture	2018
Top speed	119 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	154 BHP
Max. torque	189 Nm at 5.000 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption extra urban	53.3 mpg
Consumption combined	176.6 mpg
CO2 emission	37 g/km
CO2 label	A







Internet history

Entry 1

Date	2022-01-08
Pictures	17
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT expiry date</b>	2022-09-02
<b>MOT pass rate</b>	75 %
<b>MOT passed</b>	6
<b>Failed MOT tests</b>	2
<b>Total advice items</b>	5
<b>Total items failed</b>	6

<b>MOT #8</b>	2021-09-03 12:41
<b>MOT test number</b>	988106526779
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-09-02

<b>MOT #7</b>	2021-03-06 13:37
<b>MOT test number</b>	501860390028
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #6</b>	2021-03-06 13:37
<b>MOT test number</b>	879826353269
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Front Windscreen washer provides insufficient washer liquid (3.5 (a))
<b>Advice</b>	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Pass with rectification</b>	Nearside Front Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
<b>Advice</b>	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2020-09-09 14:13**MOT test number** 123980381922**Result** ✓ Passed**MOT #4** 2020-09-08 15:20**MOT test number** 872625860644**Result** ✗ Failed**Fail** Front Windscreen wiper does not clear the windscreen effectively Both Sides (3.4 (b) (ii))**Fail** Front Brake pad(s) less than 1.5 mm thick Both Sides (1.1.13 (a) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #3** 2020-03-11 11:32**MOT test number** 848667676572**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**MOT #2** 2019-09-17 11:35**MOT test number** 555201024703**Result** ✓ Passed**MOT #1** 2019-03-22 16:27**MOT test number** 197148504674**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✗  
**MOT**  
**Expired:**  
2 September 2022

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	2 September 2022
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	59
<b>Band</b>	B
<b>First licence fee (12 months)</b>	£ 0,00,-
<b>Standard rate (12 months)</b>	£ 170,00,-
<b>Standard rate (6 months)</b>	£ 93,50,-
<b>Premium rate (12 months)</b>	£ 560,00,-
<b>Premium rate (6 months)</b>	£ 308,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	<b>YS18JYE</b>
Plate since	2019-03-28
Current registration	<b>YS18JYE</b>
Plate since	2019-03-28

More info >





Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2018-06-08
Last registration	2021-09-03
Complete history	<a href="#">See info</a>



Registration #1	2018-06-08	11 mi
Registration #2	2019-03-22	10.488 mi
Registration #3	2019-09-17	22.719 mi
Registration #4	2020-03-11	27.995 mi
Registration #5	2020-09-08	37.215 mi
Registration #6	2020-09-08	37.215 mi
Registration #7	2020-09-08	37.215 mi
Registration #8	2020-09-08	37.215 mi
Registration #9	2020-09-08	37.215 mi
Registration #10	2020-09-08	37.215 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	86%
Pedestrian	67%
Safety systems	71%
Overall rating	80%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1860 mm
Height	1465 mm
Length	4855 mm
Wheel base	2805 mm
Kerb weight	1850 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Engine number

G4NGHH018596