





report date: 2024-03-29

### General information

Make	RENAULT
Model	SCENIC DYNAMIQUE TOMTOM BOSE PACK DCI
Colour	Silver
Year of manufacture	2011
Top speed	112 mph
0 - 100 km/h	12.5 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	78 kW / 106 HP / 110 BHP
Max. torque	240 Nm at 1.750 rpm
<b>Engine capacity</b>	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	128 g/km
CO2 label	D



CarCheck.co.uk page 1/14



### Internet history

#### Entry 2

Date 2021-08-11

Pictures 14

Listing price <u>View report</u>









source: autotrader.co.uk

#### Entry 1

Date	2021-06-30
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/14



## MOT history

MOT expiry date	2024-08-20
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	33
Total items failed	8

MOT #15		2023-08-16 13:50
MOT test	number	155323858071
Result		✓ Passed
Next expi	ry date	2024-08-20
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii	))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/14



MOT #14 2023-08-16 07:56
MOT test number 909696399228

Result × Failed Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i)) Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii)) **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Minor Nearside Rear Tyre obviously under inflated (5.2.3 (I)) **Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i)) Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Minor Offside Rear Tyre obviously under inflated (5.2.3 (I))

**MOT #13** 2022-08-16 08:12

**MOT test number** 843126437354

Result \( \sqrt{Passed} \)

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**Advice** Front brake discs corroded on inner faces

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**Advice** Front tyres have slight wear on egdes

MOT #12 2021-08-06 11:50

MOT test number 271881578759

Result \rightarrow Passed

**Advice** Brake pad(s) wearing thin front and rear (1.1.13 (a) (ii))

CarCheck.co.uk page 4/14



**MOT #11** 2021-08-04 09:34

**MOT test number** 148207002321

**Result** X Failed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Offside Track rod end ball joint has slight play (2.1.3 (b) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**MOT #10** 2020-08-02 11:48

MOT test number 479990270405

Result 

Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #9 2019-08-20 09:50

**MOT test number** 523458455625

Result Passed

Advice Both rear tyres bold inner and outer

MOT #8 2019-08-20 08:36

**MOT test number** 714869972902

**Result** X Failed

**Advice** Both rear tyres bold inner and outer

Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #7 2018-08-21 15:03

**MOT test number** 459702927650

**Result** ✓ Passed

CarCheck.co.uk page 5/14



**MOT #6** 2017-09-30 09:27

**MOT test number** 327215211985

**Result** 
✓ Passed

**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

**Advice** Nearside shock absorber gaiter split

MOT #5 2017-09-29 12:01

MOT test number 918916925143

**Result** X Failed

**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice Nearside shock absorber gaiter split

**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

MOT #4 2016-10-06 14:40

**MOT test number** 943896892381

Result \( \sqrt{Passed} \)

**Advice** Vehicles internal headlight adjuster altered to recheck lights

**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

MOT #3 2015-10-12 15:30

**MOT test number** 166283198079

**Result** 
✓ Passed

CarCheck.co.uk page 6/14



MOT #2 2014-10-13 16:22 MOT test number 276036784207

**Notice** Engine covers fitted obscuring some components in the engine bay

**Notice** Under-trays fitted obscuring some underside components

MOT #1 2014-10-13 16:22

MOT test number 138156984265

Result × Failed

Pass with rectification Nearside Front Upper Headlamp aim too low (1.8)

**Notice** Engine covers fitted obscuring some components in the engine bay

**Notice** Under-trays fitted obscuring some underside components

**Pass with rectification** Offside Front Upper Headlamp aim too low (1.8)

CarCheck.co.uk page 7/14



## Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	20 August 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 8/14



BJ61NXS

report date: 2024-03-29

### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



## Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
*********	
***************************************	
	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	UK NE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

**Contact info** 


More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-09-30
Last registration	2023-08-16
Complete history	See info



Registration #1	2011-09-30	26 mi
Registration #2	2014-10-13	29.384 mi
Registration #3	2015-10-12	38.207 mi
Registration #4	2016-10-06	46.617 mi
Registration #5	2017-09-29	54.783 mi
Registration #6	2017-09-30	54.783 mi
Registration #7	2018-08-21	59.735 mi
Registration #8	2019-08-20	66.419 mi
Registration #9	2019-08-20	66.422 mi
Registration #5	2013-00-20	0011221111
Registration #10	2013 00 20	901.122 IIII
	2013-00-20	n m
Registration #10	2013-00-20	9 777 es 9 777 es 9 777 es
Registration #10 Registration #11	2013 00 20	
Registration #10 Registration #11 Registration #12	2013 00 20	9 199 es 9 199 es 9 199 es 9 199 es
Registration #10 Registration #11 Registration #12 Registration #13	2013 00 20	
Registration #10 Registration #11 Registration #12 Registration #13 Registration #14	2013 00 20	

More info >

CarCheck.co.uk page 13/14



## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1486 mm
Height	1637 mm
Length	4344 mm
Wheel base	2703 mm
Kerb weight	1385 kg
Max. allowed weight	1944 kg

## Additional information

Fuel tank capacity	60 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 14/14

Number of axles 2

**Engine number** D246598