



YPIOWVJ


report date: 2024-03-29

General information

Make	FORD
Model	KA ZETEC
Colour	Silver
Year of manufacture	2010
Top speed	99 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-01-30
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-02-01
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	44
Total items failed	13

MOT #17	2024-01-29 15:46
MOT test number	478005084583
Result	✓ Passed
Next expiry date	2025-02-01

MOT #16	2023-01-23 15:43
MOT test number	211084259040
Result	✓ Passed
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**MOT #15**

2022-01-14 14:17

MOT test number

739181387076

Result

✓ Passed

- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Rear Brake cable damaged but not to excess (1.1.15 (a))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Central Front Exhaust mounting defective (6.1.2 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear wiper is inoperative

MOT #14

2022-01-07 15:30

MOT test number

949173673199

Result

✗ Failed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Rear wiper is inoperative
- Advice** Offside Rear Brake cable damaged but not to excess (1.1.15 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Central Front Exhaust mounting defective (6.1.2 (a))
- Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #13

2021-02-02 11:18

MOT test number

416767214378

Result

✓ Passed



MOT #12		2021-02-02 11:18
MOT test number		125983843278
Result		✗ Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Pass with rectification	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))	

MOT #11		2020-07-01 15:34
MOT test number		593447316925
Result		✓ Passed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Rear bump stop insecure	
Advice	Oil leak, but not excessive from driveshaft seal in gearbox (8.4.1 (a) (i))	
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Front Exhaust mounting defective (6.1.2 (a))	
Advice	Rear axle corroded	

**MOT #10**

2020-07-01 07:58

MOT test number

659063424193

Result**✗ Failed**

- Fail** Offside Windscreen wiper does not clear the windscreen effectively blade split (3.4 (b) (ii))
- Advice** Nearside Rear bump stop insecure
- Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Fail** Front Brakes imbalanced across an axle (1.2.1 (b) (i))
- Fail** Offside Front Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively blade split (3.4 (b) (ii))
- Advice** Rear axle corroded
- Advice** Oil leak, but not excessive from driveshaft seal in gearbox (8.4.1 (a) (i))
- Advice** Front Exhaust mounting defective (6.1.2 (a))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

MOT #9

2019-04-26 12:56

MOT test number

141828275088

Result**✓ Passed**

- Advice** Tyre worn close to legal limit/worn on edge both front worn on inside edge (5.2.3 (e))
- Advice** Offside wiper blade split
- Advice** Tyre slightly damaged/cracking or perishing both rear (5.2.3 (d) (ii))
- Advice** Rear exhaust box outer cover corroded

**MOT #8** 2019-04-26 09:19**MOT test number** 412184918394**Result** ✗ Failed**Advice** Tyre worn close to legal limit/worn on edge both front worn on inside edge (5.2.3 (e))**Advice** Offside wiper blade split**Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Tyre slightly damaged/cracking or perishing both rear (5.2.3 (d) (ii))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Rear exhaust box outer cover corroded**Fail** Rear Exhaust system insecure clamp missing (6.1.2 (a))**MOT #7** 2018-04-26 07:14**MOT test number** 784258425324**Result** ✓ Passed**MOT #6** 2017-04-07 13:16**MOT test number** 512120324875**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Front Tyre worn close to the legal limit Both (4.1.E.1)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #5** 2016-04-27 15:24**MOT test number** 463442771349**Result** ✓ Passed

**MOT #4** 2015-04-09 14:50**MOT test number** 477549295011**Result** ✓ Passed**MOT #3** 2014-01-10 15:01**MOT test number** 675570414054**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-02-05 13:04**MOT test number** 657466833046**Result** ✓ Passed**MOT #1** 2013-01-22 13:58**MOT test number** 456582023067**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
1 February 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	1 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	YP10WVJ
Plate since	2019-09-29
Current registration	YP10WVJ
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-05-29
Last registration	2024-01-29
Complete history	See info



Registration #1	2010-05-29	18 mi
Registration #2	2013-01-22	20.510 mi
Registration #3	2013-02-05	20.705 mi
Registration #4	2014-01-10	31.314 mi
Registration #5	2015-04-09	34.083 mi
Registration #6	2016-04-27	35.979 mi
Registration #7	2017-04-07	41.390 mi
Registration #8	2018-04-26	46.260 mi
Registration #9	2019-04-26	48.906 mi
Registration #10	2019-04-26	48.906 mi
Registration #11	2020-05-29	50.000 mi
Registration #12	2021-05-29	50.000 mi
Registration #13	2022-05-29	50.000 mi
Registration #14	2023-05-29	50.000 mi
Registration #15	2024-01-29	50.000 mi
Registration #16	2024-01-29	50.000 mi
Registration #17	2024-01-29	50.000 mi
Registration #18	2024-01-29	50.000 mi
Registration #19	2024-01-29	50.000 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1320 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	5775203